



End-of-Sale and End-of-Life Announcement for the Cisco 3662 Telco Versatile DCN Access Platform

EOL4093 - Amended

Cisco® announces the end-of-sale and end-of life dates for the Cisco 3662 Telco Versatile DCN Access Platform. The last day to order the affected product(s) is January 1, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Customers who are using the Cisco 3662-AC-CO, or Cisco 3662-DC-CO are encouraged to migrate to the Cisco 3800 Series Integrated Services Routers for compatible sync/async, serial and T1/E1 densities, redundant AC or DC power, and higher levels of performance. The award-winning Cisco 3800 Series enables you to simplify deployment and management, lower the costs and complexities of your network, and support mission-critical business applications, by providing a highly secure platform with secure T3/E3 wire-speed delivery of data, voice, video, wireless, and application optimization services. For more information about the Cisco 3800 Series, visit <http://www.cisco.com/en/US/products/ps5855/index.html>.

Table 1. End-of-Life Milestones and Dates for the Cisco 3662 Telco Versatile DCN Access Platform

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	July 3, 2006
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	January 1, 2007
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	April 1, 2007
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	January 1, 2010
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	January 1, 2008
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	January 1, 2008
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	March 29, 2011
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	December 31, 2011

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

The affected products (part numbers CISCO3662-AC-CO and CISCO3662-DC-CO) will support new Cisco IOS Software features through final release of Cisco IOS Software Release 12.4T, and then will continue to receive bug fixes and TAC support through Cisco IOS Software Release 12.5 Mainline.

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
ACS-2RU-RM-19	19 inch Rack Mount Bracket for Cisco 2691, 3631, 3725	There is currently no replacement product available for this product.	
ACS-2RU-RM-19=	19 inch Rack Mount Bracket for Cisco 2691, 3631, 3725	There is currently no replacement product available for this product.	
ACS-2RU-RM-23	23 inch Rack Mount Brackets for Cisco 2691, 3631, 3725	There is currently no replacement product available for this product.	
ACS-2RU-RM-23=	23 inch Rack Mount Brackets for Cisco 2691, 3631, 3725	There is currently no replacement product available for this product.	
ACS-3600ASYN	Auxiliary/Console Port Cable Kit for the Cisco 3600 Series	There is currently no replacement product available for this product.	
ACS-3600ASYN=	Auxiliary/Console Port Cable Kit for the Cisco 3600 Series	There is currently no replacement product available for this product.	
ACS-3660RM-19	19 inch Rack Mount Kit for the Cisco 3660	There is currently no replacement product available for this product.	
ACS-3660RM-19=	19 inch Rack Mount Kit for the Cisco 3660	There is currently no replacement product available for this product.	
BOOT-3600=	Boot ROM Upgrade for Cisco 3600	There is currently no replacement product available for this product.	
CISCO3660-BP-CO	Backplane for Cisco 3660 (Central Office Version)	There is currently no replacement product available for this product.	
CISCO3660-BP-CO=	Backplane Spare for Cisco 3660 (Central Office Version)	There is currently no replacement product available for this product.	
CISCO3660-FANASSY=	Fan Assembly Spare for Cisco 3660	There is currently no replacement product available for this product.	
CISCO3660-MB-2FE	Dual Port Fast Ethernet Motherboard for Cisco 3660	There is currently no replacement product available for this product.	
CISCO3660-MB-2FE=	Dual Port Fast Ethernet Motherboard Spare for Cisco 3660	There is currently no replacement product available for this product.	
CISCO3662-AC-CO	Dual 10/100E Cisco 3660 6-slot CO Mod Router-AC w/ Telco SW	See Product Migration Options section for details.	CISCO3845
CISCO3662-DC-CO	Dual 10/100E Cisco3660 6-slot CO Mod Routr 2xDC PS, Telco SW	See Product Migration Options section for details.	CISCO3845-DC
MEM3600-16FC	16Mb Flash card for the Cisco 3600	There is currently no replacement product available for this product.	
MEM3600-16FC=	16Mb Flash Card for the Cisco 3600 series	There is currently no replacement product available for this product.	
MEM3600-16FS=	16MB Flash Memory for the 3600	There is currently no replacement product available for this product.	
MEM3600-16U32FS	16 to 32 MB Factory Flash Upgrade for Cisco 3600	There is currently no replacement product available for this product.	
MEM3600-20FC	20MB Flash card for the Cisco 3600 Series	There is currently no replacement product available for this product.	
MEM3600-20FC=	20MB Flash card for the Cisco 3600 Series	There is currently no replacement product available for this product.	
MEM3600-2X16FS=	32MB Flash for the Cisco 3600 Series (2x16MB Flash SIMMs)	There is currently no replacement product available for this product.	
MEM3600-8FS	Default Memory for the 3620s and 3640s	There is currently no replacement product available for this product.	

MEM3600-8FS=	8 MB Flash for the Cisco 3600 Series	There is currently no replacement product available for this product.	
MEM3660-128D=	128 MB DRAM Field Upgrade for the Cisco 3660	There is currently no replacement product available for this product.	
MEM3660-128U256D	Cisco 3660 128 to 256 MB Factory DRAM Upgrade	There is currently no replacement product available for this product.	
MEM3660-2X128D=	256MB DRAM for the Cisco 3660 (2x128 MB DRAM SIMMs)	There is currently no replacement product available for this product.	
MEM3660-2X32FS=	64MB Flash Memory for the Cisco 3660 (2x32 MB Flash SIMMs)	There is currently no replacement product available for this product.	
MEM3660-2X64D=	128MB DRAM for the Cisco 3660 (2x64 MB DRAM SIMMs)	There is currently no replacement product available for this product.	
MEM3660-32D=	32 MB DRAM Field Upgrade for the Cisco 3660	There is currently no replacement product available for this product.	
MEM3660-32FS=	32 MB Flash Field Upgrade for the Cisco 3660	There is currently no replacement product available for this product.	
MEM3660-32U64FS	Cisco 3660 32 to 64 MB Factory Flash Upgrade	There is currently no replacement product available for this product.	
MEM3660-64D=	64 MB DRAM Field Upgrade for the Cisco 3660	There is currently no replacement product available for this product.	
MIX-3660-64	MIX card for Cisco 3660 Series Routers	There is currently no replacement product available for this product.	
MIX-3660-64=	MIX card for Cisco 3660 Series Routers	There is currently no replacement product available for this product.	
PWR-3660-AC	AC Power Supply for Cisco 3660	There is currently no replacement product available for this product.	
PWR-3660-AC=	AC Power Supply for the Cisco 3660	There is currently no replacement product available for this product.	
PWR-3660-DC-U	Universal Power Supply, 24/48 volts	There is currently no replacement product available for this product.	
PWR-3660-DC-U=	Universal Power Supply, 24/48 volts	There is currently no replacement product available for this product.	
PWR600-AC-RPS-CAB	600W Redundant AC Power System With DC Power Cables	There is currently no replacement product available for this product.	
PWR600-AC-RPS-NCAB	600W Redundant AC Power System W/O DC Power Cables	There is currently no replacement product available for this product.	

Product Migration Options

Customers are encouraged to migrate to the Cisco 3800 Series. Information about this product can be found at: <http://www.cisco.com/en/US/products/ps5855/index.html>.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the Cisco 3662 Telco Versatile DCN Access Platform through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End of Sale date.

For More Information

For more information about the Cisco 3800 Series Integrated Services Routers, visit <http://www.cisco.com/en/US/products/ps5855/index.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:
http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to:
<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV
Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

CCDE, CCENT, Cisco Eos, Cisco Lumin, Cisco Nexus, Cisco StadiumVision, Cisco TelePresence, the Cisco logo, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn and Cisco Store are service marks; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0807R)