



## End-of-Sale and End-of-Life Announcement for the Cisco 4 Port Brooktrout Board for Unity Bridge

Cisco Systems® announces the end-of-sale and end-of-life dates for the Cisco® 4 port Brooktrout board for Unity Bridge (TR-114 variant). The last day to order the affected product is May 15, 2006. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until May 15, 2011.

Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement.

New Unity Bridge systems will use the TR-1034 variant Brooktrout boards. Table 3 provides relevant information for migrating to the replacement product.

**Table 1.** End-of-Life Milestones and Dates for the Cisco 4 Port Brooktrout Board For Unity Bridge

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	Feb 10, 2006
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 15, 2006
Last Shipment Date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	June 1, 2006
End of Software Maintenance Releases Date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	May 15, 2007
End of Routine Failure Analysis Date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	May 15, 2007
End of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	May 15, 2007
End of Service Contract Renewal Date	The last date to extend or renew a service contract for the product.	June 1, 2010
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	May 15, 2011

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
UNITY-TR114U-US	Option 4 port Brooktrout board for Unity Bridge in US/NAFTA
UNITY-TR114U-AUS	Option 4 port Brooktrout board for Unity Bridge in Australia
UNITY-TR114U-EU	Option 4 port Brooktrout board for Unity Bridge in Western Europe

End-of-Sale Product Part Number	Product Description
UNITY-TR114U-HK	Option 4 port Brooktrout board for Unity Bridge in Hong Kong
UNITY-TR114U-JPN	Option 4 port Brooktrout board for Unity Bridge in Japan
UNITY-TR114U-UK	Option 4 port Brooktrout board for Unity Bridge in United Kingdom
UNITY-TR114U-US=	Spare 4 port Brooktrout board for Unity Bridge in US/NAFTA
UNITY-TR114U-AUS=	Spare 4 port Brooktrout board for Unity Bridge in Australia
UNITY-TR114U-EU=	Spare 4 port Brooktrout board for Unity Bridge in Western Europe
UNITY-TR114U-HK=	Spare 4 port Brooktrout board for Unity Bridge in Hong Kong
UNITY-TR114U-JPN=	Spare 4 port Brooktrout board for Unity Bridge in Japan
UNITY-TR114U-UK=	Spare 4 port Brooktrout board for Unity Bridge in United Kingdom

### PRODUCT MIGRATION OPTIONS

The recommended replacement for the Cisco 4 port Brooktrout board for Unity Bridge (TR-114 variant) is the 4 or 8 port Brooktrout board for Unity Bridge (TR-1034 variant). For use as part of the Unity Bridge solution, both cards offer equivalent functionality (with the sole exception being that the TR-1034 variant come in an 8 port form factor). However, due to software incompatibilities, the TR-114 and TR-1034 cards can't run concurrently in the same Unity Bridge server.

**Table 3.** Product Comparisons

Feature	Cisco End-of-Sale Product	Cisco Replacement Product
Voice Card for use in Cisco Unity Bridge	UNITY-TR114U-US	UNITY-TR1034-4 or UNITY-TR1034-8
	UNITY-TR114U-AUS	UNITY-TR1034-4 or UNITY-TR1034-8
	UNITY-TR114U-EU	UNITY-TR1034-4 or UNITY-TR1034-8
	UNITY-TR114U-HK	
	UNITY-TR114U-JPN	UNITY-TR1034-4 or UNITY-TR1034-8
	UNITY-TR114U-UK	UNITY-TR1034-4 or UNITY-TR1034-8
	UNITY-TR114U-US=	UNITY-TR1034-4= or UNITY-TR1034-8=
	UNITY-TR114U-AUS=	UNITY-TR1034-4= or UNITY-TR1034-8=
	UNITY-TR114U-EU=	UNITY-TR1034-4= or UNITY-TR1034-8=
	UNITY-TR114U-HK=	
	UNITY-TR114U-JPN=	UNITY-TR1034-4= or UNITY-TR1034-8=
	UNITY-TR114U-UK=	UNITY-TR1034-4= or UNITY-TR1034-8=

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

## FOR MORE INFORMATION

For more information about the Cisco 4 port Brooktrout board for Unity Bridge, visit <http://www.cisco.com/en/US/products/sw/voicesw/ps2237/index.html> or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: [http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html)

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



### Corporate Headquarters

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
[www.cisco.com](http://www.cisco.com)  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

### European Headquarters

Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
[www-europe.cisco.com](http://www-europe.cisco.com)  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

### Americas Headquarters

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
[www.cisco.com](http://www.cisco.com)  
Tel: 408 526-7660  
Fax: 408 527-0883

### Asia Pacific Headquarters

Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
[www.cisco.com](http://www.cisco.com)  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel  
Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal  
Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan  
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2006 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0601R)

