



END-OF-LIFE NOTICE, NO. 752

END OF SALE FOR THE CURRENT PIX AND PIX 10000 HARDWARE

Cisco® introduces two new PIX® Firewall hardware products on May 1, 1998: Cisco PIX Firewall 510 (PIX-510) and Cisco PIX Firewall 520 (PIX-520). These two products replace the current Cisco PIX Firewall (PIX) and PIX 10000 (PIX10000). As a result, June 1, 1998, will mark the End-of-Sale for the current PIX Firewall and PIX 10000 products. Also, product bundles including either PIX Firewall or PIX 10000 will share the same End-of-Sale date. Fulfillment of all shipments for PIX Firewall and PIX 10000 products will be completed by August 1, 1998. Table 1 summarizes all affected products.

These new PIX Firewall products offer several enhancements. Both PIX Firewall 510 and 520 share a new, lower-profile chassis design with mounting options for cabling the unit either from the front or rear. PIX Firewall 510 has a 166-MHz Pentium processor and 16 MB of RAM, and the PIX Firewall 520 has a 233-MHz Pentium II processor and 32 MB of RAM. PIX Firewall 520 is also available with a 48VDC power supply and it is NEBS-compliant.

Table 1. End-of-Sale Summary

End-of-Sale Items	Part Number	End-of-Sale Date
PIX Firewall	PIX	June 1, 1998
PIX 10000	PIX10000	June 1, 1998
Two-tier PIX Firewall packages	PIX64-B-CH	June 1, 1998
	PIX1K-A-CH	June 1, 1998
	PIX1K-B-CH	June 1, 1998
	PIXUR-A-CH	June 1, 1998
	PIXUR-B-CH	June 1, 1998
Promotional bundles	EZCON-SECURE-1	June 1, 1998
	EZCON-SECURE-2	June 1, 1998

REPLACEMENT PRODUCTS

The replacement product matrix for the PIX Firewall and PIX 10000 is shown below.

Table 2. Replacement Items for PIX Firewall and PIX 10000

Current Description	Current Part Number	New Description	New Part Number
PIX Firewall	PIX	PIX Firewall 510	PIX-510
PIX 10000	PIX10000	PIX Firewall 520	PIX-520
Two-tier PIX Firewall packages	PIX64-A-CH	--	PIX-510-128-CH
	PIX64-B-CH	--	PIX-520-128-CH
	PIX1K-A-CH	--	PIX-510-1K-CH
	PIX1K-B-CH	--	PIX-520-1K-CH
	PIXUR-A-CH	--	PIX-510-UR-CH
	PIXUR-B-CH	--	PIX-520-UR-CH
Promotional bundles	EZCON-SECURE-1	--	EZCON-SECURE-10
	EZCON-SECURE-2	--	EZCON-SECURE-20

MAINTENANCE CONTRACTS

PIX Firewall and PIX 10000 products will continue to be fully supported by the SMARTnet[®] maintenance agreements. The existing SMARTnet product offerings will not change for the PIX Firewall 510 and 520, and the same part numbers should be used for ordering.

SOFTWARE SUPPORT

Cisco PIX Firewall and PIX 10000 will support the next two major releases of software. PIX Firewall 510 and 520 both support PIX Software V.4.0.7 and subsequent software releases.

UPGRADE PATH TO PIX FIREWALL 520

Both PIX Firewall and PIX 10000 customers using the Cisco Technology Migration program can upgrade to PIX Firewall 520. Contact your local Cisco sales representative or Cisco reseller for more information.

For more information on the PIX Firewall products, visit <http://www.cisco.com/en/US/products/sw/secursw/ps2120/index.html>.

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) VS/LW8343 04/05

