



## PRODUCT BULLETIN NO. EOL5079

# END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO SECURE PIX FIREWALL RELEASE 4.0

Cisco Systems® announces the end-of-sale and end-of life dates for the Cisco Secure PIX Firewall Release 4.0. The last day to order the affected product is March 8, 1999. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 in EoL product bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco Secure PIX Firewall Release 4.0.

**Table 1.** End-of-Life Milestones and Dates for the Cisco Secure PIX Firewall Release 4.0.

Milestone	Definition	Date
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	March 8, 1999
<b>Last Date of Support:</b> OS SW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	March 8, 2002

HW = Hardware OS SW = Operating System Software App SW = Application Software

### PRODUCT MIGRATION OPTIONS

PIX software versions 4.3 and greater require a minimum of 16MB RAM memory. Older PIX Firewalls with only 8MB RAM memory require a memory upgrade if version 4.3 software or later is used. The memory upgrade is not necessary for PIX10000, PIX-510, or PIX-520 models, which already have 16MB of memory or more.

A 128MB upgrade for the PIX Firewall series is now available in two memory upgrade kits. Please use the guide below to determine which upgrade to order. Note that these parts are physically different; one kit is not a replacement for the other.

**Table 2.** PIX Memory Upgrade Part Numbers

End-of-Sale Product Part Number	Product Description
PIX-MEM-UPG-128=	For PIX and PIX10000
PIX-MEM-5XX-128=	For PIX-510 and PIX-520

### PRODUCT MIGRATION OPTIONS

PIX software versions 4.3 and greater require a minimum of 16MB RAM memory. Older PIX Firewalls with only 8MB RAM memory require a memory upgrade if version 4.3 software or later is used. The memory upgrade is not necessary for PIX10000, PIX-510, or PIX-520 models, which already have 16MB of memory or more.

A 128MB upgrade for the PIX Firewall series is now available in two memory upgrade kits. Please use the guide below to determine which upgrade to order. Note that these parts are physically different; one kit is not a replacement for the other.



## **FOR MORE INFORMATION**

For more information about the Cisco Secure PIX Firewall Release 4.0, visit

[http://www.cisco.com/en/US/products/hw/vpndevc/ps2030/prod\\_eol\\_notices\\_list.html](http://www.cisco.com/en/US/products/hw/vpndevc/ps2030/prod_eol_notices_list.html) or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

[http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html)

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



Corporate Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA  
95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

European Headquarters  
Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

Americas Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA  
95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

Asia Pacific Headquarters  
Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital  
Tower  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2006 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0601R)

Printed in the USA