

sco – Troubleshooting EM_PARK Issues for EMDigital CAS Sig

Table of Contents

<u>Troubleshooting EM_PARK Issues for EMDigital CAS Signaling</u>	1
<u>Introduction</u>	1
<u>Problem</u>	1
<u>Solution</u>	1
<u>Background Information</u>	2
<u>Fake Answer</u>	2
<u>Related Information</u>	9
<u>Introduction</u>	10
<u>Problem</u>	10
<u>Solution</u>	10
<u>Background Information</u>	11
<u>Fake Answer</u>	11
<u>Related Information</u>	19

Troubleshooting EM_PARK Issues for EMDigital CAS Signaling

Introduction

Problem

Solution

Background Information

Fake Answer **Related Information**

Introduction

In digital E&M signaling on Cisco 2600, 3600, and MC3810 router platforms, some T1/E1 time slots may get stuck in the EM_PARK state. This is visible when you issue the **show voice call summary** command. This document explains how to troubleshoot this issue.

The following output shows that some time slots are in the EM_PARK state. Remember that a time slot in the EM_PARK state will not be used for voice calls.

```
Router#show voice call summary
PORT          CODEC      VAD      VTSP STATE      VPM STATE
=====      =====      ==      =====      =====
1/0:0.1       -          -          -          EM_ONHOOK
1/0:0.2       -          -          -          EM_PARK
1/0:0.3       -          -          -          EM_PARK
1/0:0.4       -          -          -          EM_ONHOOK
1/0:0.5       -          -          -          EM_ONHOOK
```

Problem

There are two possible, major reasons for the time slot to be stuck in the EM_PARK state:

- ◆ The digital signal processor (DSP) is bad; either hardware or software issues.
- ◆ The PSTN switch/PBX is sending a continuous offhook signal to the router and not releasing it.

The following hardware and/or software is affected by this issue:

- ◆ Hardware—Cisco 2600, Cisco 3600, Cisco VG200, and MC3810 routers
- ◆ Software—All

Solution

If the time slots in your system are stuck in the EM_PARK state, first check the DSPs. To check the DSPs, refer to Troubleshooting the DSP on NM-HDV for Cisco 2600/3600 Series Routers.

If the DSPs are alive, the problem can be on the PSTN switch/PBX side or the Cisco IOS (router/gateway not starting the Fake Answer procedure). For more information, refer to the Fake

Answer section.

Background Information

In T1 CAS (wink start signaling as an example), when the PBX goes offhook, the router/gateway side time slot remains in the idle (EM_ONHOOK) state until the call is answered by a remote destination. The router time slot state changes to EM_OFFHOOK when the call is answered by the remote destination.

If the call did not connect, the router/gateway plays the inband reorder tones to the caller. Since the channel state on the router side is still EM_ONHOOK, the router is unable to hang up the channel. After the caller hangs up, the PBX should change its channel state from offhook to onhook.

In some cases, the PBXs do not send the onhook messages (using the ABCD transitions). The router has a workaround for this called fake answer. Without the fake answer workaround, the channels will hang in a state of EM_PARK indefinitely.

Fake Answer

The Cisco router/gateway waits for a default value of 30 seconds (use **timeouts wait-release** and **timeouts call-disconnect** to change these values) after it knows that the time slot should be set from the PBX to onhook while playing the reorder tone.

If this does not happen, the router moves the time slot to the EM_PARK state and starts another timer with a duration of 10 seconds. If the PBX still does not go onhook after the 10-second duration, the router tricks the PBX by sending a *fake answer* of a 1-second duration and then goes onhook.

After sending the fake answer signal, the router starts another timer of five minutes. If the PBX goes onhook, the timer stops and the router transitions the time slot to the EM_ONHOOK state. Otherwise, after five minutes it sends another fake answer signal of a one-second duration, and it keeps repeating that until the PBX goes onhook. The router is forcing the PBX to clear the call.

Note: This answering transition will not be updated to any accounting record since the actual call was already cleared. The PBX will, however, understand it as an answer and the user will probably be charged for the one-second duration call.

If the DSP associated with the time slot in the EM_PARK state is alive and healthy and the problem persists, run the **debug vpm all** and **debug vtsp all** commands to see if Cisco IOS attempts to send the fake answer.

Note: You need to keep the debugs running for more than five minutes.

Note: In most cases, if the DSP is bad, the router will not perform the fake answer workaround. For more information, refer to Troubleshooting the DSP on NM-HDV for Cisco 2600/3600 Series Routers.

The debug output below shows how a time slot got stuck in EM_PARK and how the fake answer workaround works.

```
Jan 11 17:19:00.767: htsp_dsp_message: SEND/RESP_SIG_STATUS: state=0xC
timestamp
=44262 systime=31305235
Jan 11 17:19:00.767: htsp_process_event:
```

[4/1:1(10), EM_ONHOOK, E_DSP_SIG_1100]em_onhook_offhook htsp_setup_ind

! offhook signal was received from the switch

```
Jan 11 17:19:00.767: [4/1:1(10)] get_local_station_id calling num=
calling name=
calling time=01/11 17:19
Jan 11 17:19:00.767: vtsp_tsp_call_setup_ind (sdb=0x62BB7B14,
tdm_info=0x0, tsp_
info=0x62BB4050, calling_number= calling_oct3 = 0x0, called_number=
called_oct3
= 0x81, oct3a=0x0): peer_tag=0
Jan 11 17:19:00.767: : ev.clg.clir is 0
ev.clg.clid_transparent is
0
ev.clg.null_orig_clg is 1
ev.clg.calling_translated is false

Jan 11 17:19:00.767: htsp_timer - 3000 msec
Jan 11 17:19:00.767: vtsp_do_call_setup_ind
Jan 11 17:19:00.767: vtsp_allocate_cdb,cdb 0x62DCEA70
Jan 11 17:19:00.767: vtsp_do_call_setup_ind: Call ID=112722,
guid=62DC4230
Jan 11 17:19:00.767: vtsp_do_call_setup_ind: type=0,
under_spec=1640890368, name
=, id0=10, id1=1, id2=25038, calling=, called= subscriber=RegularLine
Jan 11 17:19:00.767: vtsp_do_normal_call_setup_ind
Jan 11 17:19:00.771: cc_api_call_setup_ind (vdbPtr=0x62BB7FA0,
callInfo={called=
,called_oct3=0x81,calling=,calling_oct3=0x0,calling_oct3a=0x0,calling_xlated=fal
se,subscriber_type_str=RegularLine,fdest=0,peer_tag=0,
prog_ind=3},callID=0x62DC
40DC)
Jan 11 17:19:00.771: cc_api_call_setup_ind type 1 , prot 0
Jan 11 17:19:00.771: vtsp_insert_cdb,cdb 0x62DCEA70
Jan 11 17:19:00.771: vtsp_open_voice_and_set_params
Jan 11 17:19:00.771: dsp_close_voice_channel: [4/1:1:32995]
packet_len=8 channel
_id=3 packet_id=75
Jan 11 17:19:00.771: dsp_open_voice_channel_20: [4/1:1:32995]
packet_len=16 chan
nel_id=3 packet_id=74 alaw_ulaw_select=0
associated_signaling_channel=130 time_s
lot=2 serial_port=0
Jan 11 17:19:00.771: vtsp_modem_proto_from_cdb: cap_modem_proto
1073741824
Jan 11 17:19:00.771: vtsp_modem_proto_from_cdb: cap_modem_proto
1073741824
Jan 11 17:19:00.771: dsp_encap_config: [4/1:1:32995] packet_len=30
channel_id=3
packet_id=92
TransportProtocol 2 t_ssrc=0x0 r_ssrc=0x0 t_vpxcc=0x0 r_vpxcc=0x0
sid_support=1, tse_payload=65535, seq_num=0x0, redundancy=0
Jan 11 17:19:00.771: dsp_set_payout_delay
Jan 11 17:19:00.771: dsp_set_payout: [4/1:1:32995] packet_len=18
channel_id=3 p
acket_id=76 mode=1 initial=60 min=40 max=200 fax_nom=300
dsp_set_payout_delay_config
Jan 11 17:19:00.771: dsp_set_payout_config
Jan 11 17:19:00.771: mode 0, init 60, min 40, max 200 payout default
Jan 11 17:19:00.771: dsp_set_payout_config:mode 0, init 60, min 40,
max 200
Jan 11 17:19:00.771: dsp_set_payout_config: [4/1:1:32995]
```

```

packet_len=18 channel
_id=3 packet_id=76 mode=1 initial=60 min=40 max=200 fax_nom=300
Jan 11 17:19:00.771: dsp_echo_canceler_control: echo_cancel: 1
Jan 11 17:19:00.771: dsp_echo_canceler_control: [4/1:1:32995]
echo_cancel 1, dis
able_hpf 0, flags=0x0, threshold=-21
Jan 11 17:19:00.771: dsp_echo_canceler_control: [4/1:1:32995]
packet_len=12 chan
nel_id=3 packet_id=66 flags=0x0, threshold=-21
Jan 11 17:19:00.771: set_gains: FXx/E&M:
msg->message.set_codec_gains.out_gain=0
Jan 11 17:19:00.771: dsp_set_gains: [4/1:1:32995] packet_len=12
channel_id=3 pac
ket_id=91 in_gain=0 out_gain=0
Jan 11 17:19:00.771: dsp_vad_enable: [4/1:1:32995] enable:
packet_len=12 channel
_id=3 packet_id=78 thresh=-38
Jan 11 17:19:00.771: cc_process_call_setup_ind (event=0x62E63ACC)
Jan 11 17:19:00.771: >>>CCAPI handed cid 32995 with tag 0 to app
"DEFAULT"
Jan 11 17:19:00.771: sess_appl: ev(24=CC_EV_CALL_SETUP_IND),
cid(32995), disp(0)
Jan 11 17:19:00.771: sess_appl: ev(SSA_EV_CALL_SETUP_IND), cid(32995),
disp(0)
Jan 11 17:19:00.771: ssaCallSetupInd
Jan 11 17:19:00.771: ccCallSetContext (callID=0x80E3,
context=0x62DFBCF0)
Jan 11 17:19:00.771: ssaCallSetupInd cid(32995),
st(SSA_CS_MAPPING),oldst(0), ev
(24)ev->e.evCallSetupInd.nCallInfo.finalDestFlag = 0
Jan 11 17:19:00.771: ccCallSetupAck (callID=0x80E3)
Jan 11 17:19:00.771: ccGenerateTone (callID=0x80E3 tone=8)
Jan 11 17:19:00.771: ccCallReportDigits (callID=0x80E3, enable=0x1)
Jan 11 17:19:00.771: vtsp_report_digit_control: enable=1: digit
reporting enabled
Jan 11 17:19:00.771: cc_api_call_report_digits_done
(vdbPtr=0x62BB7FA0, callID=0x80E3, disp=0)
Jan 11 17:19:00.771: : vtsp_get_digit_timeouts
Jan 11 17:19:00.771: sess_appl: ev(52=CC_EV_CALL_REPORT_DIGITS_DONE),
cid(32995), disp(0)
Jan 11 17:19:00.771:
cid(32995)st(SSA_CS_MAPPING)ev(SSA_EV_CALL_REPORT_DIGITS_DONE)
oldst(SSA_CS_MAPPING)cfid(-1)csize(0)in(1)fDest(0)
Jan 11 17:19:00.771: ssaReportDigitsDone cid(32995) peer list: (empty)
Jan 11 17:19:00.771: ssaReportDigitsDone callid=32995 Enable succeeded
Jan 11 17:19:00.771: ccGenerateTone (callID=0x80E3 tone=8)
Jan 11 17:19:00.771: vtsp:[4/1:1:32995, S_SETUP_INDICATED,
E_CC_SETUP_ACK]
Jan 11 17:19:00.775: act_setup_ind_ack
Jan 11 17:19:00.775: vtsp_modem_proto_from_cdb: cap_modem_proto 0
Jan 11 17:19:00.775: vtsp_modem_proto_from_cdb: cap_modem_proto 0
Jan 11 17:19:00.775: dsp_encap_config: [4/1:1:32995] packet_len=30
channel_id=3
packet_id=92 TransportProtocol 2 t_ssrc=0x0 r_ssrc=0x0 t_vpxcc=0x0
r_vpxcc=0x0
sid_support=1, tse_payload=65535, seq_num=0x0, redundancy=0
Jan 11 17:19:00.775: dsp_voice_mode: [4/1:1:32995] cdb 62DCEA70,
cdb->codec_para
ms.modem 2, inband_detect flags 0x21
Jan 11 17:19:00.775: map_dtmf_relay_type--digit relay mode: 2
Jan 11 17:19:00.775: dsp_voice_mode: [4/1:1:32995] packet_len=24
channel_id=3 pa
cket_id=73 coding_type=1 voice_field_size=160 VAD_flag=0
echo_length=256 comfort

```

```

_noise=1 inband_detect=33 digit_relay_mode=2
AGC_flag=0act_setup_ind_ack: modem_mode = 0, fax_relay_on = 1
Jan 11 17:19:00.775: act_setup_ind_ack(): dsp_dtmf_mode()
dsp_dtmf_mode(VTSP_TONE_DTMF_MODE)

Jan 11 17:19:00.775: dsp_dtmf_mode: [4/1:1:32995] packet_len=10
channel_id=3 pac
ket_id=65 dtmf_or_mf=0
Jan 11 17:19:00.775: vtsp_timer: 31305236
Jan 11 17:19:00.775: vtsp:[4/1:1:32995, S_DIGIT_COLLECT,
E_CC_GEN_TONE]
Jan 11 17:19:00.775: act_gen_tone
Jan 11 17:19:00.775: dsp_cp_tone_off: [4/1:1:32995] packet_len=8
channel_id=3 pa
cket_id=71
Jan 11 17:19:00.775: dsp_cp_tone_on: [4/1:1:32995] packet_len=38
channel_id=3 pa
cket_id=72 tone_id=4 n_freq=2 freq_of_first=350 freq_of_second=440
amp_of_first=
5514 amp_of_second=5514 direction=1 on_time_first=65535
off_time_first=0 on_time_second=0 off_time_second=0
Jan 11 17:19:00.775: vtsp:[4/1:1:32995, S_DIGIT_COLLECT,
E_CC_GEN_TONE]
Jan 11 17:19:00.775: act_gen_tone
Jan 11 17:19:00.775: dsp_cp_tone_off: [4/1:1:32995] packet_len=8
channel_id=3 pa
cket_id=71
Jan 11 17:19:00.775: dsp_cp_tone_on: [4/1:1:32995] packet_len=38
channel_id=3 pa
cket_id=72 tone_id=4 n_freq=2 freq_of_first=350 freq_of_second=440
amp_of_first=
5514 amp_of_second=5514 direction=1 on_time_first=65535
off_time_first=0 on_time
_second=0 off_time_second=0
Jan 11 17:19:00.775: htsp_process_event: [4/1:1(10),
EM_WAIT_SETUP_ACK, E_HTSP_SETUP_ACK]em_wait_setup_ack_get_ack
Jan 11 17:19:00.775: htsp_timer_stop
Jan 11 17:19:00.775: htsp_timer2 - 172 msec
Jan 11 17:19:00.947: htsp_process_event: [4/1:1(10),
EM_WAIT_SETUP_ACK, E_HTSP_EVENT_TIMER2]em_wait_prewink_timer
Jan 11 17:19:00.947: em_offhook (0)[recEive and transMit4/1:1(10)] set
signal st
ate = 0x8em_onhook (200)[recEive and transMit4/1:1(10)] set signal
state = 0x0

! wink of duration 200 msec was sent out to the switch

Jan 11 17:19:01.471: vtsp_process_dsp_message:
MSG_TX_DTMF_DIGIT_BEGIN: digit=9,
rtp_timestamp=0xED31C493

Jan 11 17:19:01.471: vtsp:[4/1:1:32995, S_DIGIT_COLLECT,
E_DSP_DTMF_DIGIT_BEGIN]
Jan 11 17:19:01.471: act_report_digit_begin
Jan 11 17:19:01.471: cc_api_call_digit_begin (dstVdbPtr=0x0,
dstCallId=0xFFFFFFFF
F, srcCallId=0x80E3,
digit=9, digit_begin_flags=0x1, rtp_timestamp=0xED31C493
rtp_expiration=0x0, dest_mask=0x1)
Jan 11 17:19:01.471: sess_appl: ev(10=CC_EV_CALL_DIGIT_BEGIN),
cid(32995), disp(0)
Jan 11 17:19:01.471:
cid(32995)st(SSA_CS_MAPPING)ev(SSA_EV_DIGIT_BEGIN)

```

```

oldst(SSA_CS_MAPPING)cfid(-1)csize(0)in(1)fDest(0)
Jan 11 17:19:01.471: ssaIgnore cid(32995),
st(SSA_CS_MAPPING),oldst(0), ev(10)
Jan 11 17:19:01.503: vtsp_process_dsp_message: MSG_TX_DTMF_DIGIT_OFF:
digit=9, duration=65
Jan 11 17:19:01.503: vtsp:[4/1:1:32995, S_DIGIT_COLLECT,
E_DSP_DTMF_DIGIT]
Jan 11 17:19:01.503: act_report_digit_end
Jan 11 17:19:01.503: vtsp_timer_stop: 31305308
Jan 11 17:19:01.503: dsp_cp_tone_off: [4/1:1:32995] packet_len=8
channel_id=3 pa
cket_id=71
Jan 11 17:19:01.503: cc_api_call_digit_end (dstVdbPtr=0x0,
dstCallId=0xFFFFFFFF,
srcCallId=0x80E3,
digit=9,duration=65,xruleCallingTag=0,xruleCalledTag=0,
dest_mask=0x1), digi
t_tone_mode=0
Jan 11 17:19:01.503: htsp_digit_ready: digit = 39
Jan 11 17:19:01.503: vtsp_timer: 31305308
Jan 11 17:19:01.503: htsp_process_event: [4/1:1(10), EM_OFFHOOK,
E_VTSP_DIGIT]em_offhook_digit_collect
Jan 11 17:19:01.503: sess_appl: ev(9=CC_EV_CALL_DIGIT_END),
cid(32995), disp(0)
Jan 11 17:19:01.503: cid(32995)st(SSA_CS_MAPPING)ev(SSA_EV_CALL_DIGIT)
oldst(SSA_CS_MAPPING)cfid(-1)csize(0)in(1)fDest(0)
Jan 11 17:19:01.503: ssaDigit
Jan 11 17:19:01.503: ssaDigit, 0. sct->digit , sct->digit len 0,
usrDigit 9, digit_tone_mode=0
Jan 11 17:19:01.503: ssaDigit,1. callinfo.called , digit 9,
callinfo.calling , x
rulecallingtag 0, xrulecalledtag 0
Jan 11 17:19:01.503: ssaDigit, 7. callinfo.calling , sct->digit 9,
result 1
Jan 11 17:19:01.603: vtsp_process_dsp_message:
MSG_TX_DTMF_DIGIT_BEGIN: digit=1, rtp_timestamp=0xED31C493

Jan 11 17:19:01.603: vtsp:[4/1:1:32995, S_DIGIT_COLLECT,
E_DSP_DTMF_DIGIT_BEGIN]
Jan 11 17:19:01.603: act_report_digit_begin
Jan 11 17:19:01.603: cc_api_call_digit_begin (dstVdbPtr=0x0,
dstCallId=0xFFFFFFFF
F, srcCallId=0x80E3,
digit=1, digit_begin_flags=0x1, rtp_timestamp=0xED31C493
rtp_expiration=0x0, dest_mask=0x1)
Jan 11 17:19:01.603: sess_appl: ev(10=CC_EV_CALL_DIGIT_BEGIN),
cid(32995), disp(0)
Jan 11 17:19:01.603:
cid(32995)st(SSA_CS_MAPPING)ev(SSA_EV_DIGIT_BEGIN)
oldst(SSA_CS_MAPPING)cfid(-1)csize(0)in(1)fDest(0)
Jan 11 17:19:01.603: ssaIgnore cid(32995),
st(SSA_CS_MAPPING),oldst(0), ev(10)
Jan 11 17:19:01.643: vtsp_process_dsp_message: MSG_TX_DTMF_DIGIT_OFF:
digit=1, duration=75
Jan 11 17:19:01.643: vtsp:[4/1:1:32995, S_DIGIT_COLLECT,
E_DSP_DTMF_DIGIT]
Jan 11 17:19:01.643: act_report_digit_end
Jan 11 17:19:01.643: vtsp_timer_stop: 31305322
Jan 11 17:19:01.643: cc_api_call_digit_end (dstVdbPtr=0x0,
dstCallId=0xFFFFFFFF,
srcCallId=0x80E3,
digit=1,duration=75,xruleCallingTag=0,xruleCalledTag=0,
dest_mask=0x1), digit_tone_mode=0
Jan 11 17:19:01.643: htsp_digit_ready: digit = 31

```

```

Jan 11 17:19:01.643: vtsp_timer: 31305322
Jan 11 17:19:01.643: htsp_process_event: [4/1:1(10), EM_OFFHOOK,
E_VTSP_DIGIT]em_offhook_digit_collect
Jan 11 17:19:01.643: sess_appl: ev(9=CC_EV_CALL_DIGIT_END),
cid(32995), disp(0)
Jan 11 17:19:01.643: cid(32995)st(SSA_CS_MAPPING)ev(SSA_EV_CALL_DIGIT)
oldst(SSA_CS_MAPPING)cfid(-1)csize(0)in(1)fDest(0)
Jan 11 17:19:01.643: ssaDigit
Jan 11 17:19:01.643: ssaDigit, 0. sct->digit 9, sct->digit len 1,
usrDigit 1, digit_tone_mode=0
Jan 11 17:19:01.643: ssaDigit,1. callinfo.called , digit 91,
callinfo.calling ,
xrulecallingtag 0, xrulecalledtag 0
Jan 11 17:19:01.643: ssaDigit, 7. callinfo.calling , sct->digit 91,
result 1
Jan 11 17:19:01.743: vtsp_process_dsp_message:
MSG_TX_DTMF_DIGIT_BEGIN: digit=8, rtp_timestamp=0xED31C493

Jan 11 17:19:01.743: vtsp:[4/1:1:32995, S_DIGIT_COLLECT,
E_DSP_DTMF_DIGIT_BEGIN]
Jan 11 17:19:01.743: act_report_digit_begin
Jan 11 17:19:01.743: cc_api_call_digit_begin (dstVdbPtr=0x0,
dstCallId=0xFFFFFFFF
F, srcCallId=0x80E3,
digit=8, digit_begin_flags=0x1, rtp_timestamp=0xED31C493
rtp_expiration=0x0, dest_mask=0x1)
Jan 11 17:19:01.743: sess_appl: ev(10=CC_EV_CALL_DIGIT_BEGIN),
cid(32995), disp(0)
Jan 11 17:19:01.743:
cid(32995)st(SSA_CS_MAPPING)ev(SSA_EV_DIGIT_BEGIN)
oldst(SSA_CS_MAPPING)cfid(-1)csize(0)in(1)fDest(0)
Jan 11 17:19:01.743: ssaIgnore cid(32995),
st(SSA_CS_MAPPING),oldst(0), ev(10) r
adius_decrypt: null length
Jan 11 17:19:01.843: vtsp_process_dsp_message: MSG_TX_DTMF_DIGIT_OFF:
digit=8, duration=75
Jan 11 17:19:01.843: vtsp:[4/1:1:32995, S_DIGIT_COLLECT,
E_DSP_DTMF_DIGIT]
Jan 11 17:19:01.843: act_report_digit_end
Jan 11 17:19:01.843: vtsp_timer_stop: 31305342
Jan 11 17:19:01.843: cc_api_call_digit_end (dstVdbPtr=0x0,
dstCallId=0xFFFFFFFF,
srcCallId=0x80E3,
digit=8,duration=75,xruleCallingTag=0,xruleCalledTag=0,
dest_mask=0x1), digi
t_tone_mode=0
Jan 11 17:19:01.843: htsp_digit_ready: digit = 38
Jan 11 17:19:01.843: vtsp_timer: 31305342
Jan 11 17:19:01.843: htsp_process_event: [4/1:1(10), EM_OFFHOOK,
E_VTSP_DIGIT]em_offhook_digit_collect
Jan 11 17:19:01.843: sess_appl: ev(9=CC_EV_CALL_DIGIT_END),
cid(32995), disp(0)
Jan 11 17:19:01.843: cid(32995)st(SSA_CS_MAPPING)ev(SSA_EV_CALL_DIGIT)
oldst(SSA_CS_MAPPING)cfid(-1)csize(0)in(1)fDest(0)
Jan 11 17:19:01.843: ssaDigit
Jan 11 17:19:01.843: ssaDigit, 0. sct->digit 91, sct->digit len 2,
usrDigit 8, d
igit_tone_mode=0
Jan 11 17:19:01.843: ssaDigit,1. callinfo.called , digit 918,
callinfo.calling ,
xrulecallingtag 0, xrulecalledtag 0
Jan 11 17:19:01.843: ssaDigit, 7. callinfo.calling , sct->digit 918,
result -1
Jan 11 17:19:01.843: ccCallDisconnect (callID=0x80E3, cause=0x1C

```

```
tag=0x0)
Jan 11 17:19:01.843: vtsp:[4/1:1:32995, S_DIGIT_COLLECT,
E_CC_DISCONNECT]
Jan 11 17:19:01.843: act_pre_con_disconnect
Jan 11 17:19:01.843: vtsp_ring_noan_timer_stop: 31305342
Jan 11 17:19:01.843: dsp_cp_tone_off: [4/1:1:32995] packet_len=8
channel_id=3 pa
cket_id=71
Jan 11 17:19:01.843: dsp_voice_mode: [4/1:1:32995] cdb 62DCEA70,
cdb->codec_para
ms.modem 2, inband_detect flags 0x21
Jan 11 17:19:01.843: map_dtmf_relay_type--digit relay mode: 2
Jan 11 17:19:01.843: dsp_voice_mode: [4/1:1:32995] packet_len=24
channel_id=3 pa
cket_id=73 coding_type=1 voice_field_size=160 VAD_flag=0
echo_length=256 comfort
_noise=1 inband_detect=33 digit_relay_mode=2 AGC_flag=0
Jan 11 17:19:01.843: dsp_cp_tone_on: [4/1:1:32995] packet_len=38
channel_id=3 pa
cket_id=72 tone_id=3 n_freq=2 freq_of_first=480
freq_of_second=620amp_of_first=
5206 amp_of_second=2928 direction=1 on_time_first=250
off_time_first=250 on_time_second=0 off_time_second=0
Jan 11 17:19:01.843: vtsp_timer: 31305342
Jan 11 17:19:01.843: htsp_pre_connect_disconnect, cdb = 62DCEA70 cause
= 1C
```

! since the call is disconnected because the number received was "unassigned" or "invalid" the router will start playing reorder tone and a timer will start (this timer is the wait-release timeout timer, with default 30 seconds. Notice that this call was disconnected prior to the connect state.

```
Jan 11 17:19:01.843: htsp_process_event: [4/1:1(10), EM_OFFHOOK,
E_HTSP_PRE_CONN_DISC]
Jan 11 17:19:31.844: vtsp_main: timer: 31308342
```

! the wait-release timer expires after 30 seconds.

```
Jan 11 17:19:31.844: vtsp:[4/1:1:32995, S_WAIT_RELEASE_NC, E_TIMER]
```

! the VTSP module is in wait release state for that call and it got event timer, which means that the timer expires so that it goes into another state.

```
Jan 11 17:19:31.844: act_pre_con_disc_rel htsp_release_req: cause 28,
no_onhook
0
Jan 11 17:19:31.844: htsp_process_event: [4/1:1(10), EM_OFFHOOK,
E_HTSP_RELEASE_REQ]em_offhook_release
Jan 11 17:19:31.844: htsp_timer_stop2 em_onhook (0)[recEive and
transMit4/1:1(10
)] set signal state = 0x0
Jan 11 17:19:31.844: htsp_timer_stop
Jan 11 17:19:31.844: em_start_timer: 400 ms
Jan 11 17:19:31.844: htsp_timer - 400 msec
```

! HTSP got an event requesting releasing the time slot and it goes into EM wait onhook state, but it cannot do anything since it says I am onhook already. And the router starts a timer of 400 msec.

```
Jan 11 17:19:32.296: htsp_process_event: [4/1:1(10), EM_WAIT_ONHOOK,
```

```
E_HTSP_EVENT_TIMER]em_wait_timeout
Jan 11 17:19:32.296: em_stop_timers
Jan 11 17:19:32.296: htsp_timer_stop
Jan 11 17:19:32.296: em_start_timer: 400 ms
Jan 11 17:19:32.296: htsp_timer - 400 msec
```

! when the 400 msec timer expires HTSP gets into EM clear pending state. And it starts another timer of 400 msec.

```
Jan 11 17:19:32.696: htsp_process_event: [4/1:1(10), EM_CLR_PENDING,
E_HTSP_EVENT_TIMER]em_clr_timeout
Jan 11 17:19:32.696: em_stop_timers
Jan 11 17:19:32.696: htsp_timer_stop
Jan 11 17:19:32.696: em_start_timer: 10000 ms
Jan 11 17:19:32.696: htsp_timer - 10000 msec
Jan 11 17:19:32.700: htsp_dsp_message: SEND/RESP_SIG_STATUS: state=0xC
timestamp=1533 systime=31308428
Jan 11 17:19:32.700: htsp_process_event: [4/1:1(10), EM_PARK,
E_DSP_SIG_1100]em_park_offhook
```

! when the 400 msec timer expires, the router puts the time slot into EM_PARK state, and it starts another timer of 10 seconds. And notice that the router is still seeing the ABCD=1100 from the switch.

```
Jan 11 17:19:42.760: htsp_process_event: [4/1:1(10), EM_PARK,
E_HTSP_EVENT_TIMER]em_park_timerhtsp_report_onhook_sig
Jan 11 17:19:42.760: em_offhook (0)[recEive and transMit4/1:1(10)] set
signal st
ate = 0x8em_onhook (1000)[recEive and transMit4/1:1(10)] set signal
state = 0x0
Jan 11 17:19:42.760: htsp_timer2 - 300000 msec
Jan 11 17:19:42.760: htsp_process_event: [4/1:1(10), EM_PARK,
E_HTSP_EVENT_TIMER]em_park_timerhtsp_report_onhook_sig
Jan 11 17:19:42.760: em_offhook (0)[recEive and transMit4/1:1(10)] set
signal state = 0x8em_onhook (1000)[recEive and transMit4/1:1(10)] set
signal state = 0x0
Jan 11 17:19:42.760: htsp_timer2 - 300000 msec
```

! as you see from the timestamps, when 10 seconds the timer expires, the router goes offhook for one second (1000 msec) and then onhook, and it also starts another timer of 300000 msec (5 minutes).

Related Information

- ◆ [Voice, Telephony and Messaging Technical Tips](#)
- ◆ [Voice, Telephony and Messaging Technologies](#)
- ◆ [Voice, Telephony and Messaging Products](#)
- ◆ [Voice, Telephony and Messaging Devices](#)
- ◆ [Voice, Telephony and Messaging Software](#)
- ◆ [Technical Assistance Center](#)
- ◆ [Voice, Telephony and Messaging Top Issues](#)
- ◆ [Field Notices](#)
- ◆ [Voice, Telephony and Messaging TAC eLearning Solutions](#)

All contents are Copyright © 1992—2002 Cisco Systems, Inc. All rights reserved. Important Notices and Privacy Statement.

Updated: Nov 27, 2002

Document ID: 18959

Introduction

Problem

Solution

Background Information

Fake Answer **Related Information**

Introduction

In digital E&M signaling on Cisco 2600, 3600, and MC3810 router platforms, some T1/E1 time slots may get stuck in the EM_PARK state. This is visible when you issue the **show voice call summary** command. This document explains how to troubleshoot this issue.

The following output shows that some time slots are in the EM_PARK state. Remember that a time slot in the EM_PARK state will not be used for voice calls.

```
Router#show voice call summary
PORT          CODEC      VAD      VTSP STATE      VPM STATE
=====      =====   ===      =====
1/0:0.1       -         -         -             EM_ONHOOK
1/0:0.2       -         -         -             EM_PARK
1/0:0.3       -         -         -             EM_PARK
1/0:0.4       -         -         -             EM_ONHOOK
1/0:0.5       -         -         -             EM_ONHOOK
```

Problem

There are two possible, major reasons for the time slot to be stuck in the EM_PARK state:

- ◇ The digital signal processor (DSP) is bad; either hardware or software issues.
- ◇ The PSTN switch/PBX is sending a continuous offhook signal to the router and not releasing it.

The following hardware and/or software is affected by this issue:

- ◇ Hardware—Cisco 2600, Cisco 3600, Cisco VG200, and MC3810 routers
- ◇ Software—All

Solution

If the time slots in your system are stuck in the EM_PARK state, first check the DSPs. To check the DSPs, refer to Troubleshooting the DSP on NM-HDV for Cisco 2600/3600 Series Routers.

If the DSPs are alive, the problem can be on the PSTN switch/PBX side or the Cisco IOS (router/gateway not starting the Fake Answer procedure). For more information, refer to the Fake Answer section.

Background Information

In T1 CAS (wink start signaling as an example), when the PBX goes offhook, the router/gateway side time slot remains in the idle (EM_ONHOOK) state until the call is answered by a remote destination. The router time slot state changes to EM_OFFHOOK when the call is answered by the remote destination.

If the call did not connect, the router/gateway plays the inband reorder tones to the caller. Since the channel state on the router side is still EM_ONHOOK, the router is unable to hang up the channel. After the caller hangs up, the PBX should change its channel state from offhook to onhook.

In some cases, the PBXs do not send the onhook messages (using the ABCD transitions). The router has a workaround for this called fake answer. Without the fake answer workaround, the channels will hang in a state of EM_PARK indefinitely.

Fake Answer

The Cisco router/gateway waits for a default value of 30 seconds (use **timeouts wait-release** and **timeouts call-disconnect** to change these values) after it knows that the time slot should be set from the PBX to onhook while playing the reorder tone.

If this does not happen, the router moves the time slot to the EM_PARK state and starts another timer with a duration of 10 seconds. If the PBX still does not go onhook after the 10-second duration, the router tricks the PBX by sending a *fake answer* of a 1-second duration and then goes onhook.

After sending the fake answer signal, the router starts another timer of five minutes. If the PBX goes onhook, the timer stops and the router transitions the time slot to the EM_ONHOOK state. Otherwise, after five minutes it sends another fake answer signal of a one-second duration, and it keeps repeating that until the PBX goes onhook. The router is forcing the PBX to clear the call.

Note: This answering transition will not be updated to any accounting record since the actual call was already cleared. The PBX will, however, understand it as an answer and the user will probably be charged for the one-second duration call.

If the DSP associated with the time slot in the EM_PARK state is alive and healthy and the problem persists, run the **debug vpm all** and **debug vtsp all** commands to see if Cisco IOS attempts to send the fake answer.

Note: You need to keep the debugs running for more than five minutes.

Note: In most cases, if the DSP is bad, the router will not perform the fake answer workaround. For more information, refer to Troubleshooting the DSP on NM-HDV for Cisco 2600/3600 Series Routers.

The debug output below shows how a time slot got stuck in EM_PARK and how the fake answer workaround works.

```
Jan 11 17:19:00.767: htsp_dsp_message: SEND/RESP_SIG_STATUS:  
state=0xC timestamp
```

```
=44262 systime=31305235
Jan 11 17:19:00.767: htsp_process_event:
[4/1:1(10), EM_ONHOOK, E_DSP_SIG_1100]em_onhook_offhook
htsp_setup_ind
```

```
! offhook signal was received from the switch
```

```
Jan 11 17:19:00.767: [4/1:1(10)] get_local_station_id calling
num= calling name=
calling time=01/11 17:19
Jan 11 17:19:00.767: vtsp_tsp_call_setup_ind (sdb=0x62BB7B14,
tdm_info=0x0, tsp_
info=0x62BB4050, calling_number= calling_oct3 = 0x0,
called_number= called_oct3
= 0x81, oct3a=0x0): peer_tag=0
Jan 11 17:19:00.767: : ev.clg.clir is 0
ev.clg.clid_transparent is
0
ev.clg.null_orig_clg is 1
ev.clg.calling_translated is false
```

```
Jan 11 17:19:00.767: htsp_timer - 3000 msec
Jan 11 17:19:00.767: vtsp_do_call_setup_ind
Jan 11 17:19:00.767: vtsp_allocate_cdb,cdb 0x62DCEA70
Jan 11 17:19:00.767: vtsp_do_call_setup_ind: Call ID=112722,
guid=62DC4230
Jan 11 17:19:00.767: vtsp_do_call_setup_ind: type=0,
under_spec=1640890368, name
=, id0=10, id1=1, id2=25038, calling=, called=
subscriber=RegularLine
Jan 11 17:19:00.767: vtsp_do_normal_call_setup_ind
Jan 11 17:19:00.771: cc_api_call_setup_ind (vdbPtr=0x62BB7FA0,
callInfo={called=
,called_oct3=0x81,calling=,calling_oct3=0x0,calling_oct3a=0x0,calling_xlated=
se,subscriber_type_str=RegularLine,fdest=0,peer_tag=0,
prog_ind=3},callID=0x62DC
40DC)
Jan 11 17:19:00.771: cc_api_call_setup_ind type 1 , prot 0
Jan 11 17:19:00.771: vtsp_insert_cdb,cdb 0x62DCEA70
Jan 11 17:19:00.771: vtsp_open_voice_and_set_params
Jan 11 17:19:00.771: dsp_close_voice_channel: [4/1:1:32995]
packet_len=8 channel
_id=3 packet_id=75
Jan 11 17:19:00.771: dsp_open_voice_channel_20: [4/1:1:32995]
packet_len=16 chan
nel_id=3 packet_id=74 alaw_ulaw_select=0
associated_signaling_channel=130 time_s
lot=2 serial_port=0
Jan 11 17:19:00.771: vtsp_modem_proto_from_cdb: cap_modem_proto
1073741824
Jan 11 17:19:00.771: vtsp_modem_proto_from_cdb: cap_modem_proto
1073741824
Jan 11 17:19:00.771: dsp_encap_config: [4/1:1:32995]
packet_len=30 channel_id=3
packet_id=92
TransportProtocol 2 t_ssrc=0x0 r_ssrc=0x0 t_vpxcc=0x0
r_vpxcc=0x0
sid_support=1, tse_payload=65535, seq_num=0x0, redundancy=0
Jan 11 17:19:00.771: dsp_set_playout_delay
Jan 11 17:19:00.771: dsp_set_playout: [4/1:1:32995]
packet_len=18 channel_id=3 p
acket_id=76 mode=1 initial=60 min=40 max=200 fax_nom=300
dsp_set_playout_delay_config
```

```

Jan 11 17:19:00.771: dsp_set_playout_config
Jan 11 17:19:00.771: mode 0, init 60, min 40, max 200 playout
default
Jan 11 17:19:00.771: dsp_set_playout_config:mode 0, init 60,
min 40, max 200
Jan 11 17:19:00.771: dsp_set_playout_config: [4/1:1:32995]
packet_len=18 channel
_id=3 packet_id=76 mode=1 initial=60 min=40 max=200 fax_nom=300
Jan 11 17:19:00.771: dsp_echo_canceler_control: echo_cancel: 1
Jan 11 17:19:00.771: dsp_echo_canceler_control: [4/1:1:32995]
echo_cancel 1, dis
able_hpf 0, flags=0x0, threshold=-21
Jan 11 17:19:00.771: dsp_echo_canceler_control: [4/1:1:32995]
packet_len=12 chan
nel_id=3 packet_id=66 flags=0x0, threshold=-21
Jan 11 17:19:00.771: set_gains: FXx/E&M:
msg->message.set_codec_gains.out_gain=0
Jan 11 17:19:00.771: dsp_set_gains: [4/1:1:32995] packet_len=12
channel_id=3 pac
ket_id=91 in_gain=0 out_gain=0
Jan 11 17:19:00.771: dsp_vad_enable: [4/1:1:32995] enable:
packet_len=12 channel
_id=3 packet_id=78 thresh=-38
Jan 11 17:19:00.771: cc_process_call_setup_ind
(event=0x62E63ACC)
Jan 11 17:19:00.771: >>>>CCAPI handed cid 32995 with tag 0 to
app "DEFAULT"
Jan 11 17:19:00.771: sess_appl: ev(24=CC_EV_CALL_SETUP_IND),
cid(32995), disp(0)
Jan 11 17:19:00.771: sess_appl: ev(SSA_EV_CALL_SETUP_IND),
cid(32995), disp(0)
Jan 11 17:19:00.771: ssaCallSetupInd
Jan 11 17:19:00.771: ccCallSetContext (callID=0x80E3,
context=0x62DFBCF0)
Jan 11 17:19:00.771: ssaCallSetupInd cid(32995),
st(SSA_CS_MAPPING),oldst(0), ev
(24)ev->e.evCallSetupInd.nCallInfo.finalDestFlag = 0
Jan 11 17:19:00.771: ccCallSetupAck (callID=0x80E3)
Jan 11 17:19:00.771: ccGenerateTone (callID=0x80E3 tone=8)
Jan 11 17:19:00.771: ccCallReportDigits (callID=0x80E3,
enable=0x1)
Jan 11 17:19:00.771: vtsp_report_digit_control: enable=1: digit
reporting enabled
Jan 11 17:19:00.771: cc_api_call_report_digits_done
(vdbPtr=0x62BB7FA0, callID=0x80E3, disp=0)
Jan 11 17:19:00.771: : vtsp_get_digit_timeouts
Jan 11 17:19:00.771: sess_appl:
ev(52=CC_EV_CALL_REPORT_DIGITS_DONE), cid(32995), disp(0)
Jan 11 17:19:00.771:
cid(32995)st(SSA_CS_MAPPING)ev(SSA_EV_CALL_REPORT_DIGITS_DONE)
oldst(SSA_CS_MAPPING)cfid(-1)csize(0)in(1)fDest(0)
Jan 11 17:19:00.771: ssaReportDigitsDone cid(32995) peer list:
(empty)
Jan 11 17:19:00.771: ssaReportDigitsDone callid=32995 Enable
succeeded
Jan 11 17:19:00.771: ccGenerateTone (callID=0x80E3 tone=8)
Jan 11 17:19:00.771: vtsp:[4/1:1:32995, S_SETUP_INDICATED,
E_CC_SETUP_ACK]
Jan 11 17:19:00.775: act_setup_ind_ack
Jan 11 17:19:00.775: vtsp_modem_proto_from_cdb: cap_modem_proto
0
Jan 11 17:19:00.775: vtsp_modem_proto_from_cdb: cap_modem_proto
0
Jan 11 17:19:00.775: dsp_encap_config: [4/1:1:32995]

```

```

packet_len=30 channel_id=3
packet_id=92 TransportProtocol 2 t_ssrc=0x0 r_ssrc=0x0
t_vpxcc=0x0 r_vpxcc=0x0
sid_support=1, tse_payload=65535, seq_num=0x0, redundancy=0
Jan 11 17:19:00.775: dsp_voice_mode: [4/1:1:32995] cdb
62DCEA70, cdb->codec_para
ms.modem 2, inband_detect flags 0x21
Jan 11 17:19:00.775: map_dtmf_relay_type--digit relay mode: 2
Jan 11 17:19:00.775: dsp_voice_mode: [4/1:1:32995]
packet_len=24 channel_id=3 pa
cket_id=73 coding_type=1 voice_field_size=160 VAD_flag=0
echo_length=256 comfort
_noise=1 inband_detect=33 digit_relay_mode=2
AGC_flag=0act_setup_ind_ack: modem_mode = 0, fax_relay_on = 1
Jan 11 17:19:00.775: act_setup_ind_ack(): dsp_dtmf_mode()
dsp_dtmf_mode(VTSP_TONE_DTMF_MODE)

Jan 11 17:19:00.775: dsp_dtmf_mode: [4/1:1:32995] packet_len=10
channel_id=3 pac
cket_id=65 dtmf_or_mf=0
Jan 11 17:19:00.775: vtsp_timer: 31305236
Jan 11 17:19:00.775: vtsp:[4/1:1:32995, S_DIGIT_COLLECT,
E_CC_GEN_TONE]
Jan 11 17:19:00.775: act_gen_tone
Jan 11 17:19:00.775: dsp_cp_tone_off: [4/1:1:32995]
packet_len=8 channel_id=3 pa
cket_id=71
Jan 11 17:19:00.775: dsp_cp_tone_on: [4/1:1:32995]
packet_len=38 channel_id=3 pa
cket_id=72 tone_id=4 n_freq=2 freq_of_first=350
freq_of_second=440 amp_of_first=
5514 amp_of_second=5514 direction=1 on_time_first=65535
off_time_first=0 on_time_second=0 off_time_second=0
Jan 11 17:19:00.775: vtsp:[4/1:1:32995, S_DIGIT_COLLECT,
E_CC_GEN_TONE]
Jan 11 17:19:00.775: act_gen_tone
Jan 11 17:19:00.775: dsp_cp_tone_off: [4/1:1:32995]
packet_len=8 channel_id=3 pa
cket_id=71
Jan 11 17:19:00.775: dsp_cp_tone_on: [4/1:1:32995]
packet_len=38 channel_id=3 pa
cket_id=72 tone_id=4 n_freq=2 freq_of_first=350
freq_of_second=440 amp_of_first=
5514 amp_of_second=5514 direction=1 on_time_first=65535
off_time_first=0 on_time
_second=0 off_time_second=0
Jan 11 17:19:00.775: htsp_process_event: [4/1:1(10),
EM_WAIT_SETUP_ACK, E_HTSP_SETUP_ACK]em_wait_setup_ack_get_ack
Jan 11 17:19:00.775: htsp_timer_stop
Jan 11 17:19:00.775: htsp_timer2 - 172 msec
Jan 11 17:19:00.947: htsp_process_event: [4/1:1(10),
EM_WAIT_SETUP_ACK, E_HTSP_EVENT_TIMER2]em_wait_prewink_timer
Jan 11 17:19:00.947: em_offhook (0)[recEive and
transMit4/1:1(10)] set signal st
ate = 0x8em_onhook (200)[recEive and transMit4/1:1(10)] set
signal state = 0x0

! wink of duration 200 msec was sent out to the switch

Jan 11 17:19:01.471: vtsp_process_dsp_message:
MSG_TX_DTMF_DIGIT_BEGIN: digit=9,
rtp_timestamp=0xED31C493

```

```

Jan 11 17:19:01.471: vtsp:[4/1:1:32995, S_DIGIT_COLLECT,
E_DSP_DTMF_DIGIT_BEGIN]
Jan 11 17:19:01.471: act_report_digit_begin
Jan 11 17:19:01.471: cc_api_call_digit_begin (dstVdbPtr=0x0,
dstCallId=0xFFFFFFFF
F, srcCallId=0x80E3,
digit=9, digit_begin_flags=0x1, rtp_timestamp=0xED31C493
rtp_expiration=0x0, dest_mask=0x1)
Jan 11 17:19:01.471: sess_appl: ev(10=CC_EV_CALL_DIGIT_BEGIN),
cid(32995), disp(0)
Jan 11 17:19:01.471:
cid(32995)st(SSA_CS_MAPPING)ev(SSA_EV_DIGIT_BEGIN)
oldst(SSA_CS_MAPPING)cfid(-1)csize(0)in(1)fDest(0)
Jan 11 17:19:01.471: ssaIgnore cid(32995),
st(SSA_CS_MAPPING),oldst(0), ev(10)
Jan 11 17:19:01.503: vtsp_process_dsp_message:
MSG_TX_DTMF_DIGIT_OFF: digit=9, duration=65
Jan 11 17:19:01.503: vtsp:[4/1:1:32995, S_DIGIT_COLLECT,
E_DSP_DTMF_DIGIT]
Jan 11 17:19:01.503: act_report_digit_end
Jan 11 17:19:01.503: vtsp_timer_stop: 31305308
Jan 11 17:19:01.503: dsp_cp_tone_off: [4/1:1:32995]
packet_len=8 channel_id=3 pa
cket_id=71
Jan 11 17:19:01.503: cc_api_call_digit_end (dstVdbPtr=0x0,
dstCallId=0xFFFFFFFF,
srcCallId=0x80E3,
digit=9,duration=65,xruleCallingTag=0,xruleCalledTag=0,
dest_mask=0x1), digi
t_tone_mode=0
Jan 11 17:19:01.503: htsp_digit_ready: digit = 39
Jan 11 17:19:01.503: vtsp_timer: 31305308
Jan 11 17:19:01.503: htsp_process_event: [4/1:1(10),
EM_OFFHOOK, E_VTSP_DIGIT]em_offhook_digit_collect
Jan 11 17:19:01.503: sess_appl: ev(9=CC_EV_CALL_DIGIT_END),
cid(32995), disp(0)
Jan 11 17:19:01.503:
cid(32995)st(SSA_CS_MAPPING)ev(SSA_EV_CALL_DIGIT)
oldst(SSA_CS_MAPPING)cfid(-1)csize(0)in(1)fDest(0)
Jan 11 17:19:01.503: ssaDigit
Jan 11 17:19:01.503: ssaDigit, 0. sct->digit , sct->digit len
0, usrDigit 9, digit_tone_mode=0
Jan 11 17:19:01.503: ssaDigit,1. callinfo.called , digit 9,
callinfo.calling , x
rulecallingtag 0, xrulecalledtag 0
Jan 11 17:19:01.503: ssaDigit, 7. callinfo.calling , sct->digit
9, result 1
Jan 11 17:19:01.603: vtsp_process_dsp_message:
MSG_TX_DTMF_DIGIT_BEGIN: digit=1, rtp_timestamp=0xED31C493

Jan 11 17:19:01.603: vtsp:[4/1:1:32995, S_DIGIT_COLLECT,
E_DSP_DTMF_DIGIT_BEGIN]
Jan 11 17:19:01.603: act_report_digit_begin
Jan 11 17:19:01.603: cc_api_call_digit_begin (dstVdbPtr=0x0,
dstCallId=0xFFFFFFFF
F, srcCallId=0x80E3,
digit=1, digit_begin_flags=0x1, rtp_timestamp=0xED31C493
rtp_expiration=0x0, dest_mask=0x1)
Jan 11 17:19:01.603: sess_appl: ev(10=CC_EV_CALL_DIGIT_BEGIN),
cid(32995), disp(0)
Jan 11 17:19:01.603:
cid(32995)st(SSA_CS_MAPPING)ev(SSA_EV_DIGIT_BEGIN)
oldst(SSA_CS_MAPPING)cfid(-1)csize(0)in(1)fDest(0)
Jan 11 17:19:01.603: ssaIgnore cid(32995),

```

```

st(SSA_CS_MAPPING),oldst(0), ev(10)
Jan 11 17:19:01.643: vtsp_process_dsp_message:
MSG_TX_DTMF_DIGIT_OFF: digit=1, duration=75
Jan 11 17:19:01.643: vtsp:[4/1:1:32995, S_DIGIT_COLLECT,
E_DSP_DTMF_DIGIT]
Jan 11 17:19:01.643: act_report_digit_end
Jan 11 17:19:01.643: vtsp_timer_stop: 31305322
Jan 11 17:19:01.643: cc_api_call_digit_end (dstVdbPtr=0x0,
dstCallId=0xFFFFFFFF,
srcCallId=0x80E3,
digit=1,duration=75,xruleCallingTag=0,xruleCalledTag=0,
dest_mask=0x1), digit_tone_mode=0
Jan 11 17:19:01.643: htsp_digit_ready: digit = 31
Jan 11 17:19:01.643: vtsp_timer: 31305322
Jan 11 17:19:01.643: htsp_process_event: [4/1:1(10),
EM_OFFHOOK, E_VTSP_DIGIT]em_offhook_digit_collect
Jan 11 17:19:01.643: sess_appl: ev(9=CC_EV_CALL_DIGIT_END),
cid(32995), disp(0)
Jan 11 17:19:01.643:
cid(32995)st(SSA_CS_MAPPING)ev(SSA_EV_CALL_DIGIT)
oldst(SSA_CS_MAPPING)cfid(-1)csize(0)in(1)fDest(0)
Jan 11 17:19:01.643: ssaDigit
Jan 11 17:19:01.643: ssaDigit, 0. sct->digit 9, sct->digit len
1, usrDigit 1, digit_tone_mode=0
Jan 11 17:19:01.643: ssaDigit,1. callinfo.called , digit 91,
callinfo.calling ,
xrulecallingtag 0, xrulecalledtag 0
Jan 11 17:19:01.643: ssaDigit, 7. callinfo.calling , sct->digit
91, result 1
Jan 11 17:19:01.743: vtsp_process_dsp_message:
MSG_TX_DTMF_DIGIT_BEGIN: digit=8, rtp_timestamp=0xED31C493

Jan 11 17:19:01.743: vtsp:[4/1:1:32995, S_DIGIT_COLLECT,
E_DSP_DTMF_DIGIT_BEGIN]
Jan 11 17:19:01.743: act_report_digit_begin
Jan 11 17:19:01.743: cc_api_call_digit_begin (dstVdbPtr=0x0,
dstCallId=0xFFFFFFFF
F, srcCallId=0x80E3,
digit=8, digit_begin_flags=0x1, rtp_timestamp=0xED31C493
rtp_expiration=0x0, dest_mask=0x1)
Jan 11 17:19:01.743: sess_appl: ev(10=CC_EV_CALL_DIGIT_BEGIN),
cid(32995), disp(0)
Jan 11 17:19:01.743:
cid(32995)st(SSA_CS_MAPPING)ev(SSA_EV_DIGIT_BEGIN)
oldst(SSA_CS_MAPPING)cfid(-1)csize(0)in(1)fDest(0)
Jan 11 17:19:01.743: ssaIgnore cid(32995),
st(SSA_CS_MAPPING),oldst(0), ev(10) r
adius_decrypt: null length
Jan 11 17:19:01.843: vtsp_process_dsp_message:
MSG_TX_DTMF_DIGIT_OFF: digit=8, duration=75
Jan 11 17:19:01.843: vtsp:[4/1:1:32995, S_DIGIT_COLLECT,
E_DSP_DTMF_DIGIT]
Jan 11 17:19:01.843: act_report_digit_end
Jan 11 17:19:01.843: vtsp_timer_stop: 31305342
Jan 11 17:19:01.843: cc_api_call_digit_end (dstVdbPtr=0x0,
dstCallId=0xFFFFFFFF,
srcCallId=0x80E3,
digit=8,duration=75,xruleCallingTag=0,xruleCalledTag=0,
dest_mask=0x1), digi
t_tone_mode=0
Jan 11 17:19:01.843: htsp_digit_ready: digit = 38
Jan 11 17:19:01.843: vtsp_timer: 31305342
Jan 11 17:19:01.843: htsp_process_event: [4/1:1(10),
EM_OFFHOOK, E_VTSP_DIGIT]em_offhook_digit_collect

```

```

Jan 11 17:19:01.843: sess_appl: ev(9=CC_EV_CALL_DIGIT_END),
cid(32995), disp(0)
Jan 11 17:19:01.843:
cid(32995)st(SSA_CS_MAPPING)ev(SSA_EV_CALL_DIGIT)
oldst(SSA_CS_MAPPING)cfid(-1)csize(0)in(1)fDest(0)
Jan 11 17:19:01.843: ssaDigit
Jan 11 17:19:01.843: ssaDigit, 0. sct->digit 91, sct->digit len
2, usrDigit 8, d
igit_tone_mode=0
Jan 11 17:19:01.843: ssaDigit,1. callinfo.called , digit 918,
callinfo.calling ,
xrulecallingtag 0, xrulecalledtag 0
Jan 11 17:19:01.843: ssaDigit, 7. callinfo.calling , sct->digit
918, result -1
Jan 11 17:19:01.843: ccCallDisconnect (callID=0x80E3,
cause=0x1C tag=0x0)
Jan 11 17:19:01.843: vtsp:[4/1:1:32995, S_DIGIT_COLLECT,
E_CC_DISCONNECT]
Jan 11 17:19:01.843: act_pre_con_disconnect
Jan 11 17:19:01.843: vtsp_ring_noan_timer_stop: 31305342
Jan 11 17:19:01.843: dsp_cp_tone_off: [4/1:1:32995]
packet_len=8 channel_id=3 pa
cket_id=71
Jan 11 17:19:01.843: dsp_voice_mode: [4/1:1:32995] cdb
62DCEA70, cdb->codec_para
ms.modem 2, inband_detect flags 0x21
Jan 11 17:19:01.843: map_dtmf_relay_type--digit relay mode: 2
Jan 11 17:19:01.843: dsp_voice_mode: [4/1:1:32995]
packet_len=24 channel_id=3 pa
cket_id=73 coding_type=1 voice_field_size=160 VAD_flag=0
echo_length=256 comfort
_noise=1 inband_detect=33 digit_relay_mode=2 AGC_flag=0
Jan 11 17:19:01.843: dsp_cp_tone_on: [4/1:1:32995]
packet_len=38 channel_id=3 pa
cket_id=72 tone_id=3 n_freq=2 freq_of_first=480
freq_of_second=620amp_of_first=
5206 amp_of_second=2928 direction=1 on_time_first=250
off_time_first=250 on_time_second=0 off_time_second=0
Jan 11 17:19:01.843: vtsp_timer: 31305342
Jan 11 17:19:01.843: htsp_pre_connect_disconnect, cdb =
62DCEA70 cause = 1C

```

! since the call is disconnected because the number received was "unassigned" or "invalid" the router will start playing reorder tone and a timer will start (this timer is the wait-release timeout timer, with default 30 seconds. Notice that this call was disconnected prior to the connect state.

```

Jan 11 17:19:01.843: htsp_process_event: [4/1:1(10),
EM_OFFHOOK, E_HTSP_PRE_CONN_DISC]
Jan 11 17:19:31.844: vtsp_main: timer: 31308342

```

! the wait-release timer expires after 30 seconds.

```

Jan 11 17:19:31.844: vtsp:[4/1:1:32995, S_WAIT_RELEASE_NC,
E_TIMER]

```

! the VTSP module is in wait release state for that call and it got event timer, which means that the timer expires so that it goes into another state.

```

Jan 11 17:19:31.844: act_pre_con_disc_rel htsp_release_req:
cause 28, no_onhook

```

0
Jan 11 17:19:31.844: htsp_process_event: [4/1:1(10),
EM_OFFHOOK, E_HTSP_RELEASE_REQ]em_offhook_release
Jan 11 17:19:31.844: htsp_timer_stop2 em_onhook (0)[recEive and
transMit4/1:1(10
)] set signal state = 0x0
Jan 11 17:19:31.844: htsp_timer_stop
Jan 11 17:19:31.844: em_start_timer: 400 ms
Jan 11 17:19:31.844: htsp_timer - 400 msec

! HTSP got an event requesting releasing the time slot and it goes into EM wait onhook state, but it cannot do anything since it says I am onhook already. And the router starts a timer of 400 msec.

Jan 11 17:19:32.296: htsp_process_event: [4/1:1(10),
EM_WAIT_ONHOOK, E_HTSP_EVENT_TIMER]em_wait_timeout
Jan 11 17:19:32.296: em_stop_timers
Jan 11 17:19:32.296: htsp_timer_stop
Jan 11 17:19:32.296: em_start_timer: 400 ms
Jan 11 17:19:32.296: htsp_timer - 400 msec

! when the 400 msec timer expires HTSP gets into EM clear pending state. And it starts another timer of 400 msec.

Jan 11 17:19:32.696: htsp_process_event: [4/1:1(10),
EM_CLR_PENDING, E_HTSP_EVENT_TIMER]em_clr_timeout
Jan 11 17:19:32.696: em_stop_timers
Jan 11 17:19:32.696: htsp_timer_stop
Jan 11 17:19:32.696: em_start_timer: 10000 ms
Jan 11 17:19:32.696: htsp_timer - 10000 msec
Jan 11 17:19:32.700: htsp_dsp_message: SEND/RESP_SIG_STATUS:
state=0xC timestamp=1533 systemtime=31308428
Jan 11 17:19:32.700: htsp_process_event: [4/1:1(10), EM_PARK,
E_DSP_SIG_1100]em_park_offhook

! when the 400 msec timer expires, the router puts the time slot into EM_PARK state, and it starts another timer of 10 seconds. And notice that the router is still seeing the ABCD=1100 from the switch.

Jan 11 17:19:42.760: htsp_process_event: [4/1:1(10), EM_PARK,
E_HTSP_EVENT_TIMER]em_park_timerhtsp_report_onhook_sig
Jan 11 17:19:42.760: em_offhook (0)[recEive and
transMit4/1:1(10)] set signal st
ate = 0x8em_onhook (1000)[recEive and transMit4/1:1(10)] set
signal state = 0x0
Jan 11 17:19:42.760: htsp_timer2 - 300000 msec
Jan 11 17:19:42.760: htsp_process_event: [4/1:1(10), EM_PARK,
E_HTSP_EVENT_TIMER]em_park_timerhtsp_report_onhook_sig
Jan 11 17:19:42.760: em_offhook (0)[recEive and
transMit4/1:1(10)] set signal state = 0x8em_onhook
(1000)[recEive and transMit4/1:1(10)] set signal state = 0x0
Jan 11 17:19:42.760: htsp_timer2 - 300000 msec

! as you see from the timestamps, when 10 seconds the timer expires, the router goes offhook for one second (1000 msec) and then onhook, and it also starts another timer of 300000 msec (5 minutes).

Related Information

- ◇ [Voice, Telephony and Messaging Technical Tips](#)
 - ◇ [Voice, Telephony and Messaging Technologies](#)
 - ◇ [Voice, Telephony and Messaging Products](#)
 - ◇ [Voice, Telephony and Messaging Devices](#)
 - ◇ [Voice, Telephony and Messaging Software](#)
 - ◇ [Technical Assistance Center](#)
 - ◇ [Voice, Telephony and Messaging Top Issues](#)
 - ◇ [Field Notices](#)
 - ◇ [Voice, Telephony and Messaging TAC eLearning Solutions](#)
-
-

Updated: Nov 27, 2002

Document ID: 18959
