

Recall, End of Sales, End of Engineering and End of Life for Cisco uBR914 Cable Data Service Unit

Cisco Systems, Inc. is announcing the recall, end of sales (EOS), end of engineering (EOE), and end of life (EOL) for the Cisco uBR914 Cable Data Service Unit. Milestone dates are listed in Table 1.

Effective June 12, 2001, Cisco Systems is recalling the Cisco uBR914 Cable Data Service Unit. At the same time, we are announcing EOS, EOE, and EOL of the product. Customers who purchased this product are being offered full refund or credit on future purchase. Cisco will work with those customers using the Cisco uBR914 Cable Data Service Unit in a production environment and help identify the best migration plan on a case-by-case basis.

Table 1 Cisco uBR914 Cable Data Service Unit Milestones

Milestone	Effective Date
Recall	June 12, 2001
End of Sales (EOS)	June 12, 2001
End of Engineering (EOE)	June 12, 2001
End of Life (EOL)	September 12, 2001

Definitions

- Recall: Cisco requests customers return equipment for full refund or credit on future product.
- EOS: The date at which product is removed from the price list and is no longer orderable through the normal, non-exception, order fulfillment process.
- EOE: The date after which scheduled maintenance releases will not be produced; no software and hardware is produced; no contracts are renewed.
- EOL: The date after which Cisco's customer support organization no longer supports the product.

Hardware Products Affected

- UBR914
- UBR914-SER-KIT
- SER-UBR914-1T
- SER-UBR914-1T=
- UBR914-RPS
- UBR914-RPS=
- UBR914-RM19
- UBR914-RM24

Software Products Affected

The last Cisco uBR914 Cable Data Service Unit software release is Cisco IOS 12.2(1). Detailed image information is shown below:

Table 2 Software Products Affected

Ordering Number	Feature Set	Comment
S91C6K8-12201	IP routing	Current baseline image for uBR914
S91C9-12105T	IP bridging	
S91S91C6-12105T	IP routing	
S91C9-12103T	IP bridging	
S91S91C6-12103T	IP routing	

Product Replacement

Although there is no direct replacement for the Cisco uBR914 Cable Data Service Unit, an alternative solution will be provided as determined on a case-by-case basis for customers using the product in a production environment.

Availability

Cisco uBR914 Cable Data Service Unit orderability will be closed on June 12, 2001.

Assistance

For specific orderability questions, please contact your Customer Service Representative.



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems Europe
11, Rue Camille Desmoulins
92782 Issy Les Moulineaux
Cedex 9
France
www.cisco.com
Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems Australia, Pty., Ltd
Level 17, 99 Walker Street
North Sydney
NSW 2059 Australia
www.cisco.com
Tel: +61 2 8448 7100
Fax: +61 2 9957 4350

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the

Cisco.com Web site at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam •

All contents are Copyright © 1992–2001 Cisco Systems, Inc. All rights reserved. Important Notices and Privacy Statement. Access Registrar, AccessPath, Are You Ready, ATM Director, Browse with Me, CCDA, CCDE, CCDP, CCIE, CCNA, CCNP, CCSI, CD-PAC, *CiscoLink*, the Cisco NetWorks logo, the Cisco Powered Network logo, Cisco Systems Networking Academy, Fast Step, FireRunner, Follow Me Browsing, FormShare, GigaStack, IGX, Intelligence in the Optical Core, Internet Quotient, IP/VC, iQ Breakthrough, iQ Expertise, iQ FastTrack, iQuick Study, iQ Readiness Scorecard, The iQ Logo, Kernel Proxy, MGX, Natural Network Viewer, Network Registrar, the Networkers logo, *Packet*, PIX, Point and Click Internetworking, Policy Builder, RateMUX, ReyMaster, ReyView, ScriptShare, Secure Script, Shop with Me, SlideCast, SMARTnet, SVX, TrafficDirector, TransPath, VlanDirector, Voice LAN, Wavelength Router, Workgroup Director, and Workgroup Stack are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, Empowering the Internet Generation, are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, Cisco, the Cisco Certified Internetwork Expert Logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Collision Free, Enterprise/Solver, EtherChannel, EtherSwitch, FastHub, FastLink, FastPAD, IOS, IP/TV, IPX, LightStream, LightSwitch, MICA, NetRanger, Post-Routing, Pre-Routing, Registrar, StrataView Plus, Stratm, SwitchProbe, TeleRouter, are registered trademarks of Cisco Systems, Inc. or its affiliates in the U.S. and certain other countries.

All other brands, names, or trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0103R)