



Cisco 12000 Series Ten-Port Gigabit Ethernet Line Card End-of-Sale Announcement

Cisco Systems is announcing the end of sale (EOS) for the Cisco 12000 Series Ten-Port Gigabit Ethernet Line Card. A newer, modular Gigabit Ethernet line card is now available that provides field-configurable multiple-port Gigabit Ethernet versatility, enabling service providers to cost-effectively scale their distribution networks and data centers to higher traffic capacities in order to deliver sophisticated, higher-value services without increasing complexity (refer to Tables 1 and 2).

Table 1 Line Cards and Associated Product IDs That Will No Longer be Orderable After December 1, 2002

Line Card	Product ID
Cisco 12000 Series Ten-Port Gigabit Ethernet Line Card	10x1GE-SFP-LC-B

Table 2 Alternate Line Cards and Associated Part Numbers

Line Card	Part number	Minimum Cisco IOS® Software Release Required
Cisco 12000 Series Modular Gigabit Ethernet Line Card (baseboard)	EPA-GE/FE-BBRD	12.0.(21)SZ or 12.0(23)S
Three-Port Gigabit Ethernet port adapter for above line card	EPA-3GE-SX/LH-LC	12.0.(21)SZ or 12.0(23)S
Cisco 12000 Series Three-Port Gigabit Ethernet Line Card	3 GE-GBIC-SC	12.0(11)S3



Key Dates

Table 3 lists the key dates associated with this product bulletin.

Table 3 [Needs Table Title]

Milestone	Definitions	Date
EOS bulletin	This document.	August 1, 2002
End of orderability and removal from Cisco price list (EOS)	The product will no longer be orderable and will no longer be on the Cisco price list.	December 1, 2002
End of hardware support	Cisco will no longer provide hardware fixes to newly discovered hardware bugs.	December 1, 2004
End of software support	Cisco will no longer provide software fixes to newly discovered software bugs.	December 1, 2005
End of one-year service contract renewals	One-year service contracts for this product will not be renewed after this date.	December 1, 2006
End of six-month service contract renewals	Six-month service contracts for this product will not be renewed after this date.	June 1, 2007
End of support (product obsolescence)	Cisco will no longer support these products and they are considered obsolete. Cisco Customer Advocacy Service Logistics will no longer carry inventory for customer return material authorizations (RMAs). The Cisco Technical Assistance Center (TAC) will no longer support these products.	December 1, 2007

If you have questions or need more information, contact your Cisco account team.



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: +65 317 7777
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the
Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992-2002, Cisco Systems, Inc. All rights reserved. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company.
(0208R) LW3613 0902