

Cisco IOS Early Deployment Release 12.0(5)WC9

Introduction

This Product Bulletin describes the content and delivery information concerning Cisco IOS® Software Release 12.0(5)WC9. This release is only for the Cisco Catalyst® 2900 Series XL, Cisco Catalyst 2900 LRE Series XL, and Cisco Catalyst 3500 Series XL switches. For more information about the Cisco IOS Software release process, please see Product Bulletin No. 537 located at: http://www.cisco.com/warp/public/cc/pd/iosw/iore/prodlit/537_pp.htm

Migration Guide

Figures 1 and 2 show the Cisco IOS 12.0(5)WC9 release functionality relative to the 12.0 and 12.0T releases. This diagram identifies the recommended migration path. Refer to Figure 1 for the recommended migration path for the Cisco Catalyst 2900 LRE XL. Refer to Figure 2 for the recommended migration path for the Cisco Catalyst 2900 XL and Cisco Catalyst 3500 XL switches.

Figure 1
Cisco IOS Release 12.0(5)WC9 Release Train and Migration Path for the Cisco Catalyst 2900 LRE XL Switches.





Figure 2
Cisco IOS Release 12.0(5)WC9 Release Train and Migration Path for the Cisco Catalyst 2900 Series XL and 3500 Series XL Switches.



New Features in Cisco IOS Release 12.0(5)WC9

This release is a maintenance release. There are no new feature enhancements.

Detailed Information

For more information on this software release, refer to the following Release Notes:

<http://www.cisco.com/univercd/cc/td/doc/product/lan/c2900xl/index.htm>

Support

Cisco IOS Software Release 12.0(5)WC9 follows the standard Cisco support policy:

<http://www.cisco.com/warp/public/437/27.html>

Table 1 Cisco Catalyst 2900 XL, 2900 LRE XL, and 3500 XL Cisco IOS Software Release

Platform	Cisco IOS Software Feature Set	Product Code	Image	Flash	DRAM
Cisco Catalyst 2900 Series XL	12.0(5)WC9	N/A	c2900xl-c3h2s-mz.120-5.WC9.bin	4 MB	8 MB
Cisco Catalyst 2900 Series LRE XL	12.0(5)WC9	N/A	c2900xl-c3h2l9s-mz.120-5.WC9.bin	8 MB	16 MB
Cisco Catalyst 3500 Series XL	12.0(5)WC9	N/A	c3500xl-c3h2s-mz.120-5.WC9.bin	4 MB	8 MB

Software Download Information

Customers can download Cisco IOS Release 12.0(5)WC9 software from Cisco in the Software Image Library:

<http://www.cisco.com/public/sw-center/sw-ios.shtml>



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the

Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2003 Cisco Systems, Inc. All rights reserved. CCIP, CCSP, the Cisco Arrow logo, the Cisco *Powered* Network mark, Cisco Unity, Follow Me Browsing, FormShare, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, MGX, MICA, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, ScriptShare, SlideCast, SMARTnet, StrataView Plus, Stratm, SwitchProbe, TeleRouter, The Fastest Way to Increase Your Internet Quotient, TransPath, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company.
(0304R) ETMG 203144—MH 09/03