

# Cisco IOS™ 2500 Series 11.1 to 11.2 Upgrade Path

## For Customers Without SMARTnet Contracts

**Table 25:** 2500 Upgrade Path from 11.1 to 11.2 for Increased Functionality

		From 11.1							
		IP	IP/IBM	IP/IPX/IBM	IP/IPX/IBM/ APPN	Desktop	Desktop/ IBM	Enterprise	Enterprise/ APPN
To: 11.2	IP	SW25C-11.2xx=	—	—	—	—	—	—	—
	IP Plus	SW25CP-11.2xx= and FL25-P=	SW25CP-11.2xx= and FL25-CS-C= and FL25-IBM-P=	SW25CP-11.2xx= and FL25-DS-C= and FL25-IBM-P=	—	—	—	—	—
	IP Plus 40	SW25CW-11.2xx= and FL25-W=	SW25CP-11.2xx= and FL25-CS-C= and FL25-IBM-P= and FL25-P-W=	SW25CW-11.2xx= and FL25-DS-C= and FL25-IBM-P= and FL25-P-W=	—	—	—	—	—
	IP Plus 56	SW25CY-11.2xx= and FL25-Y=	SW25CP-11.2xx= and FL25-CS-C= and FL25-IBM-P= and FL25-P-Y=	SW25CY-11.2xx= and FL25-DS-C= and FL25-IBM-P= and FL25-P-Y=	—	—	—	—	—
	IP/IPX/IBM/APPN	SW25DSN-11.2xx= and FL25-C-DS= and FL25-APPN=	SW25DSN-11.2xx= and FL25-CS-DS= and FL25-APPN=	SW25DSN-11.2xx= and FL25-APPN=	SW25DSN-11.2xx=	—	—	—	—
	IP/IPX/AT/DEC	SW25B-11.2xx= and FL25-C-B=	SW25B-11.2xx= and FL25-CS-B=	—	—	SW25B-11.2xx=	SW25B-11.2xx= and FL25-BS-B=	—	—
	IP/IPX/AT/DEC Plus	SW25BP-11.2xx= and FL25-C-B= and FL25-P=	SW25BP-11.2xx= and FL25-CS-B= and FL25-IBM-P=	SW25BP-11.2xx= and FL25-DS-B= and FL25-IBM-P=	SW25BP-11.2xx= and FL25-IBM-P=	SW25BP-11.2xx= and FL25-P=	SW25BP-11.2xx= and FL25-BS-B= and FL25-IBM-P=	—	—

From 11.1(Continued)									
	IP	IP/IBM	IP/IPX/IBM	IP/IPX/IBM/ APPN	Desktop	Desktop/ IBM	Enterprise	Enterprise/ APPN	
To: 11.2 (Continued)	IP/IPX/AT/DEC Plus 40	SW25BW-11.2xx= and FL25-C-B= and FL25-W=	SW25BW-11.2xx= and FL25-CS-B= and FL25-IBM-P= and FL25-P-W=	SW25BW-11.2xx= and FL25-DS-B= and FL25-IBM-P= and FL25-P-W=	SW25BW-11.2xx= and FL25-IBM-P= and FL25-P-W=	SW25BW-11.2xx= and FL25-W=	SW25BW-11.2xx= and FL25-BS-B= and FL25-IBM-P and FL25-P-W=	—	—
	IP/IPX/AT/DEC Plus 56	SW25BY-11.2xx= and FL25-C-B= and FL25-Y=	SW25BY-11.2xx= and FL25-CS-B= and FL25-IBM-P= and FL25-P-Y=	SW25BY-11.2xx= and FL25-DS-B= and FL25-IBM-P= and FL25-P-Y=	SW25BY-11.2xx= and FL25-IBM-P= and FL25-P-Y=	SW25BY-11.2xx= and FL25-Y=	SW25BY-11.2xx= and FL25-BS-B= and FL25-IBM-P= and FL25-P-Y=	—	—
	Enterprise	SW25A-11.2xx= and FL25-C-A=	SW25A-11.2xx= and FL25-CS-A=	SW25A-11.2xx= and FL25-DS-A=	SW25A-11.2xx= and FL25-DS-A=	SW25A-11.2xx= and FL25-B-A=	SW25A-11.2xx= and FL25-BS-A=	SW25A-11.2xx=	—
	Enterprise Plus	SW25AP-11.2xx= and FL25-C-A= and FL25-P=	SW25AP-11.2xx= and FL25-CS-A= and FL25-IBM-P=	SW25AP-11.2xx= and FL25-DS-A= and FL25-IBM-P=	SW25AP-11.2xx= and FL25-DS-A= and FL25-IBM-P=	SW25AP-11.2xx= and FL25-B-A= and FL25-P=	SW25AP-11.2xx= and FL25-BS-A= and FL25-IBM-P=	SW25AP-11.2xx= and FL25-P=	—
	Enterprise Plus 40	SW25AW-11.2xx= and FL25-C-A= and FL25-W=	SW25AW-11.2xx= and FL25-CS-A= and FL25-IBM-P= and FL25-P-W=	SW25AW-11.2xx= and FL25-DS-A= and FL25-IBM-P= and FL25-P-W=	SW25AW-11.2xx= and FL25-DS-A= and FL25-IBM-P= and FL25-P-W=	SW25AW-11.2xx= and FL25-B-A= and FL25-W=	SW25AW-11.2xx= and FL25-BS-A= and FL25-IBM-P= and FL25-P-W=	SW25AW-11.2xx= and FL25-W=	—
	Enterprise Plus 56	SW25AY-11.2xx= and FL25-C-A= and FL25-Y=	SW25AY-11.2xx= and FL25-CS-A= and FL25-IBM-P= and FL25-P-Y=	SW25AY-11.2xx= and FL25-DS-A= and FL25-IBM-P= and FL25-P-Y=	SW25AY-11.2xx= and FL25-DS-A= and FL25-IBM-P= and FL25-P-Y=	SW25AY-11.2xx= and FL25-B-A= and FL25-Y=	SW25AY-11.2xx= and FL25-BS-A= and FL25-IBM-P= and FL25-P-Y=	SW25AY-11.2xx= and FL25-Y=	—
	Enterprise/APPN Plus	SW25ANP-11.2xx= and FL25-C-A= and FL25-APPN= and FL25-P=	SW25ANP-11.2xx= and FL25-CS-A= and FL25-APPN= and FL25-IBM-P=	SW25AN-11.2xx= and FL25-DS-A= and FL-APPN= and FL25-IBM-P=	SW25ANP-11.2xx= and FL25-DS-A= and FL25-APPN= and FL25-IBM-P=	SW25ANP-11.2xx= and FL25-B-A= and FL25-APPN= and FL25-P=	SW25ANP-11.2xx= and FR25-BS-A= and FL25-APPN= and FL25-IBM-P=	SW25ANP-11.2xx= and FL25-APPN= and FL25-P=	SW25ANP-11.2xx= and FL25-P=
	Enterprise /APPN/Plus 40	SW25ANW-11.2xx= and FL25-C-A= and FL25-APPN= and FL25-W=	SW25ANW-11.2xx= and FL25-CS-A= and FL25-APPN= and FL25-IBM-P= and FL25-P-W=	SW25ANW-11.2xx= and FL25-DS-A= and FL-APPN= and FL25-IBM-P= and FL25-P-W=	SW25ANW-11.2xx= and FL25-DS-A= and FL25-APPN= and FL25-IBM-P= and FL25-P-W=	SW25ANW-11.2xx= and FL25-B-A= and FL25-APPN= and FL25-W=	SW25ANW-11.2xx= and FR25-BS-A= and FL25-APPN= and FL25-IBM-P= and FL25-P-W=	SW25ANW-11.2xx= and FL25-APPN= and FL25-W=	SW25ANW-11.2xx= and FL25-W=



From 11.1(Continued)									
	IP	IP/IBM	IP/IPX/IBM	IP/IPX/IBM/ APPN	Desktop	Desktop/ IBM	Enterprise	Enterprise/ APPN	
Enterprise/APPN/Plus 56	SW25ANY- 11.2xx= and FL25-C-A= and FL25-APPN= and FL25-Y=	SW25ANY- 11.2xx= and FL25-C-A= and FL25-APPN= and FL25-IBM-P= and FL25-P-Y=	SW25ANY- 11.2xx= and FR25-DS-A= and FL-APPN= and FL25-IBM-P= and FL25-P-W=	SW25ANY- 11.2xx= and FR25-BS-A= and FL25-APPN= and FL25-IBM-P= and FL25-P-Y=	SW25ANY- 11.2xx= and FL25-BS-A= and FL25-APPN= and FL25-Y=	SW25ANY- 11.2xx= and FR25-BS-A= and FL25-APPN= and FL25-IBM-P= and FL25-P-Y=	SW25ANY- 11.2xx= and FL25-APPN= and FL25-Y=	SW25ANY- 11.2xx= and FL25-Y=	

- “Plus” feature sets include: NAT, RMON, IBM, MP, AND VPDN/L2F7.
- Where “xx,” specify desired maintenance release.

**Corporate Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
<http://www.cisco.com>  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

**European Headquarters**

Cisco Systems Europe s.a.r.l.  
Parc Evolic, Batiment L1/L2  
16 Avenue du Quebec  
Villebon, BP 706  
91961 Courtaboeuf Cedex  
France  
<http://www-europe.cisco.com>  
Tel: 33 1 6918 61 00  
Fax: 33 1 6928 83 26

**Americas**

**Headquarters**  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
<http://www.cisco.com>  
Tel: 408 526-7660  
Fax: 408 527-0883

**Asia Headquarters**

Nihon Cisco Systems K.K.  
Fuji Building, 9th Floor  
3-2-3 Marunouchi  
Chiyoda-ku, Tokyo 100  
Japan  
<http://www.cisco.com>  
Tel: 81 3 5219 6250  
Fax: 81 3 5219 6001

**Cisco Systems has more than 200 offices in the following countries. Addresses, phone numbers, and fax numbers are listed on the Cisco Connection Online Web site at <http://www.cisco.com>.**

Argentina • Australia • Austria • Belgium • Brazil • Canada • Chile • China (PRC) • Colombia • Costa Rica • Czech Republic • Denmark • England • France • Germany • Greece • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Russia • Saudi Arabia • Scotland • Singapore • South Africa • Spain • Sweden • Switzerland • Taiwan, ROC • Thailand • Turkey • United Arab Emirates • United States • Venezuela

Copyright © 1997 Cisco Systems, Inc. All rights reserved. Printed in USA. AccessPath, AtmDirector, Cache Director System, CD-PAC, Cisco IOS, the Cisco IOS logo, CiscoLink, the Cisco Powered Network logo, ClickStart, ControlStream, Fast Step, FragmentFree, IGX, JumpStart, LAN<sup>2</sup>LAN Enterprise, LAN<sup>2</sup>LAN Remote Office, MICA, NetBeyond, NetFlow, Netsys Technologies, Packet, PIX, Point and Click Internetworking, RouteStream, SMARTnet, StrataSphere, StrataSphere BILLder, StrataSphere Connection Manager, StrataSphere Modeler, StrataSphere Optimizer, Stratum, StreamView, SwitchProbe, The Cell, TokenSwitch, TrafficDirector, VirtualStream, VlanDirector, Workgroup Director, Workgroup Stack, and XCI are trademarks; The Network Works. No Excuses. is a service mark; and BPX, Catalyst, Cisco, Cisco Systems, the Cisco Systems logo, EtherChannel, FastHub, FastPacket, ForeSight, IPX, LightStream, OptiClass, Phase/IP, StrataCom, and StrataView Plus are registered trademarks of Cisco Systems, Inc. in the U.S. and certain other countries. All other trademarks mentioned in this document are the property of their respective owners. 978R