

Cisco IOS


Early Deployment Release 12.0(5)WC4

This product bulletin describes the content and delivery information concerning Cisco IOS® Software Release 12.0(5)WC4. This release is specific for the Long-Reach Ethernet (LRE) solution and should be used by the Cisco Catalyst® 2900 LRE XL Series switches and not the Cisco Catalyst 2900 and 3500 Series XL. This release provides support for the product release of the Cisco 585 LRE customer premises equipment (CPE). For more information about the Cisco IOS Software release process, see Product Bulletin #537.

Migration Guide

Figure 1 displays Cisco IOS 12.0(5)WC4 release functionality relative to the 12.0 and 12.0T releases. This diagram identifies the recommended migration path for the Cisco Catalyst 2900 Series LRE XL switches only. LRE customers should upgrade from 12.0(5)WC2 directly to 12.0(5)WC4.

Figure 1 LRE Migration Path



New Features in Cisco IOS Release 12.0(5)WC4

This is an Early Deployment release for the following platform: Cisco Catalyst 2900 LRE XL. Please note that this release is *not* intended for Cisco Catalyst 2900 XL and 3500 XL. The following features will be delivered in the initial release of 12.0(5)WC4 and incorporate all new features added from 12.0(5)WC2.

New features include the following:

- Support for the new Cisco 585 LRE CPE
- Enhanced Web-based switch management (Cisco Cluster Management Suite [CMS])
- Media Access Control (MAC) address notification
- Internet Group Management Protocol (IGMP) filtering

Detailed Information

For more information about the platforms and features being delivered in 12.0(5)WC4, reference the following release notes documents:

<http://www.cisco.com/univercd/cc/td/doc/product/lan/c2900xl/index.htm>

Support

Cisco IOS Software Release 12.0(5)WC4 follows the standard Cisco support policy as indicated in the following link:

<http://www.cisco.com/warp/public/437/27.html>

Product NumbersbDownload Information

Platform	Software Feature Set	Product Code	Image	Flash	DRAM
c2900 LRE XL	12.0(5)WC4	-	c2900xl-c3h2l9s-mz	8 MB	16 MB

Customers can download Cisco IOS Release 12.0(5)WC4 Software from Cisco.com in the Software Image Library:

<http://www.cisco.com/public/sw-center/sw-ios.shtml>



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the

Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992-2002, Cisco Systems, Inc. All rights reserved. Catalyst, Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo, are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0206R)