



# Cisco 10000 Series GBIC and SFP Product Code Transition

Cisco Systems is migrating the Cisco 10000 Series Gigabit Interface Converter (GBIC) and Small Form Factor Pluggable Optics (SFP) product codes to standard Cisco product codes. There is no change in functionality, compatibility, or compliance because the physical hardware will remain the same. Only the product code will change.

## Product Code Transition Matrix

Table 1 details the new product codes that will be available for purchase on the Cisco 10000 Series.

Table 1

GBIC and SFP Product Code Transition Matrix

Former Product Code	New Product Code	Product Description
ESR-SFP-SX	GLC-SX-MM	Gigabit Ethernet SFP, LC connector SX transceiver
ESR-SFP-SX=	GLC-SX-MM=	Gigabit Ethernet SFP, LC connector SX transceiver
ESR-SFP-LX	GLC-LH-SM	Gigabit Ethernet SFP, LC connector LX/LH transceiver
ESR-SFP-LX=	GLC-LH-SM=	Gigabit Ethernet SFP, LC connector LX/LH transceiver
ESR-GBIC-SX	WS-G5484	1000BASE-SX short wavelength GBIC (Multimode only)
ESR-GBIC-SX=	WS-G5484=	1000BASE-SX short wavelength GBIC (Multimode only)
ESR-GBIC-LHLX	WS-G5486	1000BASE-LX/LH long-haul GBIC (single mode or multimode)
ESR-GBIC-LHLX=	WS-G5486=	1000BASE-LX/LH long-haul GBIC (single mode or multimode)
ESR-GBIC-ZX	WS-G5487	1000BASE-ZX extended-reach GBIC (single mode)
ESR-GBIC-ZX=	WS-G5487=	1000BASE-ZX extended-reach GBIC (single mode)

Beginning April 28, 2003, the former product codes (illustrated in the first column of Table 1) will no longer be available.

## Additional Information

For more information, please contact [ask-c10k-pm@cisco.com](mailto:ask-c10k-pm@cisco.com) or [ask-gbic-pm@cisco.com](mailto:ask-gbic-pm@cisco.com).



Corporate Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

European Headquarters  
Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

Americas Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

Asia Pacific Headquarters  
Cisco Systems, Inc.  
Capital Tower  
168 Robinson Road  
#22-01 to #29-01  
Singapore 068912  
www.cisco.com  
Tel: +65 317 7777  
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the  
**Cisco Web site at [www.cisco.com/go/offices](http://www.cisco.com/go/offices)**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland  
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland  
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden  
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2003, Cisco Systems, Inc. All rights reserved. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo, are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0303R)