

Part **Number** Change for

OC48E/POS-SR-SC/FC(=)

OC48E/POS-1550-SC/FC(=)



The OC-48/STM-16 Packet-over-SONET/Synchronous Digital Hierarchy (POS/SDH) interface module for the Cisco 12000 Series Internet Router, shipping for over a year, provides a unique combination of performance and class-of-service (CoS) features for delivering advanced end-to-end networking features.

The existing part numbers for the OC-48/STM-16 POS interface module are changing.

The following OC-48/STM-16 part numbers:

- OC48E/POS-SR-SC(=)
- OC48E/POS-SR-FC(=)
- OC48E/POS-1550-FC(=)
- OC48E/POS-1550-SC(=)

will be superseded on December 27, 2000, by the following OC-48/STM-16 part numbers:

- OC48E/POS-SR-SC-B(=)
- OC48E/POS-SR-FC-B(=)
- OC48E/POS-LR-FC-B(=)
- OC48E/POS-LR-SC-B(=)

The part number change is due to design optimizations on the current interface card. These optimizations have led to the need for a new version of Cisco IOS® Software (12.0(10)S or better and 11.2(19)GS5 or better).

The new B parts will not change any functionality or performance in the OC-48/STM-16 interface module. Both the existing version of OC-48/STM-16 and the new “B” version of OC-48/STM-16 interfaces are the same in form fit and function when running with Cisco IOS image 12.0(10)S or higher or IOS image 11.2(19)GS5 or higher.

Cisco strongly recommends that all existing OC-48 orders that have not been shipped be converted to reflect the new B part number.

A summary of the Cisco IOS version requirements on the POS interface card follows:

	Cisco IOS 12.XX	Cisco IOS 11.XX
OC-48E/POS—non-B Version	12.0(6)S or greater	11.2(18)GS2 or greater
OC-48E/POS—B Version	12.0(10)S or greater	11.2(19)GS5 or greater

NOTE: Both the original OC48 (non-B) and the new OC48 (B version) have ECC.

The new OC-48 (B) versions will have the same prices as the existing OC-48 (non-B) versions.

Part Number	Price
OC48E/POS-SR-SC-B(=)	\$65,000
OC48E/POS-SR-FC-B(=)	\$65,000
OC48E/POS-LR-FC-B(=)	\$95,000
OC48E/POS-LR-SC-B(=)	\$95,000

Orderability

The non-B parts will be orderable for up to three weeks beginning on December 27, 2000. Thereafter, the non-B parts will be orderable only as spares. Full orderability will be shut down on April 2, 2001.

All last-time-buy orders by customers must be received on or before this date.

Upgrade

Customers wishing to upgrade from existing non-B versions of the OC-48/STM-16 interface modules to new B versions of the OC-48/STM-16 interface modules should follow the technology migration plan guidelines located at:

http://www.cisco.com/offer/tic/TMP_PA.html

Calculations for credits/trade-in values can be found by using the TMP Calculator found under:

<http://www.cisco.com/go/tradein>

Further Information

For more information on the Cisco 12000 Series platform, please visit:

<http://www.cisco.com/warp/customer/cc/pd/rt/12000/index.shtml>

If you have any further questions, please contact your local sales team.



Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems Europe
11, Rue Camille Desmoulins
92782 Issy Les Moulineaux Cedex 9
France
www.cisco.com
Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems Australia, Pty., Ltd
Level 17, 99 Walker Street
North Sydney
NSW 2059 Australia
www.cisco.com
Tel: +61 2 8448 7100
Fax: +61 2 9957 4350

Cisco Systems has more than 200 offices in the following countries. Addresses, phone numbers, and fax numbers are listed on the

Cisco.com Web site at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2000, Cisco Systems, Inc. All rights reserved. Printed in the USA. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. or its affiliates in the U.S. and certain other countries. All other brands, names, or trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0010R)