

Cisco 12000 Route Processor Card Part Number Update

Cisco Systems announces a part number update for the Cisco 12000 route processor card.

This change was made to bring attention to the new enhanced ECC functionality. There are no mechanical, Cisco IOS® software, or memory differences. The board is compatible with the previous version and it does not require a software upgrade.

Table 1 Part Number and Description

Old Part Number	New Part Number	Description
GRP=	GRP-B=	Route processor, 128 MB, 20-MB Flash, ECC support, spare
GRP/R	GRP-B/R	Route processor, 128 MB, 20-MB Flash, ECC support, redundant

See Table 2 for important milestones.

Table 2 Important Dates

Milestone	Date
Part Number Update Announcement	June 1, 2000
New Part Number Orderability	June 20, 2000

End-of-Sales for Cisco 12000 Route Processor Card

The “GRP=” part number will no longer be orderable after June 20, 2000. All last-time-buy orders by customers must be received on or before this date.

For more information on the replacement line card, see the product collateral at www.cisco.com/warp/public/cc/pd/rt/12000/prodlit/index.shtml.

For more information on increasing network availability with ECC, please go to www.cisco.com/warp/public/779/largeent/learn/technologies/ina/.

CISCO SYSTEMS



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems Europe
11, Rue Camille Desmoulins
92782 Issy Les Moulineaux
Cedex 9
France
www.cisco.com
Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems Australia, Pty., Ltd
Level 17, 99 Walker Street
North Sydney
NSW 2059 Australia
www.cisco.com
Tel: +61 2 8448 7100
Fax: +61 2 9957 4350

Cisco Systems has more than 190 offices in the following countries. Addresses, phone numbers, and fax numbers are listed on the
Cisco.com Web site at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Canada • Chile • China • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE
Finland • France • Germany • Greece • Hong Kong • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia
Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Singapore
Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela
Copyright © 2000, Cisco Systems, Inc. All rights reserved. Printed in the USA. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo, are registered trademarks of Cisco Systems, Inc. or its affiliates in the U.S. and certain other countries. All other trademarks mentioned in this document are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0007R)