

# Announcing End of Sale of the Cisco 7200 PWR-7200-DC Power Supply



With the introduction of the new Cisco 7200 power supply (PWR-7200-DC+), Cisco Systems announces end of sale (EoS) of the Cisco PWR-7200-DC power supply, effective January 31, 2002.

The Cisco PWR-7200-DC will remain orderable until January 31, 2002. This notice does not affect the AC power supply available for the Cisco 7200 Series.

## Benefits

The recently announced Cisco PWR-7200-DC+ provides a wider range of voltage support (24V-60V) than the PWR-7200-DC (48V-60V). This broader functionality allows the Cisco 7200 Series to support the requirements of wireless environments while still fulfilling the needs of existing applications.

## Upgrade Path

Table 1 illustrates the upgrade path for the PWR-7200-DC.

Table 1 Power Supply Substitution

EoS Product	Replacement Product	Replacement Product Description
PWR-7200-DC	PWR-7200-DC+	24-60V DC Power Supply
PWR-7200-DC=	PWR-7200-DC+=	24-60V DC Power Supply (spare)
PWR-7200/2-DC	PWR-7200/2-DC+	24-60V DC Power Supply, Dual Option

## Cisco IOS Software

Table 2 indicates the minimum required Cisco IOS® Software versions for the PWR-7200-DC+.

Table 2 Minimum Required Cisco IOS Software Versions for PWR-7200-DC+

Product ID	Minimum Cisco IOS Release(s)
PWR-7200-DC+	12.1(7)E, 12.2(3), 12.2(2)T, 12.2(2)DD1, 12.0(17)S
PWR-7200-DC+=	12.1(7)E, 12.2(3), 12.2(2)T, 12.2(2)DD1, 12.0(17)S
PWR-7200/2-DC+	12.1(7)E, 12.2(3), 12.2(2)T, 12.2(2)DD1, 12.0(17)S

## Support Programs

End of sale refers to the time when certain products are no longer available for new purchases. It does not apply to the service and support programs for those products. Cisco will continue to support the PWR-7200-DC product group through the SMARTnet™ and comprehensive maintenance programs. Customers with either of these service contracts are entitled to free software updates, 24-hour phone support through the Technical Assistance Center (TAC), and advanced replacement of hardware for repairs. Comprehensive maintenance customers also receive onsite service. Customers who do not have a maintenance contract can purchase software updates and hardware repair services from Cisco to meet specific requirements rather than full-service coverage. Cisco is committed to providing software support for a minimum of two years and providing hardware support for a period of five years after the end-of-sale date.

Table 3 End of Sale Schedule

Products Affected	End of Sale	End of Support
PWR-7200-DC	January 31, 2002	January 31, 2007
PWR-7200-DC=	January 31, 2002	January 31, 2007
PWR-7200/2-DC	January 31, 2002	January 31, 2007

## Further Assistance

If you have questions, contact the Cisco TAC at 800 553-2447 or 408 526-7209, or send e-mail to [TAC@cisco.com](mailto:TAC@cisco.com).

For further information about Cisco 7200 Series routers, visit <http://www.cisco.com/warp/public/cc/pd/rt/7200/>.

For further assistance, please contact:

Kimberley Smith

Product Manager

E-mail: [kimbemi@cisco.com](mailto:kimbemi@cisco.com)

Telephone: 408 853-3159



Corporate Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
[www.cisco.com](http://www.cisco.com)  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

European Headquarters  
Cisco Systems Europe  
11, Rue Camille Desmoulins  
92782 Issy-les-Moulineaux  
Cedex 9  
France  
[www-europe.cisco.com](http://www-europe.cisco.com)  
Tel: 33 1 58 04 60 00  
Fax: 33 1 58 04 61 00

Americas Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
[www.cisco.com](http://www.cisco.com)  
Tel: 408 526-7660  
Fax: 408 527-0883

Asia Pacific Headquarters  
Cisco Systems Australia, Pty., Ltd  
Level 9, 80 Pacific Highway  
P.O. Box 469  
North Sydney  
NSW 2060 Australia  
[www.cisco.com](http://www.cisco.com)  
Tel: +61 2 8448 7100  
Fax: +61 2 9957 4350

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the

**Cisco Web site at [www.cisco.com/go/offices](http://www.cisco.com/go/offices)**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia  
Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru  
Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa  
Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2001, Cisco Systems, Inc. All rights reserved. Printed in the USA. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0106R)

09/01 LW2626