



Flash Memory Increases in Cisco 805 Serial Router

Effective May 30th, 2003, the Cisco® 805 Serial Router's default Flash memory increases to 8 MB from 4 MB. The Cisco 805 list price will remain the same.

The Cisco 805 Serial Access Router provides secure, managed access through serial WAN link with firewall protection and encryption for VPNs with Cisco IOS® Software. Effective immediately, the default Flash memory configuration is upgraded from 4 MB to 8 MB, while the default DRAM memory remains unchanged at 8 MB.

Additional Flash memory is being provided to ensure the Cisco 805 Serial Router will be able to support future versions of Cisco IOS Software. The memory enhancement to the Cisco 805 router will allow customers, resellers, and service providers to benefit from the greater capabilities that Cisco IOS Software offers today and in the future. Investment protection is also increased because the risk of truck rolls to upgrade the memory is negated.

Cisco 805 Flash Memory Information

- Flash memory—Ships with 8 MB (NEW)
- Max Flash memory—12 MB

Ordering Information

Product Number: CISCO805

View the Cisco Pricing Tool for pricing information:

<http://www.cisco.com/commarch/html/pricing-tool/>

Contact Information

Qing Hu—(qinghu@cisco.com) Product Manager for Cisco 800 and SOHO Series Ethernet Broadband Routers
+1 408 902 8395

Geir Leirvik—(gleirvik@cisco.com) EMEA Product Manager for Cisco 800 and SOHO Routers and New Technology
+47 (0) 23 27 36 41



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the
Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2003 Cisco Systems, Inc. All rights reserved. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company.
(0304R) MS/LW4743 06/03