



## Flash Memory Increases in Cisco 831, 836, and 837 Secure Broadband Routers

Effective May 30th, 2003, the Cisco® 830 Series of Secure Broadband Routers' default Flash memory increases to 12 MB. The Cisco 830 Series list prices will remain the same.

The Cisco 830 Series of routers provide advanced security for data, voice, and video access, ideal for small offices and teleworkers. Cisco 830 Series routers utilize a wide range of integrated security services and advanced quality of service (QoS) features as well as easy deployment and remote management features with Cisco IOS® Software.

Effective immediately, the default Flash memory configuration is upgraded from 8 MB to 12 MB.

Additional Flash Memory is being provided to ensure the Cisco 830 Series Access Routers will be able to support new versions of Cisco IOS Software that deliver new and more powerful IP services. The memory addition to the Cisco 830 series will allow customers, resellers, and service providers to benefit from the greater capabilities that Cisco IOS Software offers today and in the future. Investment protection is also increased because the risk of truck rolls to upgrade the memory is reduced.

### Cisco 830 Series Memory Information

- Flash: 12 MB (new)
- Maximum Flash: 24 MB
- DRAM—Ships with 32 MB DRAM
- Maximum DRAM: 48 MB

### Ordering Information

#### Product Numbers:

CISCO831-K9

CISCO836-K9

CISCO837-K9

View the Cisco Pricing Tool for pricing information:

<http://www.cisco.com/commarch/html/pricing-tool/>

### Contact Information

Hari Harikrishnan—(harikris@cisco.com)  
Product Manager for Cisco 800 and SOHO Series DSL Routers +1 408 525 3954

Qing Hu—(qinghu@cisco.com) Product  
Manager for Cisco 800 and SOHO Series  
Ethernet Routers

Geir Leirvik—(gleirvik@cisco.com) EMEA  
Product Manager for Cisco 800 and SOHO  
Routers and New Technology  
+47 (0) 23 27 36 41



Corporate Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

European Headquarters  
Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

Americas Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

Asia Pacific Headquarters  
Cisco Systems, Inc.  
Capital Tower  
168 Robinson Road  
#22-01 to #29-01  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the  
**Cisco Web site at [www.cisco.com/go/offices](http://www.cisco.com/go/offices)**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland  
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland  
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden  
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2003 Cisco Systems, Inc. All rights reserved. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company.  
(0304R) MS/LW4743 06/03