

Cisco 4xDMT End of Life Announcement



Overview

Cisco is announcing the End of Life (EOL) for the ATUC-1-4DMT and ATUC-1-4DMT-2 ADI-based four-port discrete multitone (DMT) line card. Customers are encouraged to purchase the ATUC-4-FLX-2, ATUC-8-DMT-1, or ATUC-8-DMT-1-H for continuing DSL rollouts, and participate in the Technology Migration Program. Customers with existing Cisco 677 customer premises equipment (CPE) can interoperate with Cisco 12.1(6) IOS[®] releases and above. Thus the ATUC-4-FLX-2 or ATUC-8-DMT-1-H will interoperate with both the Cisco 677 and the Cisco 678.

After the EOL of the Cisco 677 and 678, customers are encouraged to migrate to the Cisco SOHO77, Cisco 827, or a third-party CPE that has been tested for interoperability with Cisco 6000 IP digital-subscriber-line (DSL) switches.

Product IDs and dates (Last-Time Buy, End of Hardware Support, and End of Software Support) are listed below.

End-of-Life Products

Definitions: LTB = Last-Time Buy, EOSS = End of Software Support (no more software bug fixes), EOHS = End of Hardware Support (no more hardware bug fixes)

| Product Name | Description | LTB Date | EOSS Date | EOHS Date |
|-----------------------|------------------------------|----------|-----------|-----------|
| DSL Line Cards | | | | |
| ATUC-1-4DMT | 4-port DMT issue 2 line card | 4/2/01 | 4/2/04 | 4/2/06 |
| ATUC-1-4DMT= | 4-port DMT issue 2 line card | 4/2/01 | 4/2/04 | 4/2/06 |
| ATUC-1-4DMT-2 | 4port DMT issue 2 line card | 4/2/01 | 4/2/04 | 4/2/06 |
| ATUC-1-4DMT-2= | 4-port DMT issue 2 line card | 4/2/01 | 4/2/04 | 4/2/06 |

Last day to order product: April 2, 2001

Last Software Support Date

Last date of support is April 2, 2004. Any issues with software or hardware beyond these dates will not be addressed. The customer will be required to migrate to new DSL products available at that time.

Date for Discontinuing Renewal of Contracts

Existing service contracts will be honored. New contracts will not be honored beyond End of Support dates for the software or hardware.

Date Obsolete

The ATUC-1-4DMT and ATUC-1-4DMT-2 line cards are considered obsolete, and all activities required to support these products will cease on April 2, 2006.



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems Europe
11, Rue Camille Desmoulins
92782 Issy Les Moulineaux
Cedex 9
France
www.cisco.com
Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems Australia, Pty., Ltd
Level 17, 99 Walker Street
North Sydney
NSW 2059 Australia
www.cisco.com
Tel: +61 2 8448 7100
Fax: +61 2 9957 4350

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the
Cisco.com Web site at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE
Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia
Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam •

All contents are Copyright © 1992–2001 Cisco Systems, Inc. All rights reserved. Important Notices and Privacy Statement. Printed in the USA. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. or its affiliates in the U.S. and certain other countries.

All other brands, names, or trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0102R)