

End-of-Life Announcement for Catalyst 5000 Supervisor Engine I

Overview

The Cisco Systems Workgroup Business Unit is announcing the end of life (EOL) of the following Catalyst® 5000 supervisor engines:

Table 1 End-of-Life Products

Cisco Part Number	Description
WS-X5005	Catalyst 5000 Supervisor Engine I, Single-mode Fiber
WS-X5006	Catalyst 5000 Supervisor Engine I, Multimode Fiber
WS-X5009	Catalyst 5000 Supervisor Engine I, TX

End of sales: April 23, 1999
End of shipment: May 23, 1999
End of support: May 23, 2004

Pricing Information

The Technology Migration Program includes attractive upgrades to newer technology for all Supervisor Engine I modules. Supervisor Engine II/III products offer increased performance and a migration path to the 5500 series chassis. Please reference the Technology Migration Program or contact your account manager for the latest upgrade pricing.

Ordering Information

After April 23, 1999, orders for Supervisor Engine I should be replaced with Supervisor Engine II/III as detailed on page two.

Table 2 Replacement Options for Catalyst 5000 Supervisor Engine I

EOL Part Number	Replacement Part Number(s)	Description
WS-X5005	• WS-X5530-E3A, WS-U5536-GELX	Sup III, with Dual-Port 1000BaseLX/LH
	• WS-X5530-E3A, WS-U5535-FEFX-SMF	Sup III, with Dual-Port 100BaseFX, SMF
	• WS-X5505	Sup II, 100BaseFX, SMF
WS-X5006	• WS-X5530-E3A, WS-U5536-GELX	Sup III, with Dual-Port 1000BaseLX/LH
	• WS-X5530-E3A, WS-U5534-GESX	Sup III, with Dual-Port 1000BaseSX
	• WS-X5530-E3A, WS-X5538-FEFX-MMF	Sup III, with Four-Port 100BaseFX, MMF
	• WS-X5530-E3A, WS-U5533-FEFX-MMF	Sup III, with Dual-Port 100BaseFX, MMF
	• WS-X5506	Sup II, 100BaseFX, MMF
WS-X5009	• WS-X5530-E3A, WS-U5537-FETX	Sup III, with Four-Port 100BaseTX
	• WS-X5530-E3A, WS-U5531-FETX	Sup III, with Dual-Port 100BaseTX
	• WS-X5509	Sup II, 100BaseTX, MII

Software Support

Supervisor Engine I will be supported for Catalyst 5000 software releases through the release 4.5 scheduled for March/April CY99. It will not be supported in new software releases after this release.



Corporate Headquarters

Cisco Systems, Inc.
 170 West Tasman Drive
 San Jose, CA 95134-1706
 USA
<http://www.cisco.com>
 Tel: 408 526-4000
 800 553-NETS (6387)
 Fax: 408 526-4100

European Headquarters

Cisco Systems Europe s.a.r.l.
 Parc Evolic, Batiment L1/L2
 16 Avenue du Quebec
 Villebon, BP 706
 91961 Courtaboeuf Cedex
 France
<http://www-europe.cisco.com>
 Tel: 33 1 69 18 61 00
 Fax: 33 1 69 28 83 26

Americas Headquarters

Cisco Systems, Inc.
 170 West Tasman Drive
 San Jose, CA 95134-1706
 USA
<http://www.cisco.com>
 Tel: 408 526-7660
 Fax: 408 527-0883

Asia Headquarters

Nihon Cisco Systems K.K.
 Fuji Building, 9th Floor
 3-2-3 Marunouchi
 Chiyoda-ku, Tokyo 100
 Japan
<http://www.cisco.com>
 Tel: 81 3 5219 6250
 Fax: 81 3 5219 6001

Cisco Systems has more than 200 offices in the following countries. Addresses, phone numbers, and fax numbers are listed on the Cisco Connection Online Web site at <http://www.cisco.com/offices>.

Argentina • Australia • Austria • Belgium • Brazil • Canada • Chile • China • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE Finland • France • Germany • Greece • Hong Kong • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Singapore Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela