

# Cisco Announces End-of-Sales for Specific Modules of the Cisco Catalyst 8500 Series Products

Cisco Systems announces End of Sales (EOS) for specific modules of its Cisco Catalyst® 8500 Series of Layer 3-enabled ATM switch-router products. Customers are encouraged to migrate from their current 16K Fast Ethernet line cards to the 64K line cards with built-in access control list (ACL) daughter cards. Customers can infuse higher performance into their Cisco Catalyst 8500 Series products with additional security.

Cisco is committed to growing and supporting its Cisco Catalyst 8500 Series products. This EOS program helps focus on the more popular modules with additional performance, scalability, and built-in security.

**Table 1** End-of-Sales (EOS) of Specific Cisco Catalyst 8500 Modules

Milestone	Effective Date
End-of-Sales	November 15, 2002
End-of-Support and Product Obsolescence	November 16, 2007

**Table 2** EOS of Fast Ethernet (FE) Modules

Part Number	Description
C85FE-16F-16K (=)	Cisco Catalyst 8540 16-Port 100-FX MT-RJ 16K
C85FE-16FACL-16K (=)	Cisco Catalyst 8540 16-Port 100-FX MT-RJ with ACL 16K
C85FE-16F-64K (=)	Cisco Catalyst 8540 16-Port 100-FX MT-RJ 64K
C85FE-16T-16K (=)	Cisco Catalyst 8540 16-Port 10/100 RJ-45 16K
C85FE-16T-64K (=)	Cisco Catalyst 8540 16-Port 10/100 RJ-45 64K
C85FE-16TACL-16K (=)	Cisco Catalyst 8540 16-Port 10/100 RJ45 with ACL 16K
C85FE-8F-16K (=)	Cisco Catalyst 8510 8-Port 100-FX MT-RJ 16K
C85FE-8T-16K (=)	Cisco Catalyst 8510 8-Port 10/100 RJ45 16K



**Table 3** Replacement Modules for Fast Ethernet (FE) Modules

Part Number	Replacement
C85FE-16F-16K (=)	C85FE-16FACL-64K (=)
C85FE-16FACL-16K (=)	C85FE-16FACL-64K (=)
C85FE-16F-64K (=)	C85FE-16FACL-64K (=)
C85FE-16T-16K (=)	C85FE-16TACL-64K (=)
C85FE-16T-64K (=)	C85FE-16TACL-64K (=)
C85FE-16TACL-16K (=)	C85FE-16TACL-64K (=)
C85FE-8F-16K (=)	C85FE-8F-64K (=)
C85FE-8T-16K (=)	C85FE-8T-64K (=)

**Table 4** EOS of ATM Uplink Modules

Part Number	Description
C85-10C3MGE-64K (=)	1-Port ATM OC-3 MMF Uplink + 1-Port GE 64K
C85-10C3SGE-64K (=)	1-Port ATM OC3 SMF-IR Uplink + 1-Port GE 64K
C85-10C12MGE-256K (=)	1-Port ATM OC12 MMF Uplink + 1-Port GE 256K
C85-10C12MGE-64K (=)	1-Port ATM OC12 MMF Uplink + 1-Port GE 64K
C85-10C12SGE-256K (=)	1-Port ATM OC12 SMF-IR Uplink + 1-Port GE 256K
C85-10C12SGE-64K (=)	1-Port ATM OC12 SMF-IR Uplink + 1-Port GE 64K

**Table 5** EOS of POS Uplink Modules

Part Number	Description
C85-POSOC12I-64K (=)	1-Port POS OC12 SMF-IR Uplink + 1-Port GE 64K
C85-POSOC12I-256K (=)	1-Port POS OC12 SMF-IR Uplink + 1-Port GE 256K
C85-POSOC12L-64K (=)	1-Port POS OC12 SMF-LR Uplink + 1-Port GE 64K
C85-POSOC12L-256K (=)	1-Port POS OC12 SMF-LR Uplink + 1-Port GE 256K

**Table 6** EOS of Long Reach OC-48 Modules and Other EOS Cisco Catalyst 8500 Products

Part Number	Description
C85MS-1DS3-FRBNC (=)	Cisco Catalyst 8500 1-Port Channelized DS3 Frame-Relay PAM
C85MS-1F4S-OC48LR (=)	Cisco Catalyst 8540 1-Port OC-48c/STM-16 SMF-LR + 4-Port OC12 SMF
C85MS-2F-OC48LR (=)	Cisco Catalyst 8540 2-Port OC-48c/STM-16 SMF-LR
WAI-OC3-4U5 (=)	4-Port STS-3c/STM-1 UTP-5 PAM
MEM-ASP-FLC8M =	Cisco Catalyst 8500/LS1010 PCMCIA Flash Memory Card 8 MB (spare)



Corporate Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

European Headquarters  
Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

Americas Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

Asia Pacific Headquarters  
Cisco Systems, Inc.  
Capital Tower  
168 Robinson Road  
#22-01 to #29-01  
Singapore 068912  
www.cisco.com  
Tel: +65 317 7777  
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the

**Cisco Web site at [www.cisco.com/go/offices](http://www.cisco.com/go/offices)**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland  
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland  
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden  
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992-2002, Cisco Systems, Inc. All rights reserved. CCIP, the Cisco Arrow logo, the Cisco Powered Network mark, the Cisco Systems Verified logo, Cisco Unity, Follow Me Browsing, FormShare, iQ Breakthrough, iQ Expertise, iQ FastTrack, the iQ logo, iQ Net Readiness Scorecard, Networking Academy, ScriptShare, SMARTnet, TransPath, and Voice LAN are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, Discover All That's Possible, The Fastest Way to Increase Your Internet Quotient, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, Internet Quotient, IOS, IP/TV, LightStream, MGX, MICA, the Networkers logo, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, SlideCast, StrataView Plus, Stratum, SwitchProbe, TeleRouter, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company.  
(0208R) LW3614 0902