



Cisco Catalyst Operating System Software Version 7.4(1) for the Cisco Catalyst 4000 Family Switches

The Cisco Catalyst[®] Operating System (CatOS) software version 7.4(1) for the Cisco Catalyst 4000 Family Supervisor Engine supports Cisco Catalyst 4000 Family switches including the Cisco Catalyst 2948G, 4912G, and 2980G-A switches.

Hardware Supported

The Cisco CatOS software version 7.4(1) supports all chassis and cards previously supported under the Cisco CatOS for the Cisco Catalyst 4000 Family Supervisor Engine. In addition, CatOS version 7.4(1) supports the hardware for the Cisco Catalyst Supervisor II Engine listed below.

Table 1 Cisco Catalyst Supervisor II Engine Hardware Supported by CatOS Version 7.4(1)

Chassis	Description
WS-C4503	Cisco Catalyst 4500 Series 3-slot chassis
WS-C4506	Cisco Catalyst 4500 Series 6-slot chassis
Power Supplies	
PWR-C45-1000AC	Cisco Catalyst 4500 1000 watt AC power supply (data only)
PWR-C45-2800ACV	Cisco Catalyst 4500 2800 watt AC power supply (with integrated voice)

Orderable Software Images

Table 2 lists the software versions and applicable ordering information for the Cisco Catalyst 4000 Family Supervisor Engine software.

Caution: Always back up the switch configuration file before you upgrade or downgrade the switch software to avoid losing the configuration stored in nonvolatile RAM (NVRAM). When you downgrade switch software, you lose your configuration. Use the write network command or the copy config tftp command to back up your configuration to a Trivial File Transfer Protocol (TFTP) server. Use the copy config flash command to back up the configuration to a Flash memory device.

Table 2 Software Ordering Information

Product Number	Description	Image
SC4K-SUPK8-7.4.1 SC4K-SUPK8-7.4.1=	Cisco Catalyst 4000 Supervisor Flash image, version 7.4.1 Spare	cat4000-k8
SC4K-SCVK8-7.4.2 SC4K-SCVK8-7.4.2=	Cisco Catalyst 4000 CiscoView image, version 7.4.2 Spare	cat4000-cv
SC4K-SUPK9-7.4.1 SC4K-SUPK9-7.4.1=	Cisco Catalyst 4000 Supervisor Flash image with SSH, version 7.4.1 Spare	cat4000-k9

For more detailed information, refer to the Cisco Catalyst 4000 Family release notes at:

<http://www.cisco.com/univercd/cc/td/doc/product/lan/cat4000/relnotes/index.htm>.

Also, review the Cisco Catalyst 4000 Family documentation at:

<http://www.cisco.com/univercd/cc/td/doc/product/lan/cat4000/index.htm>.



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: +65 317 7777
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the

Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2002, Cisco Systems, Inc. All rights reserved. Catalyst, Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company.
(0208R) LW3376 0902