

End of Life of IGX-NPM64, IGX-FRM, IGX-FRM-2, IGX-FRM-31, and BC-550100-J1.

Overview

Cisco Systems, Inc. announces the end of life (EoL) of IGX-NPM64, IGX-FRM, IGX-FRM-2, IGX-FRM-31, and BC-550100-J1 listed in Table 1. These cards have been replaced by new-generation cards, which have greater functionality (except for the IGX-FRM-2, which has no replacement).

Table 1 Comparison

EoL Cisco Product Number	Replacement card
IGX-NPM-64 <ul style="list-style-type: none"> • 4 Meg Flash • Does not work with VSI/MPLS 	IGX-NPM-64B <ul style="list-style-type: none"> • 8 Meg Flash • Does work with VSI/MPLS
IGX-FRM <ul style="list-style-type: none"> • 4 Port • 2 Meg Max throughput • No FR to ATM SIW support 	IGX-UFM-U <ul style="list-style-type: none"> • 16 Port • 16 Meg Max throughput • FR to ATM SIW support
IGX-FRM-2	No Replacement Card Available, since FRM went with the Port Concentrator Shelf (PCS) which has been EoL/EoS.
IGX-FRM-31 <ul style="list-style-type: none"> • 1 (T1/E1) • 2 Meg Max throughput • No FR to ATM SIW support 	IGX-UFM-C <ul style="list-style-type: none"> • 8 (T1/E1) • 16 Meg Max throughput • FR to ATM SIW support
BC-550100-J1 (used with CVM)	BC-UVI-2J1EC (used with UVM)

Product

Cisco Systems, Inc. announces the end of life (EoL) of IGX-NPM64, IGX-FRM, IGX-FRM-2, IGX-FRM-31, and BC-550100-J1 listed in Table 2.

Table 2 EoL Cards

EoL Cisco Product Number	Description
IGX-NPM-64	Network Processor Module, 64 MB
IGX-FRM	Frame Relay Module (and associated BCs)
IGX-FRM-2	Frame Relay Module, for use with PCS (and associated BCs)
IGX-FRM-31	Frame Relay Module, 31 Channels (and associated BCs)
BC-550100-J1 (BC-J1)	Back Card J1 (BC-J1)

These cards will be replaced (with the exception of IGX-FRM-2) with the next generation cards listed in Table 3.

Table 3 Replacement Cards

EOL Cards	New Replacement Cards
IGX-NPM-64	IGX-NPM-64B
IGX-FRM	IGX-UFM-U
IGX-FRM-31	IGX-UFM-C
BC-550100-J1 (BC-J1)	BC-UVI-2J1EC

Ordering Information

May 30, 2001 will be the last date to enter orders for IGX-FRM, IGX-FRM-2, IGX-FRM-31, and BC-550100-J1 (BC-J1). December 8, 2000 will be the last date to enter orders for IGX-NPM-64. Hardware support, for these products, will be provided until November 2005. Switch software Release 9.3 will be the last release supporting the IGX-NPM64, IGX-FRM, IGX-FRM-2, IGX-FRM-31, and BC-550100-J1. Customers will continue to receive Technical Assistance Center (TAC) and RMA support, for these modules, for a period of five years, after their respective EoS announcements.



Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems Europe
11, Rue Camille Desmoulins
92782 Issy-les-Moulineaux
Cedex 9
France
www.cisco.com
Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems Australia, Pty., Ltd
Level 17, 99 Walker Street
North Sydney
NSW 2059 Australia
www.cisco.com
Tel: +61 2 8448 7100
Fax: +61 2 9957 4350

Cisco Systems has more than 190 offices in the following countries. Addresses, phone numbers, and fax numbers are listed on the

Cisco.com Web site at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE
Finland • France • Germany • Greece • Hong Kong • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The
Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia
Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2000, Cisco Systems, Inc. All rights reserved. Printed in the USA. IGX is a trademark of Cisco Systems, Inc.; and Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. or its affiliates in the U.S. and certain other countries. All other brands, names, or trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0008R)