



End-of-Life Announcement for Cisco BPX 8600 and IGX 8400 Switch Software Version 9.1

Cisco Systems is officially announcing the end of sales and end of life (EOS/EOL) for the Cisco BPX® 8600 and IGX 8400 Switch Software Version 9.1 with an effective announcement date of June 28, 2002. Cisco customers may continue to receive software support for a longer period as set forth in the milestones and timelines in Table 1.

Cisco BPX 8600 and IGX 8400 Switch Software releases 9.2.x and later will replace the software release version affected by this announcement.

It is recommended to consult with your support group before upgrading software and compatible firmware. In an effort to provide full and proper engineering support for two main baselines and encourage customers to upgrade to the latest developed releases, Cisco is ending the life of the Cisco BPX 8600 and IGX 8400 Switch Software Version 9.1. It shall be implied that any 9.1.x release not listed in Table 2 below is also covered by this End-of-sales announcement.

In summary, the milestones, their definitions, and effective EOL dates for the Cisco BPX 8600 and IGX 8400 Switch Software are listed in Table..

Table 1 Milestones and Effective End-of-Life Dates for Cisco BPX 8600 and IGX 8400 Switch Software

Milestone	Definition	Effective Date
End-of-sales announcement	The date that the end of sales announcement will be released to the public.	June 28, 2002
End of sales	The last date to enter orders of the product in the Cisco Marketplace "Orderability" Tool.	December 27, 2002
End of production	The date that Cisco Manufacturing completed/will complete fulfillment and shipment of new equipment purchase orders.	January 27, 2003
End of hardware maintenance (engineering)	The date that Cisco Engineering ceased or will cease considering the repair/maintenance of confirmed hardware defects related to components within this system configuration.	¹
End of software maintenance (engineering)	The date that Cisco Engineering ceased or will cease considering the repair/maintenance of confirmed operating system software defects or card download software defects within this system configuration.	June 28, 2005



Table 1 Milestones and Effective End-of-Life Dates for Cisco BPX 8600 and IGX 8400 Switch Software

Milestone	Definition	Effective Date
Discontinue contract renewal	The date that renewing/extending a service contract for this system will discontinue.	–
End of support/end of life/product obsolescence	The date that Cisco Logistics will no longer have any obligation to support the products listed in this product bulletin. This includes processing RMA orders for components with this system configuration; it is also the date that the Cisco Technical Assistance Center (TAC) will no longer have any obligation to assist customers with any issues related to this software. Any assistance rendered by Cisco will be on an as available basis without warranties at the sole discretion of Cisco Systems.	June28, 2007

1 Not Applicable

Cisco BPX 8600 and IGX 8400 Switch Software Part Numbers

Table 2 lists the Cisco BPX 8600 and IGX 8400 Switch Software part numbers that are affected by this EOS/EOL announcement.

Table 2 Cisco BPX 8600 and IGX 8400 Switch Software Part Numbers

Product Number	Product Description	EOS Last Order (Sales) Date	End of Production Last Shipment Date	End of Engineering Hardware Maintenance Date	End of Engineering Software Maintenance Date	Dis-continue Contract Renewal Date	End of Support/Product Obsolescence Date
BPX-SW-9110	BPX System Software License - Release (version 9.1.10)	12/27/2002	1/27/2003	– ¹	6/28/2005	–	6/28/2007
BPX-SW-9111	BPX System Software License - Release (version 9.1.11)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
BPX-SW-9115	BPX System Software License - Release (version 9.1.15)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
BPX-SW-9116	BPX System Software License - Release (version 9.1.16)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
BPX-SW-9117	BPX System Software License - Release (version 9.1.17)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
BPX-SW-9118	BPX System Software License - Release (version 9.1.18)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
BPX-SW-9119	BPX System Software License - Release (version 9.1.19)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
BPX-SW-9122	BPX System Software License - Release (version 9.1.22)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
BPX-SW-9124	BPX System Software License - Release (version 9.1.24)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
BPX-SW-9125	BPX System Software License - Release (version 9.1.25)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
BPX-SW-9130	BPX System Software License - Release (version 9.1.30)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007

Product Number	Product Description	EOS Last Order (Sales) Date	End of Production Last Shipment Date	End of Engineering Hardware Maintenance Date	End of Engineering Software Maintenance Date	Dis-continue Contract Renewal Date	End of Support/Product Obsolescence Date
IGX-SW-9110	IGX System Software License - Release (version 9.1.10)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
IGX-SW-9111	IGX System Software License - Release (version 9.1.11)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
IGX-SW-9115	IGX System Software License - Release (version 9.1.15)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
IGX-SW-9116	IGX System Software License - Release (version 9.1.16)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
IGX-SW-9117	IGX System Software License - Release (version 9.1.17)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
IGX-SW-9118	IGX System Software License - Release (version 9.1.18)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
IGX-SW-9119	IGX System Software License - Release (version 9.1.19)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
IGX-SW-9122	IGX System Software License - Release (version 9.1.22)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
IGX-SW-9124	IGX System Software License - Release (version 9.1.24)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
IGX-SW-9125	IGX System Software License - Release (version 9.1.25)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
IGX-SW-9130	IGX System Software License - Release (version 9.1.30)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007

1 Not Applicable

Ordering Information

December 27, 2002 will be the last date to enter orders for Cisco BPX 8600 and IGX 8400 Switch Software versions 9.1. Support for software will be provided according to the effective dates stated in Table 1.

For More Information

Erick Pong

Product Manager

Phone: 408 525-1007

E-mail: epong@cisco.com

CISCO SYSTEMS



Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA

www.cisco.com

Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems Europe
11 Rue Camille Desmoulins
92782 Issy-les-Moulineaux
Cedex 9
France

www-europe.cisco.com

Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA

www.cisco.com

Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912

www.cisco.com
Tel: +65 317 7777
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2002, Cisco Systems, Inc. All rights reserved. BPX, Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo, are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0201R)

LW3092 03/02