

End of Life Announcement for IGX Modules

End of Life Announcement for

- IGX-UXME-2-155XLR and IGX-UXME-4-155XLR Bundles
- BC-UAI-2SMFXLR and BC-UAI-4SMFXLR Back Cards
- IGX-UXME-4-T1-DB, IGX-UXME-4-E1-BN and IGX-UXME-4-E1-DB Bundles
- BC-UAI-4-T1-DB15, BC-UAI-4-E1-BNC and BC-UAI-4-E1-DB15 Back Cards
- BC-UVI-2J1EC Back Card
- BC-550150-Y1 Back Card
- IGX-LDM Front Card and its Back Cards BC-5286A-RS232 and BC-5287A-RS232

End of Life Details

Due to low shipment volumes, Cisco Systems is announcing End of Sales (EoS) for following bundles and modules:

Table 1 Product Descriptions

Product	Product Description
IGX-UXME-2-155XLR	One IGX-UXME with one BC-UAI-2SMFXLR
BC-UAI-2SMFXLR	2 Port Single Mode Fiber (XLR) 155Mbps Back Card
IGX-UXME-4-155XLR	One IGX-UXME with one BC-UAI-4SMFXLR
BC-UAI-4SMFXLR	4 Port Single Mode Fiber (XLR) 155Mbps Back Card
IGX-UXME-4-T1-DB	One IGX-UXME with one BC-UAI-4-T1-DB15
BC-UAI-4-T1-DB15	4 Port T1 Back Card with DB15 Connector
IGX-UXME-4-E1-BN	One IGX-UXME with one BC-UAI-4-E1-BNC
BC-UAI-4-E1-BNC	4 Port E1 Back Card with BNC Connector
IGX-UXME-4-E1-DB	One IGX-UXME with one BC-UAI-4-E1-DB15
BC-UAI-4-E1-DB15	4 Port E1 Back Card with DB15 Connector
BC-UVI-2J1EC	UVM Back Card, 2 J1 Ports with Echo Cancellor
BC-550150-Y1	Backcard/Y1 (BC-Y1)
IGX-LDM	Low Speed Data Module
BC-5286A-RS232	LDM Back Card/4 Port/RS232C (LDI4)
BC-5287A-RS232	LDM Back Card/8 Port/RS232C (LDI8)

The effective date of the End of Life (EoL) is May 31, 2002. Customers will receive Technical Assistance Center (TAC) and RMA support for these modules as noted below in the Milestone Dates section.

Table 2 below outlines the EoL Replacement List.

Table 2 Replacement parts list

Comparison Overview EoL Cisco Product Number	Replacement
IGX-UXME-2-155XLR	No Replacement
BC-UA1-2SMFXLR	No Replacement
IGX-UXME-4-155XLR	No Replacement
BC-UA1-4SMFXLR	No Replacement
IGX-UXME-4-T1-DB	IGX-UXME-8-T1-DB
BC-UA1-4-T1-DB15	BC-UA1-8-T1-DB15
IGX-UXME-4-E1-BN	IGX-UXME-8-E1-BN
BC-UA1-4-E1-BNC	BC-UA1-8-E1-BNC
IGX-UXME-4-E1-DB	IGX-UXME-8-E1-DB
BC-UA1-4-E1-DB15	BC-UA1-8-E1-DB15
BC-UVI-2J1EC	None
BC-550150-Y1	None
IGX-LDM	IGX-HDM
BC-5286A-RS232	BC-5084B-RS232
BC-5287A-RS232	BC-5084B-RS232

There are a few differences between the LDM and its replacement HDM, as outlined below:

- No support of 8-port Back Card for IGX-HDM. IGX-HDM supports 4-port Back Cards with a choice of different physical interfaces.
- No support of control bit transport mode called "Embedded EIA" on IGX-HDM
- IGX-HDM supports data rates from 1.2kbps up to 1344kbps on all 4 ports. IGX-LDM supports data rates from 1.2kbps up to 56kbps per port on the 4-port version and 1.2kbps to 19.2kbps per port on the 8-port version.

Milestone Effective Dates for EoL

End of Sales & End of Life Announcement: December 14, 2001

End of Sales: May 31, 2002

End of Engineering (Firmware and Hardware): December 2004

End of Service Contract Renewal: December 10, 2005

End of Support/End of Life: December 10, 2006

Ordering Information

May 31, 2002 will be the last date to enter orders for all items listed in Table 1. Hardware support will be provided until December 2006. Switch Software 9.3 will be the last release supporting these cards. Customers will continue to receive Technical Assistance Center and RMA support until November 2006.



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: +65 317 7777
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the

Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992-2002, Cisco Systems, Inc. All rights reserved. CCIP, the Cisco Arrow logo, the Cisco Powered Network mark, the Cisco Systems Verified logo, Cisco Unity, Follow Me Browsing, FormShare, Internet Quotient, iQ Breakthrough, iQ Expertise, iQ FastTrack, the iQ logo, iQ Net Readiness Scorecard, Networking Academy, ScriptShare, SMARTnet, TransPath, and Voice LAN are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, Discover All That's Possible, The Fastest Way to Increase Your Internet Quotient, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, IOS, IP/TV, LightStream, MGX, MICA, the Networkers logo, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, SlideCast, StrataView Plus, Stratm, SwitchProbe, TeleRouter, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0206R) ETMG/8.02