

# EoL for MGX 8850 PXM-45 Switch Software

Versions 2.0.00, 2.0.01, and 2.0.02

A stylized globe graphic in blue and white, showing latitude and longitude lines, positioned on the left side of the page.

## Overview

Cisco Systems announces the end of life (EOL) for MGX™ 8850 PXM-45 Software Releases 2.0.00, 2.0.01 and 2.0.02 with an effective date of 11/10/00. These releases are no longer orderable on CCO.

Software Release 2.0.10 or later (2.0.11, 2.0.12) will replace releases 2.0.00, 2.0.01 and 2.0.02.

## Ordering Information

The new model numbers for MGX 8850 PXM-45 software release 2.0.1x (2.0.10, 2.0.11, 2.0.12) are:

- MGX8850-SW-201X
- MGX8850SW-201X
- MGX8850-SW-201XCD=

## Definitions

- *End of Life*—After this milestone date the software release is no longer supported by CSE and is removed from CCO.

For More Information Contact:

Mihir Maniar

Product Manager

MSSBU, Cisco Systems

Phone: 408 525-9491

E-mail: [mmaniar@cisco.com](mailto:mmaniar@cisco.com)

**Corporate Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

**European Headquarters**

Cisco Systems Europe  
11, Rue Camille Desmoulins  
92782 Issy Les Moulineaux  
Cedex 9  
France  
www.cisco.com  
Tel: 33 1 58 04 60 00  
Fax: 33 1 58 04 61 00

**Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

**Asia Pacific Headquarters**

Cisco Systems Australia, Pty., Ltd  
Level 17, 99 Walker Street  
North Sydney  
NSW 2059 Australia  
www.cisco.com  
Tel: +61 2 8448 7100  
Fax: +61 2 9957 4350

**Cisco Systems has more than 190 offices in the following countries. Addresses, phone numbers, and fax numbers are listed on the  
Cisco.com Web site at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE  
Finland • France • Germany • Greece • Hong Kong • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The  
Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia  
Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2000, Cisco Systems, Inc. All rights reserved. Printed in the USA. MGX is a trademark; Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. or its affiliates in the U.S. and certain other countries. All other brands, names, or trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0008R)