



End-of-Sale and End-of-Life Announcement for Cisco IDS 4210 Appliance Sensor

Cisco Systems® announces the end of life of the Cisco® IDS 4210 Appliance Sensor. The last day to order the Cisco IDS 4210 is December 6, 2003. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until December 6, 2008. Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco IDS 4210.

The replacement products for the Cisco IDS 4210 is the Cisco IDS 4215. The 4215 delivers increased performance at 80 Mbps, with a reduced form factor. The IDS 4215 also delivers lower price/performance and lowers total cost of ownership with the provision of multiple sniffing interfaces (4 FE) through an optional field upgrade.

Table 1 End-of-Life Milestones and Dates for the Cisco IDS 4210 Appliance Sensor

Milestone	Definition	Date
End-of-sale announcement date	The date the end-of-sale and end-of-life announcement is distributed to the general public.	June 6, 2003
End of sale date	The last date to order Cisco IDS 4210 through Cisco point-of-sale mechanisms. The product is no longer for sale.	December 6, 2003
Last shipment date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on led time.	March 6, 2004
End of new service attachment date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	December 6, 2004
End of service contract renewal date	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	December 6, 2007
Last date of support	The last date to receive service and support for Cisco IDS 4210 Sensor Appliance. After this date, all support services for Cisco IDS 4210 are unavailable, and the product becomes obsolete.	December 6, 2008



Table 2 Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
IDS-4210-K9	Cisco IDS 4210 Appliance Sensor

Table 3 Replacement Product Part Numbers

End-of-Sale Product Part Number	Product Description
IDS-4215-K9	Cisco IDS 4215 Appliance Sensor

Additional Information

For more information about Cisco products, contact your Cisco account manager and/or Cisco Channel Partner.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html.



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the
Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2003 Cisco Systems, Inc. All rights reserved. Cisco, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company.
(0304R) RD/LW4425 06/03