

End of Sale for Cisco Unity 2.46

Wholesale Price List Software Part Numbers and Temporary Voiceboard Lead Time Change

Effective September 14, 2001, Cisco will stop selling the Cisco Unity 2.46 software distributor part numbers. Cisco Unity 3.0 software and servers will supersede the Cisco Unity 2.46 parts listed below.

End of Sale Details

- Affected product—distributor Cisco Unity 2.46 software parts
- End of sale date—September 14, 2001
- End of sale announcement—September 14, 2001

The affected distributor part numbers are listed below:

Part number	Description
IPV4246	Unity IP, 4 ports VM
DSV4246	Unity Dual/PBX, 4 ports VM
IPV8246	Unity IP, 8 ports VM
DSV8246	Unity Dual/PBX, 8 ports VM
IPV12246	Unity IP, 200 Users VM, 12 Ports
DSV12246	Unity Dual/PBX, 200 Users VM, 12 ports
IPV16246	Unity 2.46 IP; 16 Ports VM
IPV24246	Unity 2.46 IP; 24 Ports VM
IPU4T2246	Unity IP, 4 ports UM
DSU4T2246	Unity Dual/PBX, 4 ports UM
IPU8T2246	Unity IP, 8 ports UM
DSU8T2246	Unity Dual/PBX, 8 ports UM
IPU12T2246	Unity IP, 200 Users UM, 12 Ports, 2 TTS
DSU12T2246	Unity Dual/PBX, 200 Users UM, 12 Ports, 2 TTS
IPU16T4246	Unity 2.46 IP; 16 Ports UM, 4 TTS
IPU24T4246	Unity 2.46 IP; 24 Ports UM, 4 TTS



The new distributor part numbers for Cisco Unity 3.0 are:

Part number	Description
UNITY-SVR-1400-OS=	Dell 1400 (W2K included)
UNITY-SVR-2500AOS=	Dell 2500 rack; 512MB (W2K included)
UNITY-SVR-2500BOS=	Dell 2500 rack; 512MB; RAID 5 (W2K included)
UNITY-SVR-2500COS=	Dell 2500 rack; 1GB; RAID 5, 2nd CPU (W2K included)
UNITY-SVR-7825=	MCS-7825 (W2K included)
UNITY-SVR-7835TP=	MCS-7835 with RAID 1 and tape backup (W2K included)
UNITY-SVR-7835NTP=	MCS-7835 with RAID 1 (W2K included)
UNITY-2500-RAIL=	Dell 2500 Rail Kit
UNITYU50-4-3.0=	Unity Unified Messaging, 50 users (includes 4 sessions)
UNITYU100-8-3.0=	Unity Unified Messaging, 100 users (includes 8 sessions)
UNITYU200-12-3.0=	Unity Unified Messaging, 200 users (includes 12 sessions)
UNITYU300-16-3.0=	Unity Unified Messaging, 300 users (includes 16 sessions)
UNITYU500-24-3.0=	Unity Unified Messaging, 500 users (includes 24 sessions)
UNITYU875-32-3.0=	Unity Unified Messaging, 875 users (includes 32 sessions)
UNITYU1175-40-3.0=	Unity Unified Messaging, 1175 users (includes 40 sessions)
UNITYU1600-48-3.0=	Unity Unified Messaging, 1600 users (includes 48 sessions)
UNITYV50-4-3.0=	Unity Voice Messaging, 50 users (includes 4 sessions)
UNITYV100-8-3.0=	Unity Voice Messaging, 100 users (includes 8 sessions)
UNITYV200-12-3.0=	Unity Voice Messaging, 200 users (includes 12 sessions)
UNITYV300-16-3.0=	Unity Voice Messaging, 300 users (includes 16 sessions)
UNITYV500-24-3.0=	Unity Voice Messaging, 500 users (includes 24 sessions)
UNITYV875-32-3.0=	Unity Voice Messaging, 875 users (includes 32 sessions)
UNITYV1175-40-3.0=	Unity Voice Messaging, 1175 users (includes 40 sessions)
UNITYV1600-48-3.0=	Unity Voice Messaging, 1600 users (includes 48 sessions)
UNITY-RS-2ML=	Unity, 2-port Real Speak TTS, US Eng, UK, Fr, Ger, Euro Sp
UNITY-RS-4ML=	Unity, 4-port Real Speak TTS. US Eng, UK, Fr, Ger, Euro Sp
UNITY-RS-6ML=	Unity, 6-port Real Speak TTS. US Eng, UK, Fr, Ger, Euro Sp
UNITY-MULTILANG=	Multiple Language support
UNITY-AMIS=	Unity, AMIS-A networking

Distributor part numbers for Cisco Unity 3.0 will be activated on September 14, 2001.

Services and Support

Customers with SAS or SASU contracts will continue to receive software support from Cisco TAC. SAS customers will only receive support on Cisco Unity up to version 2.46. Beginning with the shipment of Cisco Unity 3.0, SASU will be the only software support offering.

Temporary Lead Time Change for the D/120JCT Euro Voice Board

Cisco would also like to proactively communicate current sourcing problems for the D/120JCT Euro voice board. Cisco is currently unable to procure this voice board from the manufacturer. Current ETA is October 15th 2001, but this date is subject to change. All orders that have been placed using part numbers UNITY-D/120JCT-EU or UNITY-D/120JCT-EU= will be shipped as soon as Cisco has received this board in inventory. Until then, these orders will remain on hold.



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems Europe
11, Rue Camille Desmoulins
92782 Issy-les-Moulineaux
Cedex 9
France
www-europe.cisco.com
Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems Australia, Pty., Ltd
Level 9, 80 Pacific Highway
P.O. Box 469
North Sydney
NSW 2060 Australia
www.cisco.com
Tel: +61 2 8448 7100
Fax: +61 2 9957 4350

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the

Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia
Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru
Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa
Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2001, Cisco Systems, Inc. All rights reserved. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0108R)