

# Announcing CiscoWorks2000 QoS Policy Manager 2.1

Cisco Systems announces the availability of CiscoWorks2000 QoS Policy Manager (QPM) 2.1 for Windows. A key enabler of Cisco end-to-end quality of service (QoS) for enterprise networks, QPM 2.1 delivers streamlined, centralized policy control and automated reliable policy deployment.

The new CiscoWorks2000 QPM 2.1 application includes:

- Comprehensive support for voice over IP (VoIP) in Enterprise networks that now includes:
  - IP Telephony templates that contain predefined QoS policies to easily and accurately provision end-to-end priority service for voice
  - Support for Catalyst® 4224 and Catalyst 4000 Access Gateway Module.
- Class-based weighted fair queuing (CBWFQ) for ATM interfaces, sub-interfaces and virtual circuits
- Extensive QoS for Content Networking by supporting NBAR on Cisco 2600 and 3600 routers as well as dNBAR for VIP interfaces.
- Greater QoS policy management at the network edge including excess rate policing, support for Catalyst 3524XL, 2900XL, Catalyst 6000 with Distributed Forwarding Card (DFC), Catalyst 6000 configured with Supervisor Cisco IOS® 12.1(6)E or later, and traffic shaping and limiting on Catalyst 4003/4006 with layer 3 services engine.

## Availability

QPM 2.1 will begin shipping June 20, 2001. Customers interested in purchasing this solution can place orders through normal sales channels (see below for ordering information) beginning June 13, 2001.

Existing QPM 2.0 customers with current Software Application Support (SAS) contracts can request the upgrade using their service contract number at <http://www.cisco.com/upgrade> beginning June 13, 2001.

## Ordering Information

Part	Description
CWQPM-2.1-WIN	QoS Policy Manager 2.1 for NT, Win2K
CWQPM-2.1-WIN-UPG	QoS Policy Manager 2.1 for NT and Win2K; upgrades from QPM 1.1
CON-SAS-QPM2.XWIN	Cisco SAS service contract for QPM 2.X

## Existing Products Affected

With the availability of CiscoWorks2000 QPM 2.1, Cisco announces the end of sale for the following products:

Part	Description
CWQPM-2.0-NT	QoS Policy Manager 2.0 for NT
CWQPM-2.0-NT-UPG	QoS Policy Manager 2.0 for NT; upgrades from QPM 1.1
CON-SAS-QPM-2.0-NT	Cisco SAS service contract for QPM 2.0 for NT

## Product Information:

<http://www.cisco.com/warp/public/cc/pd/wr2k/qoppmn/>



### Corporate Headquarters

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA

[www.cisco.com](http://www.cisco.com)  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

### European Headquarters

Cisco Systems Europe  
11, Rue Camille Desmoulins  
92782 Issy-les-Moulineaux  
Cedex 9  
France

[www.cisco.com](http://www.cisco.com)  
Tel: 33 1 58 04 60 00  
Fax: 33 1 58 04 61 00

### Americas Headquarters

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA

[www.cisco.com](http://www.cisco.com)  
Tel: 408 526-7660  
Fax: 408 527-0883

### Asia Pacific Headquarters

Cisco Systems Australia, Pty., Ltd  
Level 9, 80 Pacific Highway  
P.O. Box 469  
North Sydney  
NSW 2060 Australia

[www.cisco.com](http://www.cisco.com)  
Tel: +61 2 8448 7100  
Fax: +61 2 9957 4350

**Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the**

**Cisco.com Web site at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Czech Republic  
Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel  
Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal  
Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden

All contents are Copyright © 1992–2001 Cisco Systems, Inc. All rights reserved. Important Notices and Privacy Statement. Printed in the USA. Catalyst, Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. or its affiliates in the U.S. and certain other countries.

All other brands, names, or trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0101R)

05/01 BW7307