

Release Notes for Cisco CVR100W Wireless-N VPN Router Firmware Version 1.0.1.24

March 2017

These Release Notes describe the resolved issues in Cisco CVR100W Wireless-N VPN Router firmware version 1.0.1.24.

Resolved Issues

The following table lists the resolved issues in firmware version 1.0.1.24:

Ref Number	Description
CSCvc14457	Remote management ACL bypass vulnerability. Solution: Fixed.

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html
Cisco Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Products. No login is required.
Product Documentation	
CVR100W	www.cisco.com/go/cvr100w
Cisco Small Business	
Cisco Partner Central (Partner Login Required)	www.cisco.com/web/partners/sell/smb

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2013 Cisco Systems, Inc. All rights reserved. PN: OL-30579-01