

Release Notes for Cisco RV042G Dual Gigabit WAN VPN Router Firmware Version 4.2.3.08

February 2017

These Release Notes describe the resolved issues in Cisco RV042G Dual Gigabit WAN VPN Router firmware version 4.2.3.08.

Resolved Issues

The following table lists the resolved issues in firmware version 4.2.3.08:

Ref Number	Description
CSCvb81527	Problem: SSL certificate only supports SHA1. Solution: SSL certificate upgraded to support SHA256.

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html
Cisco Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Products. No login is required.
Product Documentation	
CVR100W	www.cisco.com/go/RV042G
Cisco Small Business	
Cisco Partner Central (Partner Login Required)	www.cisco.com/web/partners/sell/smb

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2017 Cisco Systems, Inc. All rights reserved. PN: OL-30579-01