

Release Notes for Cisco RV130x Router Firmware Version 1.0.3.51

June 2019

This document describes known and resolved issues in the Cisco RV130x Firmware Version 1.0.3.51. Overall security on the device has improved with this firmware release.

Contents

- [Resolved Issues](#)
- [Related Information](#)

Resolved Issues

Caveats Resolved in Release 1.0.3.51

Number	Description
CSCvj79813	Some IP ranges values cannot be applied in Access Policy IP Range setup.

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Cisco Firmware Downloads	www.cisco.com/go/software Select a link to download firmware for Cisco Small Business Products. No login is required.
Product Documentation	
Cisco RV Series Routers	www.cisco.com/go/smallbizrouters

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2019 Cisco Systems, Inc. All rights reserved.