

Release Notes for Cisco RV130/RV130W Routers Firmware Version 1.0.0.21

March 2014

This document describes known issues in Cisco RV130/RV130W Firmware Version 1.0.0.21.

Contents

[Known Issues, page 2](#)

[Related Information, page 3](#)

Known Issues

Caveats Acknowledged in Firmware Version 1.0.0.21

Problem: If users set outbound firewall access rules to Deny, then create an Internet access policy to permit a specific website, the access rule does not work and other websites are also permitted. (CSCun04513)

Solution: None.

Problem: If users enable Email settings, set **Authentication with SMTP Server** to Login and enter a secondary email address to which to send logs, email is not sent to the secondary address provided. (CSCum76056)

Solution: Disable the Login authentication option.

Problem: STP does not work accurately with Link Aggregation Groups (LAG). For example, if ports 1 and 2 are included in a LAG, the STP root bridge is wrong after the link status changes for port 1. (CSCum50055)

Solution: Disable LAG.

Problem: The WDS links is not up if the peer MAC address format is incorrect. For example, users enter 001122334455 instead of 00:11:22:33:44:55. (CSCum59546)

Solution: Change the MAC address format to '00:11:22:33:44:55'.

Problem: Wireless clients may not be able to access the Internet when roaming between the device and another access point on the LAN side. (CSCum42666)

Solution: Enable WAN QoS or STP on LAN ports.

Problem: When the syslogs reach 1000, the device does not email logs to users. (CSCum72888)

Solution: Use the syslogs server to view the messages or check local syslogs.

Problem: VLAN ID 80 does not work. (CSCum31734)

Solution: Use other VLAN IDs.

Problem: If the PPTP tunnel is established and users create a new VLAN, the PPTP clients are offline and cannot connect again. (CSCum72910)

Solution: Go to the PPTP Settings page and save again.

Problem: If Dead Peer Detection is enabled, the IPsec VPN tunnel may reconnect in case of heavy traffic. (CSCum72973)

Solution: Limit heavy traffic over the VPN tunnel.

Related Information

| Support | |
|---|---|
| Cisco Small Business Support Community | www.cisco.com/go/smallbizsupport |
| Cisco Small Business Support and Resources | www.cisco.com/go/smallbizhelp |
| Cisco Small Business Firmware Downloads | www.cisco.com/go/software Select a link to download firmware for Cisco Small Business Products. No login is required. |
| Product Documentation | |
| Cisco Small Business RV Series Routers | www.cisco.com/go/smallbizrouters |
| Cisco Small Business | |
| Cisco Partner Central for Small Business (Partner Login Required) | www.cisco.com/web/partners/sell/smb |
| Cisco Small Business Home | www.cisco.com/smb |

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2014 Cisco Systems, Inc. All rights reserved.

OL-31728-01