

Release Notes for Cisco RV132W/RV134W Router Firmware Version V.1.0.1.11

February 2018

This document describes known and resolved issues in the Cisco RV132W/RV134W Firmware Version 1.0.1.11

- [Resolved Issues](#)
- [Related Information](#)

Resolved Issues

Caveats Resolved in Release 1.0.1.11

Number	Description
CSCvg92739 (RV132W)	Unauthenticated Information Disclosure Vulnerability. Solution: Fixed
CSCvg92737 (RV132W)	Remote Code Execution and Denial of Service Vulnerability. Solution: Fixed
CSCvh60170 (RV134W)	Remote Code Execution and Denial of Service Vulnerability. Solution: Fixed
CSCvh60172 (RV134W)	Unauthenticated Information Disclosure Vulnerability. Solution: Fixed

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Cisco Firmware Downloads	www.cisco.com/go/software Select a link to download firmware for Cisco Small Business Products. No login is required.
Product Documentation	
Cisco RV Series Routers	www.cisco.com/go/smallbizrouters

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2018 Cisco Systems, Inc. All rights reserved.