



# System Release 4.3.1 Release Notes



# Please Read

## Important

Please read this entire guide. If this guide provides installation or operation instructions, give particular attention to all safety statements included in this guide.

# Notices

## Trademark Acknowledgments

- Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks).
- DOCSIS is a registered trademark of Cable Television Laboratories, Inc.
- CableCARD, OCAP, OpenCable, and tru2way are trademarks of Cable Television Laboratories, Inc.
- Other third party trademarks mentioned are the property of their respective owners.
- The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1009R)

## Publication Disclaimer

Cisco Systems, Inc. assumes no responsibility for errors or omissions that may appear in this publication. We reserve the right to change this publication at any time without notice. This document is not to be construed as conferring by implication, estoppel, or otherwise any license or right under any copyright or patent, whether or not the use of any information in this document employs an invention claimed in any existing or later issued patent.

## Copyright

© 2010, 2012 Cisco and/or its affiliates. All rights reserved. Printed in the United States of America.

Information in this publication is subject to change without notice. No part of this publication may be reproduced or transmitted in any form, by photocopy, microfilm, xerography, or any other means, or incorporated into any information retrieval system, electronic or mechanical, for any purpose, without the express permission of Cisco Systems, Inc.

# Contents

<b>About This Guide</b>	<b>v</b>
<b>Chapter 1 Highlights</b>	<b>1</b>
New Features.....	2
<b>Chapter 2 Site Requirements</b>	<b>3</b>
Upgrade Logistics .....	4
DNCS and Application Server Hardware Platforms.....	5
<b>Chapter 3 Implemented Issues</b>	<b>11</b>
Report - Implemented Issues for SR 4.3.1.....	12
Report - Implemented Enhancement Issues for SR 4.3.1.....	14
Report - Implemented Issues for Report Writer 1.0.....	15
Report - Implemented Enhancement Issues for Report Writer 1.0.....	16
<b>Chapter 4 Open Issues</b>	<b>17</b>
Report - Open Issues for SR 4.3.1.....	18
<b>Chapter 5 Customer Information</b>	<b>22</b>



# About This Guide

## Introduction

System Release 4.3.1 (SR 4.3.1) is a maintenance release of Cisco's Digital Broadband Delivery System (DBDS) software. These release notes contain the following information:

- A list of highlights with descriptions
- The list of media and software versions for this release
- Site requirements
- A description of closed, open, and enhanced issues for SR 4.3.1 and Report Writer 1.0
- General information on contacting Cisco® Systems

## Purpose

The purpose of these release notes is to inform system administrators contemplating an upgrade of the new features, known issues, and upgrade notes for SR 4.3.1.

## Audience

This document was written for system operators. Field service engineers and Cisco Services engineers may also find the information in this document helpful.

## Document Version

This is the second formal release of this document.





# 1

---

## Highlights

### Introduction

New features and product improvements for SR 4.3.1 are described in this chapter.

### In This Chapter

- New Features..... 2

## New Features

### Central Inventory Management Support

Central inventory management support on the DNCS requires a new Web Services interface that allows an inventory management client application to programmatically upload set-top staging information in mini-PIMS (PowerKEY Information Management System) format. The Web Services interface also allows a client application to reset the staging state of a set-top whose entitlements have expired.

### Dual EAS Support

Dual EAS support in this release allows conversion of In-Band (IB) SCTE-18 messages to force-tune messages, while preserving an overlay Out-Of-Band (OOB) EAS message. The DNCS now sends force-tune messages to DTA set-tops even if the system is configured for text scroll EAS.

No additional configuration is required for Dual EAS support.

# 2

---

## Site Requirements

### Introduction

This chapter provides information that helps you prepare for the upgrade to System Release 4.3.1. Read this entire chapter before you upgrade.

### In This Chapter

- Upgrade Logistics ..... 4
- DNCS and Application Server Hardware Platforms ..... 5

## Upgrade Logistics

### Introduction

This section contains information that can help system operators plan the upgrade to SR 4.3.1.

### Supported Upgrade Path

Note these important upgrade requirements:

- Systems that upgrade to SR 4.3.1 must currently be operating with system software from SR 4.3, as well as DHCT client operating system (OS) 3.1 or later.
- The upgrade software is on CD. For upgrade instructions, refer to *System Release 2.8.1/3.8.1/4.3.1 CD Upgrade Installation Instructions* (part number 4036043). Rollback procedures and software are also provided in the event that the upgrade is unsuccessful.
- You must already have the DBDS Utilities software installed on the DNCS and should have already run the pre-upgrade checks to ensure system compatibility with SR 4.3.1 CD upgrade requirements. Refer to *DBDS Utilities Version 6.3 Installation Instructions and User Guide* (part number 4031374) for instructions on installing and executing the DBDS Utilities.

### Time to Complete

The entire upgrade to SR 4.3.1 must be completed within a single maintenance window that usually starts around midnight. A few pre-upgrade procedures, consisting mainly of system checks, backups, and various operations upon the metadevices of the DNCS, can be completed *before* the maintenance window begins.

Cisco engineers have determined that a typical site can be upgraded within one maintenance window. See *Scheduling Requirements* (on page 7) for additional details.

### System Performance Impact

Interactive services will not be available during the maintenance window.

# DNCS and Application Server Hardware Platforms

## Introduction

This section describes the hardware configurations that are supported by SR 4.3.1.

## Running the Doctor Report

- 1 If necessary, open an xterm window on the DNCS.
- 2 Type `cd /dvs/dnCS/Utilities/doctor` and then press **Enter**. The `/dvs/dnCS/Utilities/doctor` directory becomes the working directory.
- 3 Type `doctor` and then press **Enter**. The system generates a list of parameters that you can use to run the Doctor Report. Each parameter causes the Doctor Report to generate output with specific configuration information.

```

xterm
dudley>> cd /dvs/dnCS/Utilities/doctor
dudley>> doctor

= Doctor package version 6.3.0.14 =
doctor -agestpbinqhcrx [ vd ] or
doctor [-c<number>]

a - (almost) All options (except q and x)
g - General Info: info, installed software info, and
  App Server disk utilization, and App Server swap space,
  database utilization, database extents, load average,
  and App Server debug flags, tracing levels, and App
  Server processes, and App Server corefiles, DNS, check
  force tune for valid service, dnCS license check, large log file check
  install options
e - Element Info: DHCT state summary, DHCT type summary, active
  elements, mod slot tolerance, source, source definitions,
  segments, sessions, subscription packages, EMMs expiring soon.
s - SI Info: SI_INSERT_RATE, system time message, distinguished
  SI QAM, SI out of band interval.
t - Time Info: and App Server time sync, timezone, DST.
p - PPV Info: PPV services and events, PPV and SAM service
  discrepancies, event use services, PPV files, phoneactivetime,
  EUT, GBAMs.
b - BFS Info: BFS carousels, BFS sessions, BFS source definitions.
i - IPG Info: IPG collector, IPG data files.
n - Ping Elements: QPSK Ethernet, QPSK RF, QAM, NETCRYPT, BIG, TED.
q - Check for quarantined qams and ping elements.
  This option is NOT included in all (-a).
x - Check one-one correspondence of DHCTs and serial numbers.
  This option is NOT included in all (-a).
v - Verbose mode: Detailed output, even if OK.
d - Suppress screen output. Write to output file only.
h - Generate this help text.
c - Clean up (delete) all but the last <number> doctor reports.
  Use this switch independently of all others. Report NOT GENERATED.

r - and one of the following options:
hubqamList - list what hub are associated to which QAMs
smdgInfo - list SMDG (StatMUX Dejitter Group) and respective GQAM
sdbsgInfo - list SDB Service Group Mini Carousel Info
genericQamInfo - display generic QAMs and IPs
dualGbeQamInfo - display generic QAMs and IPs
sdbInfo - display SDB server info and status
pcgInfo - display PCGs info and status

One or more of the a, g, e, s, t, p, b, i, n, c, x or q options is required.
d and v are optional but should be used with a required option.
Option order is irrelevant.

Note the q option must be explicitly chosen. It can be time consuming.
The q option automatically sets the v (verbose) option and pings and checks rpc bind for qams.
dudley>>

```

- 4 Type **doctor -g** and press **Enter** to view the version of DNCS software installed and the DNCS and Application Server platform, CPU, and disk information.

## What to Verify Using the Doctor Report

Using the results of the Doctor Report, verify that your system meets the following requirements. For detailed information on reading the data in the Doctor Report, see the *DBDS Utilities Version 6.3 Installation Instructions and User Guide* (part number 4031374).

**Important:** DBDS Utilities 6.3 is required for SR 4.3.1.

### DNCS System Release Required

Your system must be running SR 4.3. In the Doctor Report, look for the **SAIdnscs** entry under the **All SAI Installed Package Information** section. Ensure the **SAIdnscs** version is 4.3.0.14 or later. If you have installed Service Packs for your system release, your version may include additional characters.

### DNCS Hardware Configurations

Ensure your site meets the following DNCS hardware requirements before upgrading to SR 4.3.1. The following table lists the minimum requirements for the DNCS hardware platforms that are supported by SR 4.3.1.

DNCS Server Platform	Hard Drive Configuration	Memory	Processor
Sun Fire V445	■ 4 X 73 GB	■ 4 GB min	■ 2 X 1.5 GHz min.
Sun Fire V890	■ 6 X 146 GB	■ 8 GB min.	■ 4 X 1.5 GHz min.
	■ 12 X 146 GB	■ 16 GB min.	■ 2 X 1.5 GHz min.
Sun Fire V880	■ 12 X 73 GB	■ 8 GB min.	■ 4 X 900 MHz min.
	■ 6 X 73 GB	■ 4 GB min.	■ 2 X 900 MHz min.

### Application Server Hardware Configurations

The following table lists the Application Server hardware platforms that are supported by SR 4.3.1.

Application Server Platform	Hard Drive Configuration	Memory	Processor
Sun V240	2 X 36 GB min.	512 MB min.	1 X 1.34 GHz min.
Sun V245	2 X 73 GB min.	2 GB min.	2 X 1.5 GHz min.
Sun Blade 150	1 X 20 GB min.	512 MB min.	1 X 550 MHz min.
Sun Ultra 5	1 X 18 GB min.	256 MB min.	1 X 333 MHz min.

## Scheduling Requirements

With the live upgrade, your site only needs to be down for 2 to 3 hours during the entire upgrade process. Most of the upgrade procedures have no system impact. The pre-install and pre-upgrade steps can be performed at any time of day. However, the actual upgrade process normally takes place during a maintenance window beginning at midnight. The following table provides a breakdown of each upgrade process.

Process	Length of Time	Activity
Pre-install	1-3 hours	Activities are performed by Cisco Services, including checking the overall health of the system. These activities do not impact the system.
Pre-upgrade	3-4 hours	Backing up the system: <ul style="list-style-type: none"> <li>■ Back up the system components</li> <li>■ Back up the DNCS and Application Server files</li> <li>■ Complete system checks</li> </ul> These activities do not impact the system.
Upgrade	6-8 hours total; 2-3 of these hours require system outage  <b>Note:</b> Actual time may vary based on the number of devices being upgraded.	Upgrade the DBDS network: <ul style="list-style-type: none"> <li>■ Back up the DNCS database</li> <li>■ Install the DNCS and Application Server software</li> <li>■ Determine which optional features (licensed or unlicensed) need to be enabled as a result of this upgrade</li> <li>■ Install and download the component software (QAM, MQAM, GQAM, and QPSK modulator)</li> <li>■ Reboot the hardware</li> <li>■ Complete functional checks</li> </ul> QPSK modulator upgrades and some QAM and MQAM upgrades can be completed with little or no subscriber impact. However, 2-3 hours of the upgrade require system outage.
Post-Upgrade	3-4 hours	Back up the system: <ul style="list-style-type: none"> <li>■ Back up the file system</li> <li>■ Back up the DNCS database</li> </ul> These activities do not impact the system.

## Software Configuration

### Introduction

This section lists the software versions in each media kit supplied with SR 4.3.1.

### Antecedents

This release succeeds and carries forward all of the enhancements, features, and improvements of previous system releases and related service packs.

### Software Versions

The following table lists the configuration of System Release and headend components before and after an upgrade to SR 4.3.1.

<b>DBDS Component</b>	<b>Previous Version Number</b>	<b>New Version Number</b>
<b>DNCS</b>		
DNCS Application	4.3.0.14	4.3.1.6
DNCS Patch	N/A	4.3.1.6p2
DNCS GUI	4.3.0.14	4.3.1.6
DNCS WUI	4.3.0.14	4.3.1.6
<b>DNCS Support Software</b>		
DNCS/App Server Tools	4.2.1.16	No Change
DNCS Spectrum Kit	4.2.1.0	No Change
DNCS Report Writer	4.3.0.6	r1.0.0.3
DNCS Online Help	4.3.0.3	4.3.1.0
<b>DNCS Platform</b>		
DNCS Platform (SAIcomplat/SAIdnapp)	SAIdnapp 4.3.0.5	No Change
Solaris	10 08/07 Update 4	No Change
Solaris Patches	4.3.0.1	No Change
Fore ATM Drivers	4.2.0.0	No Change
Video Propulsion DVB Direct ASI Drivers	1.0.0.6	No Change
Informix IDS	9.21.UC3	No Change
Tools (SAIttools)	4.2.1.16	No Change



DNCS and Application Server Hardware Platforms

<b>DBDS Component</b>	<b>Previous Version Number</b>	<b>New Version Number</b>
<b>Spectrum Installation</b>		
Spectrum Installation	4.2.1.0	No Change
Spectrum Enterprise Manager App Version	5.0R1	No Change
Spectrum CS1/MMS1 Supplement	CS3/MMS3 P122	No Change
<b>Application Server</b>		
App Server Application	3.5.0.1	No Change
<b>Application Server Platform</b>		
Application Server Platform	4.3.0.5	No Change
Solaris	10 08/07 Update 4	No Change
Solaris Patches	4.3.0.1	No Change
<b>ATM/BFS BIG</b>		
MSYNC Control Card D9711 App	2.25	No Change
MSYNC Control Card D9710 Boot	0.75	No Change
ATM OC3 Card D9722 Application	3.01.0	No Change
SWIF Receiver Card D9730 Application	2.02	No Change
SWIT Transmitter Card D9714 Application	2.03	No Change
<b>Grooming BIG</b>		
MSYNC Control Card D9711-2 App	3.01	No Change
MSYNC Control Card D9711-2 Boot	0.75	No Change
GPI Card D9476 App	0.8.2	No Change
GPI Card D9476 Boot	0.6.7	No Change
Automux Script	2.3	No Change

<b>DBDS Component</b>	<b>Previous Version Number</b>	<b>New Version Number</b>
<b>Sonet/ASI (STA)</b>		
Sonet/ASI (STA)	1.3.4	No Change
_Sonet/ASI (STA)	1.3.4	No Change
<b>DBDS Maintenance CD</b>		
DBDS Maintenance CD	3.3.8	No Change
Backup and Restore	6.0.18	No Change
Unipack Install Scripts	2.1.1.8	No Change
<b>Spectrum Support</b>		
Spectrum_Support	4.3.1.3	4.3.1.6
<b>Netcrypt</b>		
Netcrypt Bulk Encryptor	1.2.12	No Change
<b>QAM</b>		
QAM App	2.5.7	No Change
<b>MultiQAM</b>		
MQAM App	2.6.18	2.7.2*
<b>GQAM</b>		
GQAM	4.0.17	4.3.x**
<b>GoQAM RF / GoQAM IF</b>		
GoQAM RF / GoQAM IF	1.1.4	No Change
<b>QPSK Mod/Demod</b>		
QPSK Modulator	G08	G13*
QPSK Demodulator	G08	G13*
	App/A62 legacy	App/A62 legacy

\* These versions have been approved for use with SR 4.3.1, but are not being delivered with the SR 4.3.1 CD Upgrade Kit.

\*\* The GQAM software version is pending.

# 3

---

## Implemented Issues

### Introduction

This chapter provides a list of issues and enhancements that have been resolved in software for SR 4.3.1 and for Report Writer 1.0.

### In This Chapter

- Report - Implemented Issues for SR 4.3.1..... 12
- Report - Implemented Enhancement Issues for SR 4.3.1..... 14
- Report - Implemented Issues for Report Writer 1.0..... 15
- Report - Implemented Enhancement Issues for Report Writer 1.0.. 16

## Report - Implemented Issues for SR 4.3.1

ID #	Title
86578-06	siManager memory leaks
88145-08	QamManager audit traffic against XDQA at startup results in incomplete port resp
89452-03	OOB Bridge GUI needs to include all CCCM values in drop down list
89895-04	emmDistributor memory leak
90238-04	camAm leaks memory
91822-06	Primary SDV server doesn't recover (transition) from backup after a failover
92077-05	siManager intermittent in sending information
93004-05	Stranded sessions in qamManager after high qamManager activity
93110-06	qamManager should perform audit-based deletions first, then creations
93374-05	Online and primary fields are sometimes changed after a SDV download
93716-06	sdvManager opening multiple connections to database
93862-06	At startup qamManager audits generic qams twice, gqam and caqam only once
94077-05	Loss of DSG Filter for OCAP Object Carousel
94089-04	Sdv server wui is allowing duplicate name and ipaddress just by refreshing wui
94890-10	qamManager provisioning not complete, RF parameters and GigE IP not updating

ID #	Title
95528-07	bsm connection logic to siMgr causes re-connect churn when siMgr is down
96454-03	qpskManager cored while bouncing the DNCS
96610-07	Add scripts svcgroup_rsr.sh for postupgrade of svc_group_rsr, and updatemaxbw.sh
99590-03	qamManager can core auditing generic qams
100440-05	camEx core dumps when invalid STB mac address is sent over the OCAI interface
101977-02	QpskManager alternates sending current and old time packets
102567-02	siManager takes too long to rebuild VCT table
103064-01	OCAI requests slow to 0.5 sec each
103080-01	CamEx memory growing during VOD OCAI testing
103323-05	qamManager cache not correctly deleting QAMs
103823-03	When DCM table is split into multiple packets, first virtual ch set incorrectly
104538-02	failed session set up on GbE port of qam
105377-02	EAS Priority 0 causes DTA to force tune
106047-02	GQAM RPC API v2 does not act on TSR responses from GQAM
106229-01	EAS - 1 part channel number is not populated correctly by MMMServer in SCTE-18
108151-01	The WUI incorrectly rejects the TSR setup with GigE as input

## Report - Implemented Enhancement Issues for SR 4.3.1

ID#	Title & Description
89850-04	CCCM column db updates during SR upgrade from earlier releases CCCM default values are not currently set to the correct value during a database upgrade.
98495-06	UNCC needs to be sent from port 13818 Panasonic set-tops are expecting the UNCC to come from port 13818.

## Report - Implemented Issues for Report Writer 1.0

<b>ID#</b>	<b>Title</b>
72014-02	Channel, source and session report is not working
82951	Non Responding DHCTs-Lost connection report is showing incorrect information
86243	PCG Report is showing database error messages
87788	DNCS Reports -Channels, Sources, Sessions Report has incorrect and missing data
88986	Netcrypt Report is showing incorrect Encryption Type for an existing netcrypt
89074	qpsk Modems report is not showing exact channel frequency
90797	SNMP Poll Report is not showing the QPSK DeMod Freq correctly
91652	Combo Box support for Non-Responding DHCTs SNMP Report
97754-01	Seach function does not work properly in Report Writer
98375-01	Report Manager - DHCT Report lists N/A for all values for VCTID & ModID

## Report - Implemented Enhancement Issues for Report Writer 1.0

<b>ID#</b>	<b>Title &amp; Description</b>
91655	<p>Enabling and disabling reports for Report Writer</p> <p>Users have reported seeing reports even if the corresponding features were not enabled.</p>
93026	<p>Create new report for CableCARD combo device admin/operator status</p> <p>This new report will provide information for the CableCARD and host devices similar to the information that is currently provided in the DHCT report for the pre-CableCARD (embedded security) devices (i.e. Admin/Operational status, S/N, MAC Addr, IP Address, and so on). This CableCARD/host status information is not currently provided in the CableCARD Report.</p>
94506-02	<p>Request change to include additional data</p> <p>The following data categories have been added to Report Writer:</p> <ul style="list-style-type: none"><li>Headend</li><li>HubID</li><li>MPEG</li><li>Multicast IP</li><li>UDP</li><li>Source IP</li><li>QAM Name</li><li>QAM IP</li><li>QAM MAC</li><li>POD</li><li>SEM IP</li></ul>



# 4

---

## Open Issues

### Introduction

This chapter provides a list of open issues that were identified during testing of SR 4.3.1. Resolutions to these issues are currently under investigation or in development.

If you have questions about a particular issue, contact your account representative.

**Note:** There are no open issues for Report Writer 1.0.

### In This Chapter

- Report - Open Issues for SR 4.3.1..... 18

## Report - Open Issues for SR 4.3.1

ID #	Title & Description
106212-01	<p data-bbox="630 373 1349 401">LoadPIMSFile return codes need to meet ICD and SRS requirements</p> <p data-bbox="630 453 1357 506">Most failure cases return 'unspecified-error' instead of a more specific response.</p> <p data-bbox="630 516 1398 569">Recommendation: When error messages are vague, users should search through the logs to determine why failures occurred.</p>
107076-04	<p data-bbox="630 625 1349 653">DNCS Database Differences Are Present After a 4.3.1.x CD Upgrade</p> <p data-bbox="630 705 1398 789">When upgrading to 4.3.1.x via CD, the SAldncls_4.3.1.5_install.log indicates that there are differences (warnings) found in the dnclsdb.</p> <p data-bbox="630 831 911 852">There is no system impact.</p>
107499-01	<p data-bbox="630 909 1203 936">siManager won't come out of recovery database locked</p> <p data-bbox="630 989 911 1010">Set-top boxes will not boot.</p> <p data-bbox="630 1020 1373 1041">This problem occurs when bouncing siManager after creating a source.</p> <p data-bbox="630 1052 1349 1104">Workaround: Close the Source&gt;Source Definition List window before bouncing siManager.</p>
107500-01	<p data-bbox="630 1161 1008 1188">DNCS taking 30+ minutes to recover</p> <p data-bbox="630 1241 1398 1419">Slow recovery causes delays for set-top boots and interactive sessions. This problem only occurs when the +zip option is turned on for logging and only with a system setup where /dvs/dncls/tmp and /dvs/dncls/tmp/savelogs are not on the same file system. For example, this scenario would occur if the user hooks up an external drive or mounts a network drive in order to archive the logs.</p>
107505	<p data-bbox="630 1476 1333 1503">Cannot update TSR - DNCS database holding on to completed TSR</p> <p data-bbox="630 1556 1414 1608">This problem occurs when users attempt to change TSR parameters. TSRs cannot be updated.</p> <p data-bbox="630 1619 1430 1734">Workaround: To update a TSR, delete the TSR and set up a new one. This procedure works as long as the user has not attempted to update the TSR. If the user has made changes to the TSR, he must delete the TSR and run clearDbSessions before setting up a new one.</p>

ID #	Title & Description
107517-01	<p>XML Parsing err observed in CableCARD UI if " or &lt; is used in Phone Number field</p> <p>XML parsing errors should not occur for " or &lt;. When characters are entered that cannot be parsed, the field turns yellow to indicate an error. Do not hit Enter when the field is yellow because the system will accept the input. Once entered, the only way to correct the error is to delete the record.</p> <p>Recommendation: Use care when entering phone numbers on the CableCARD user interface.</p>
108310	<p>SAlwebui install stops and immediately restarts Tomcat and http-apache2</p> <p>During SAlwebui package installation, Tomcat and apache2 are stopped and immediately restarted. They should not restart until the post-install.</p> <p>This does not appear to have any impact as the installation, since the CD upgrade doc (4036043A) instructs the installer to reboot the DNCS and AppServer after the packages have been installed.</p>
108325-01	<p>The smdgrsr table is listing the output_port value as the device_type</p> <p>This could lead to SMDGs not being recovered correctly.</p>
108903-03	<p>DNCS sends incorrect input port on Unicast SMDG delete stranding the SMDG.</p> <p>The SMDG will be stranded on the GQAM preventing the creation of additional SMDGs on the output port until the GQAM is rebooted.</p> <p>Recommendation: Reboot the GQAM.</p>
108910-03	<p>RF Output Carrier incorrectly displayed on Multicast Session wui</p> <p>The RF output carrier is correctly entered but is incorrectly displayed on the Multicast Session wui. The database is correct.</p> <p>Recommendation: Operators should write down the output carrier value when it is entered.</p>

## Chapter 4 Open Issues

ID #	Title & Description
109566-01	<p data-bbox="630 268 1308 323">De-Selecting "VOD Redundancy Mode" and saving GQAM is not removing DB record</p> <p data-bbox="630 348 1425 407">Workaround: Delete the GQAM and re-add it without enabling dual mode or VOD redundancy.</p>
109569-01	<p data-bbox="630 464 1349 518">DRM using IP from "redun_gbe_params" table when "Dual Gbe Port" selected</p> <p data-bbox="630 552 1360 606">The DRM should be using the primary GbE IP address when the VOD Redundancy Mode is not selected.</p> <p data-bbox="630 615 1349 667">This issue will affect the changing of a dual GQAM operating in VOD redundancy mode back to normal GQAM mode.</p>
109580-01	<p data-bbox="630 724 1308 751">TSRs do not appear in WUI if GQAM management IP is changed</p> <p data-bbox="630 806 1403 890">Operators will not be able to tell if TSRs are present on a GQAM. Recommendation: Do not change the GQAM management IP if TSRs are present.</p>
109603	<p data-bbox="630 947 1344 974">mgrUIServer process settles in yellow state after the DNCS upgrade.</p> <p data-bbox="630 1026 1276 1052">Workaround: Manually restart the tomcat and apache servers.</p>
109624-01	<p data-bbox="630 1108 1073 1136">qpskManager cores while deleting a QPSK</p> <p data-bbox="630 1190 1409 1274">qpskManager should restart automatically unless the problem has occurred several times in a row. Check the DNCS moritor status. If qpskManager is down, restart the process manually.</p>

ID #	Title & Description
109952-02	<p>The manage_pims_files should run by dncs crontab only</p> <p>The /dvs/dncls/tmp/manage_pims_files.log denies overwrites. This behavior confuses users.</p> <p>When upgrading the DNCS package from SR 4.3.1.3 to higher versions there there may still be a "manage_pims_files" entry in root crontab. If there is, please remove it by following the instructions below:</p> <ol style="list-style-type: none"> <li>1) Login to the DNCS as root user.</li> <li>2) Enter crontab -l which will display the root crontab entries. The output will look something like this: <pre data-bbox="646 592 1096 1039">#ident "@(#)root 1.21 04/03/23 SMI" # # The root crontab should be used to perform accounting data collection. # # 10 3 * * * /usr/sbin/logadm 15 3 * * 0 /usr/lib/fs/nfs/nfsfind 30 3 * * * [ -x /usr/lib/gss/gsscred_clean ] &amp;&amp; /usr/lib/gss/gsscred_clean 0 0 * * * /usr/sbin/audit -n 0 * * * * /etc/security/audit_clean 45 * * * * [ -x /dvs/dncls/etc/manage_dnclsLog ] &amp;&amp; /dvs/dncls/etc/manage_dnclsLog &gt; /dvs/dncls/tmp/manage_dnclsLog.log 2&gt;&amp;1 0 0 * * * [ -x /dvs/dncls/etc/newdnclslog ] &amp;&amp; /dvs/dncls/etc/newdnclslog 30 1 * * * [ -f /dvs/dncls/bin/dnclsSetup ] &amp;&amp; ( . /dvs/dncls/bin/dnclsSetup ; \$DNCS_TOP/bin/updateStatistics.sh ) &gt; /dev/null</pre> </li> <li>3) Verify the information above. If there is an entry for "manage_pims_files," then remove it by editing the root crontab, using this command: <pre data-bbox="662 1102 771 1129">crontab -e</pre> </li> <li>4) Verify the /dvs/dncls/tmp/manage_pims_files.log. If this file exists, remove it by running the following commands: <ol style="list-style-type: none"> <li>a. Login as DNCS user.</li> <li>b. Enter <code>rm /dvs/dncls/tmp/manage_pims_files.log</code></li> <li>c. If permission is denied, login as root user and enter <code>rm /dvs/dncls/tmp/manage_pims_files.log</code> once more.</li> </ol> </li> </ol>
110173-01	<p>RFGW entries added to ServiceGroup Map file are not created</p> <p>TSIDs and Frequencies for the RFGW QAM will not get published for SARA, Native iGuide, and COMCAST SDV if they are using the files on the DNCS.</p>
110173-02	<p>RFGW entries added to ServiceGroup Map file are not created</p> <p>TSIDs and Frequencies for the RFGW QAM will not get published for SARA, Native iGuide, and COMCAST SDV if they are using the files on the DNCS.</p>

ID #	Title & Description
110173-03	RFGW entries added to ServiceGroup Map file are not created  TSIDs and Frequencies for the RFGW QAM will not get published for SARA, Native iGuide, and COMCAST SDV if they are using the files on the DNCS.

# 5

## Customer Information

### If You Have Questions

If you have technical questions, call Cisco Services for assistance. Follow the menu options to speak with a service engineer.

Access your company's extranet site to view or order additional technical publications. For accessing instructions, contact the representative who handles your account. Check your extranet site often as the information is updated frequently.





Cisco Systems, Inc.  
5030 Sugarloaf Parkway, Box 465447  
Lawrenceville, GA 30042

678 277-1120  
800 722-2009  
[www.cisco.com](http://www.cisco.com)

This document includes various trademarks of Cisco Systems, Inc. Please see the Notices section of this document for a list of the Cisco Systems, Inc. trademarks used in this document.

Product and service availability are subject to change without notice.

© 2010, 2012 Cisco and/or its affiliates. All rights reserved.

April 2012 Printed in USA

Part Number 4036044 Rev B