

Release Notes for the Cisco WAP125 Wireless-AC/N Dual Band Desktop Access Point with PoE Firmware Version 1.0.0.7

Dec 2017

These release notes describe the known issues in the Cisco WAP125 Wireless-AC/N Dual Band Desktop Access Point with PoE firmware version 1.0.0.7.

Resolved Issues

The following issues have been fixed in firmware version 1.0.0.7

- CSCvf57823 - Security Vulnerability "Cross-Site Scripting" Attack
- CSCvf96820 - Key Re-installation attacks against WPA protocol

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/go/spsc
Cisco Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Products. No login is required.
Cisco Open Source Requests	www.cisco.com/go/smallbiz_opensource_request
Cisco Partner Central (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Product Documentation	
Cisco WAP125	www.cisco.com/go/100_wap_resources
Regulatory Compliance and Safety Information	www.cisco.com/c/dam/en/us/td/docs/wireless/access_point/csbap/wap125/RCSI/WAP125_ClassB_RCSI.pdf
Warranty Information	www.cisco.com/go/warranty

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2017 Cisco Systems, Inc. All rights reserved.