

Release Notes for the Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version 1.0.1.4

October 2015

These release notes describe the known issues in the Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points firmware version 1.0.1.4.

New Features

- LLDP
- Band Steering
- IGMP Snooping
- Cluster Plus (Single IP Management, Clustering Firmware Upgrade)

Fixed Issues

- Some characters of the cluster location are dropped when you set the Cluster Location settings through the Setup Wizard. (CSCur36577)
- The WDS bridge is established between two units in different channels. (CSCuq49207)
- The port status of the VLAN cannot return to its default status after the VLAN ID (except VLAN 1) is deleted. (CSCur51986)
- Away Timeout GUI issue. (CSCuu69519)

Release Notes

Known Issues

The following table lists the known issues in firmware version 1.0.1.4:

Ref Number	Description
CSCuv04511	The IGMP Packets/Data statistics always shows 0. Workaround None.

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html
Cisco Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Products. No login is required.
Cisco Open Source Requests	www.cisco.com/go/smallbiz_opensource_request
Cisco Partner Central (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Product Documentation	
Cisco WAP131 and WAP351	www.cisco.com/go/100_wap_resources www.cisco.com/go/300_wap_resources
Regulatory Compliance and Safety Information	www.cisco.com/en/US/docs/switches/lan/csb_switching_general/rcsi/Switch_ClassA_RCSI.pdf
Warranty Information	www.cisco.com/go/warranty

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2014 Cisco Systems, Inc. All rights reserved.