

# Release Notes for the Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version 1.0.2.2

## June 2016

These release notes describe the known issues in the Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points firmware version 1.0.2.2.

## New Features

- Added Japanese support and localized GUI
- Upgraded OpenSSL to 1.0.2d and added TLSv1.2 support

## Issues Resolved in 1.0.1.4 Release

- Some characters of the cluster location are dropped when you set the Cluster Location settings through the Setup Wizard. (CSCur36577)
- The WDS bridge is established between two units in different channels. (CSCuq49207)
- The port status of the VLAN cannot return to its default status after the VLAN ID (except VLAN 1) is deleted. (CSCur51986)
- Away Timeout GUI issue. (CSCuu69519)

## Release Notes

---

## Known Issues

The following table lists the known issues in firmware version 1.0.2.2:

Ref Number	Description
CSCuv04511	The IGMP Packets/Data statistics always shows 0. <b>Workaround</b> None.

## Related Information

Support	
Cisco Support Community	<a href="http://www.cisco.com/go/smallbizsupport">www.cisco.com/go/smallbizsupport</a>
Cisco Support and Resources	<a href="http://www.cisco.com/go/smallbizhelp">www.cisco.com/go/smallbizhelp</a>
Phone Support Contacts	<a href="http://www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html">www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html</a>
Cisco Firmware Downloads	<a href="http://www.cisco.com/go/smallbizfirmware">www.cisco.com/go/smallbizfirmware</a> Select a link to download firmware for Cisco Products. No login is required.
Cisco Open Source Requests	<a href="http://www.cisco.com/go/smallbiz_opensource_request">www.cisco.com/go/smallbiz_opensource_request</a>
Cisco Partner Central (Partner Login Required)	<a href="http://www.cisco.com/web/partners/sell/smb">www.cisco.com/web/partners/sell/smb</a>
Product Documentation	
Cisco WAP131 and WAP351	<a href="http://www.cisco.com/go/100_wap_resources">www.cisco.com/go/100_wap_resources</a> <a href="http://www.cisco.com/go/300_wap_resources">www.cisco.com/go/300_wap_resources</a>
Regulatory Compliance and Safety Information	<a href="http://www.cisco.com/en/US/docs/switches/lan/csb_switching_general/rcsi/Switch_ClassA_RCSI.pdf">www.cisco.com/en/US/docs/switches/lan/csb_switching_general/rcsi/Switch_ClassA_RCSI.pdf</a>
Warranty Information	<a href="http://www.cisco.com/go/warranty">www.cisco.com/go/warranty</a>

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2014 Cisco Systems, Inc. All rights reserved.