

Release Notes for the Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points Firmware Version 1.1.0.7

July 2017

These release notes describe the known issues in the Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points firmware version 1.1.0.7.

Resolved Issues

The following issue has been fixed in firmware version 1.1.0.7:

- CSCve57076 WAP150 - Security Vulnerability “Cross-Site Scripting Attack”.

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html
Cisco Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Products. No login is required.
Cisco Open Source Requests	www.cisco.com/go/smallbiz_opensource_request
Cisco Partner Central (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Product Documentation	
Cisco WAP131 and WAP351	www.cisco.com/go/100_wap_resources www.cisco.com/go/300_wap_resources
Regulatory Compliance and Safety Information	www.cisco.com/c/dam/en/us/td/docs/wireless/access_point/csbap/wap150_361/RCSI/WAP150_WAP361_ClassB_RCSI.pdf
Warranty Information	www.cisco.com/go/warranty

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2017 Cisco Systems, Inc. All rights reserved.