

Cisco WAP371 Wireless Access Points, Firmware Version 1.1.2.x

Version 1.1.2.x

January, 2015

These release notes describe the open issues for the Cisco WAP371 Wireless Access Points.

Requirements

- Your computer must meet the recommended hardware and software requirements.
- A computer with Browser support for:
 - Internet Explorer v7.0 or later
 - Chrome v5.0 or later
 - Firefox v3.0 or later
 - Safari v3.0 or later

New in This Release

- Added LED Display Feature with Scheduler
- Added Single IP Management and Cluster Firmware Upgrade Feature
- Added CLM implementation for -K and -R SKU

Resolved Issues

- CSCup48488: Power LED flashing even you set the static IPv6 address.

Release Notes

- CSCuo89292: Client cannot connect to the SSID after Enable/Disable Work Group Bridge
- CSCuq9394 1: When traffic on tagged VLAN the throughout (especially download) is very slow.

Open Caveats

These are the open caveats for firmware version 1.1.2.x

Table 1 Open Caveats in Firmware Version 1.1.2.x

Ref Number	Description
CSCui10930	Symptom: Configure excluded view cannot access all MIB tree. Workaround: None.
CSCuh42442	Symptom: When users assign a schedule profile to VAP, the schedule rule ONLY impacts the defined scope. Weekend refers to Sunday and Saturday and daily means every day. Workaround: None.
CSCui96092	Symptom: On latest builds user is able to configure SSID with all special characters. But on the networks help page, help content is not updated accordingly. Workaround: None.

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html
EU lot 26	For EU lot 26 related test result, please check this web page: www.cisco.com/go/eu-lot26-results
Cisco Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Products. No login is required.
Cisco Open Source Requests	www.cisco.com/go/smallbiz_opensource_request
Cisco Partner Central (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Product Documentation	
Cisco WAP551 and WAP561 Administration Guide	www.cisco.com/go/500_wap_resources
Cisco Power Adaptors	www.cisco.com/go/wap_accessories

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2015 Cisco Systems, Inc. All rights reserved.