

# Release Notes for the Cisco WAP581 Wireless-AC/N Dual Radio Access Point with 2.5GbE LAN Firmware Version 1.0.1.3

## Jul 2018

These release notes describe the known issues in the Cisco WAP581 Wireless-AC/N Dual Radio Access Point with 2.5GbE LAN firmware version 1.0.1.3.

## What's New

Mobile setup wizard

Website filtering using Cisco Umbrella

Packet capture with Cloudshark

Captive portal login with Windows Active Directory Domain Services (ADDS)

Captive portal login with Facebook and Google

## Limitations

The following are the limitations for WAP581, version 1.0.1.3

- CSCvj69001 - The **Captive Portal** page doesn't display when a wireless client tries to open HSTS website using a browser that supports HSTS. Workaround: Cisco recommends to try a no HSTS website in order to trigger the captive portal feature.

## Resolved Issues

The following issues have been fixed in firmware version 1.0.1.3

- CSCvj37948 - In the **Monitor->Single Point Setup** option, the channels and client data is not populated.
- CSCvg80186 - An error message is displayed while using **Single Point Setup** option.
- CSCvh81518 - Customer is experiencing issues with **Clustering** feature dropping.

## Related Information

Support	
Cisco Support Community	<a href="http://www.cisco.com/go/smallbizsupport">www.cisco.com/go/smallbizsupport</a>
Cisco Support and Resources	<a href="http://www.cisco.com/go/smallbizhelp">www.cisco.com/go/smallbizhelp</a>
Phone Support Contacts	<a href="http://www.cisco.com/go/sbsc">www.cisco.com/go/sbsc</a>
Cisco Firmware Downloads	<a href="http://www.cisco.com/go/smallbizfirmware">www.cisco.com/go/smallbizfirmware</a> Select a link to download firmware for Cisco Products. No login is required.
Cisco Open Source Requests	<a href="http://www.cisco.com/go/smallbiz_opensource_request">www.cisco.com/go/smallbiz_opensource_request</a>
Cisco Partner Central (Partner Login Required)	<a href="http://www.cisco.com/web/partners/sell/smb">www.cisco.com/web/partners/sell/smb</a>
Product Documentation	
Cisco WAP 581	<a href="http://www.cisco.com/go/500_wap_resources">www.cisco.com/go/500_wap_resources</a>
Regulatory Compliance and Safety Information	<a href="http://www.cisco.com/c/dam/en/us/td/docs/wireless/access_point/csbap/wap581/RCSI/WAP581_ClassB_RCSI.pdf">www.cisco.com/c/dam/en/us/td/docs/wireless/access_point/csbap/wap581/RCSI/WAP581_ClassB_RCSI.pdf</a>
Warranty Information	<a href="http://www.cisco.com/go/warranty">www.cisco.com/go/warranty</a>

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2018 Cisco Systems, Inc. All rights reserved.

## Release Notes

---