

# End-of-Sale and End-of-Life Announcement for the Cisco Industrial Asset Vision

## Contents

| Overview                  | 3  |
|---------------------------|----|
| End-of-life milestones    | 3  |
| Product Part Numbers      | 4  |
| Product migration options | 10 |
| For more information      | 11 |

#### Overview

#### EOL15357

Cisco announces the end-of-sale and end-of-life dates for the Cisco Industrial Asset Vision. The last day to order the affected product(s) is April 29, 2024. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

#### End-of-life milestones

Table 1. End-of-Life Milestones and Dates for the Cisco Industrial Asset Vision

| Milestone   | Definition  | Date           |
|---|---|----------------|
| End-of-Life<br>Announcement Date  | The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.   | March 29, 2024 |
| End-of-Sale Date:<br>HW,App SW  | The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.   | April 29, 2024 |
| Last Ship Date:<br>HW,App SW  | The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.   | July 28, 2024  |
| End of SW Maintenance<br>Releases Date:<br>HW,App SW  | The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.   | April 29, 2025 |
| End of<br>Vulnerability/Security<br>Support:<br>HW  | The last date that Cisco Engineering may release a planned maintenance release or scheduled software remedy for a security vulnerability issue.   | April 30, 2026 |
| End of Routine Failure<br>Analysis Date:<br>HW  | The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.  | April 29, 2025 |
| End of New Service Attachment Date: HW,App SW For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract. |   | April 29, 2025 |
| End of Service Contract  The last date to extend or renew a service contract for the product.  Renewal Date:  HW,App SW   |   | April 29, 2026 |
| Last Date of Support:<br>HW,App SW  | The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete. | April 30, 2026 |

HW = Hardware OS SW = Operating System Software

App. SW = Application Software

### **Product Part Numbers**

 Table 2.
 Product Part Numbers Affected by This Announcement

| End-of-Sale<br>Product Part<br>Number | Product Description   | Replacement Product<br>Part Number | Replacement Product Description                   | Additional Information |
|---------------------------------------|---|------------------------------------|---|------------------------|
| IOTAV-BUNDLE-<br>US                   | Cisco Industrial Asset<br>Vision Bundle- US                 | ACT-TPE-OCP                        | ATO PID for Actility TPE                          | -                      |
| IOTAV-BUNDLE-<br>US                   | Cisco Industrial Asset<br>Vision Bundle- US                 | ACT-TPE-SAAS                       | ATO PID for Actility TPE<br>SaaS                  | -                      |
| IOTAV-BUNDLE-<br>US                   | Cisco Industrial Asset<br>Vision Bundle- US                 | LORAWAN-CPF-LIC                    | LoRaWAN ATO PID for<br>Common Packet<br>Forwarder | -                      |
| IOTAV-BUNDLE-<br>EU                   | Cisco Industrial Asset<br>Vision Bundle- EU                 | ACT-TPE-OCP                        | ATO PID for Actility TPE                          | -                      |
| IOTAV-BUNDLE-<br>EU                   | Cisco Industrial Asset<br>Vision Bundle- EU                 | ACT-TPE-SAAS                       | ATO PID for Actility TPE<br>SaaS                  | -                      |
| IOTAV-BUNDLE-<br>EU                   | Cisco Industrial Asset<br>Vision Bundle- EU                 | LORAWAN-CPF-LIC                    | LoRaWAN ATO PID for<br>Common Packet<br>Forwarder | -                      |
| IOTAV-BUNDLE-<br>AU                   | Cisco Industrial Asset<br>Vision Bundle- AU                 | ACT-TPE-OCP                        | ATO PID for Actility TPE                          | -                      |
| IOTAV-BUNDLE-<br>AU                   | Cisco Industrial Asset<br>Vision Bundle- AU                 | ACT-TPE-SAAS                       | ATO PID for Actility TPE SaaS                     | -                      |
| IOTAV-BUNDLE-<br>AU                   | Cisco Industrial Asset<br>Vision Bundle- AU                 | LORAWAN-CPF-LIC                    | LoRaWAN ATO PID for<br>Common Packet<br>Forwarder | -                      |
| IOTAV-BUNDLE-<br>IN                   | Cisco Industrial Asset<br>Vision Bundle- IN                 | ACT-TPE-OCP                        | ATO PID for Actility TPE                          | -                      |
| IOTAV-BUNDLE-<br>IN                   | Cisco Industrial Asset<br>Vision Bundle- IN                 | ACT-TPE-SAAS                       | ATO PID for Actility TPE SaaS                     | -                      |
| IOTAV-BUNDLE-<br>IN                   | Cisco Industrial Asset<br>Vision Bundle- IN                 | LORAWAN-CPF-LIC                    | LoRaWAN ATO PID for<br>Common Packet<br>Forwarder | -                      |
| IOTAV-CLD                             | Cisco Industrial Asset<br>Vision Subscription               | ACT-TPE-OCP                        | ATO PID for Actility TPE                          | -                      |
| IOTAV-CLD                             | Cisco Industrial Asset<br>Vision Subscription               | ACT-TPE-SAAS                       | ATO PID for Actility TPE<br>SaaS                  | -                      |
| IOTAV-CLD                             | Cisco Industrial Asset<br>Vision Subscription               | LORAWAN-CPF-LIC                    | LoRaWAN ATO PID for<br>Common Packet<br>Forwarder | -                      |
| IOTAV-CLD-ESS                         | Cisco Industrial Asset<br>Vision Essentials<br>Subscription | ACT-TPE-OCP                        | ATO PID for Actility TPE                          | -                      |

| End-of-Sale<br>Product Part<br>Number | Product Description  | Replacement Product Part Number                                       | Replacement Product Description                   | Additional Information |
|---------------------------------------|--|---|---|------------------------|
| IOTAV-CLD-ESS                         | Cisco Industrial Asset<br>Vision Essentials<br>Subscription  | ACT-TPE-SAAS  | ATO PID for Actility TPE<br>SaaS                  | -                      |
| IOTAV-CLD-ESS                         | Cisco Industrial Asset<br>Vision Essentials<br>Subscription  | LORAWAN-CPF-LIC   | LoRaWAN ATO PID for<br>Common Packet<br>Forwarder | -                      |
| IOTOC-AV-IXM-<br>CPF                  | Cisco Industrial Asset<br>Vision - IXM CPF                   | ACT-TPE-OCP   | ATO PID for Actility TPE                          | -                      |
| IOTOC-AV-IXM-<br>CPF                  | Cisco Industrial Asset<br>Vision - IXM CPF                   | ACT-TPE-SAAS  | ATO PID for Actility TPE<br>SaaS                  | -                      |
| IOTOC-AV-IXM-<br>CPF                  | Cisco Industrial Asset<br>Vision - IXM CPF                   | LORAWAN-CPF-LIC   | LoRaWAN ATO PID for<br>Common Packet<br>Forwarder | -                      |
| IOTOC-<br>EDGEDEVMGR                  | Cisco Industrial Asset<br>Vision - Edge Device<br>Manager    | ACT-TPE-OCP   | ATO PID for Actility TPE                          | -                      |
| IOTOC-<br>EDGEDEVMGR                  | Cisco Industrial Asset<br>Vision - Edge Device<br>Manager    | ACT-TPE-SAAS  | ATO PID for Actility TPE<br>SaaS                  | -                      |
| IOTOC-<br>EDGEDEVMGR                  | Cisco Industrial Asset<br>Vision - Edge Device<br>Manager    | LORAWAN-CPF-LIC   | LoRaWAN ATO PID for<br>Common Packet<br>Forwarder | -                      |
| AV400-BRI-US                          | Cisco 900MHz<br>LoRaWAN Industrial<br>Sensor Bridge          | There is currently no replacement product available for this product. | -   | -                      |
| AV251-VIB-US                          | Cisco 900MHz<br>LoRaWAN Machine<br>Vibration Sensor          | There is currently no replacement product available for this product. | -   | -                      |
| IOTAV-L-PTM-I1-<br>US                 | Cisco 900MHz<br>LoRaWAN Product<br>Temperature Sensor        | There is currently no replacement product available for this product. | -   | -                      |
| IOTAV-L-FRZ-O1-<br>US                 | Cisco 900MHz<br>LoRaWAN Refrigerator<br>Temp/Humidity Sensor | There is currently no replacement product available for this product. | -   | -                      |
| IOTAV-L-OCU-I1-<br>US                 | Cisco 900MHz<br>LoRaWAN Indoor<br>Occupancy Sensor           | There is currently no replacement product available for this product. | -   | -                      |

| End-of-Sale<br>Product Part<br>Number | Product Description  | Replacement Product<br>Part Number                                    | Replacement Product Description | Additional Information |
|---------------------------------------|--|---|---------------------------------|------------------------|
| IOTAV-L-ENV-<br>01-US                 | Cisco 900MHz<br>LoRaWAN Outdoor<br>Temp/Humidity Sensor      | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-MTM-<br>01-US                 | Cisco 900MHz<br>LoRaWAN Machine<br>Temperature Sensor        | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-WLK-<br>01-US                 | Cisco 900MHz<br>LoRaWAN Water Leak<br>Sensor                 | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-LUX-I1-<br>US                 | Cisco 900MHz<br>LoRaWAN Light Level<br>Sensor                | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-GPS-L1-<br>US                 | Cisco 900MHz<br>LoRaWAN Outdoor GPS<br>Sensor                | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-HAL-I1-<br>US                 | Cisco 900MHz<br>LoRaWAN<br>Door/Window Sensor                | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-ENV-I1-<br>US                 | Cisco 900MHz<br>LoRaWAN Indoor<br>Temp/Humidity Sensor       | There is currently no replacement product available for this product. | -                               | -                      |
| AV400-BRI-EU                          | Cisco 800MHz<br>LoRaWAN Industrial<br>Sensor Bridge          | There is currently no replacement product available for this product. | -                               | -                      |
| AV251-VIB-EU                          | Cisco 800MHz<br>LoRaWAN Machine<br>Vibration Sensor          | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-PTM-I1-<br>EU                 | Cisco 800MHz<br>LoRaWAN Product<br>Temperature Sensor        | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-FRZ-O1-<br>EU                 | Cisco 800MHz<br>LoRaWAN Refrigerator<br>Temp/Humidity Sensor | There is currently no replacement product available for this product. | -                               | -                      |

| End-of-Sale<br>Product Part<br>Number | Product Description                                     | Replacement Product Part Number                                       | Replacement Product Description | Additional Information |
|---------------------------------------|---|---|---------------------------------|------------------------|
| IOTAV-L-OCU-I1-<br>EU                 | Cisco 800MHz<br>LoRaWAN Indoor<br>Occupancy Sensor      | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-ENV-<br>O1-EU                 | Cisco 800MHz<br>LoRaWAN Outdoor<br>Temp/Humidity Sensor | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-MTM-<br>O1-EU                 | Cisco 800MHz<br>LoRaWAN Machine<br>Temperature Sensor   | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-WLK-<br>O1-EU                 | Cisco 800MHz<br>LoRaWAN Water Leak<br>Sensor            | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-LUX-I1-<br>EU                 | Cisco 800MHz<br>LoRaWAN Light Level<br>Sensor           | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-GPS-L1-<br>EU                 | Cisco 800MHz<br>LoRaWAN Outdoor GPS<br>Sensor           | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-HAL-I1-<br>EU                 | Cisco 800MHz<br>LoRaWAN<br>Door/Window Sensor           | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-ENV-I1-<br>EU                 | Cisco 800MHz<br>LoRaWAN Indoor<br>Temp/Humidity Sensor  | There is currently no replacement product available for this product. | -                               | -                      |
| AV400-BRI-AU                          | Cisco 915MHz<br>LoRaWAN Industrial<br>Sensor Bridge     | There is currently no replacement product available for this product. | -                               | -                      |
| AV251-VIB-AU                          | Cisco 915MHz<br>LoRaWAN Machine<br>Vibration Sensor     | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-PTM-I1-<br>AU                 | Cisco 915MHz<br>LoRaWAN Product<br>Temperature Sensor   | There is currently no replacement product available for this product. | -                               | -                      |

| End-of-Sale<br>Product Part<br>Number | Product Description  | Replacement Product<br>Part Number                                    | Replacement Product Description | Additional Information |
|---------------------------------------|--|---|---------------------------------|------------------------|
| IOTAV-L-FRZ-O1-<br>AU                 | Cisco 915MHz<br>LoRaWAN Refrigerator<br>Temp/Humidity Sensor | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-OCU-I1-<br>AU                 | Cisco 915MHz<br>LoRaWAN Indoor<br>Occupancy Sensor           | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-ENV-<br>O1-AU                 | Cisco 915MHz<br>LoRaWAN Outdoor<br>Temp/Humidity Sensor      | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-MTM-<br>O1-AU                 | Cisco 915MHz<br>LoRaWAN Machine<br>Temperature Sensor        | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-WLK-<br>O1-AU                 | Cisco 915MHz<br>LoRaWAN Water Leak<br>Sensor                 | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-LUX-I1-<br>AU                 | Cisco 915MHz<br>LoRaWAN Light Level<br>Sensor                | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-GPS-L1-<br>AU                 | Cisco 915MHz<br>LoRaWAN Outdoor GPS<br>Sensor                | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-HAL-I1-<br>AU                 | Cisco 915MHz<br>LoRaWAN<br>Door/Window Sensor                | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-ENV-I1-<br>AU                 | Cisco 915MHz<br>LoRaWAN Indoor<br>Temp/Humidity Sensor       | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-PTM-I1-<br>IN                 | Cisco 865MHz<br>LoRaWAN Product<br>Temperature Sensor        | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-FRZ-O1-<br>IN                 | Cisco 865MHz<br>LoRaWAN Refrigerator<br>Temp/Humidity Sensor | There is currently no replacement product available for this product. | -                               | -                      |

| End-of-Sale<br>Product Part<br>Number | Product Description                                     | Replacement Product<br>Part Number                                    | Replacement Product Description | Additional Information |
|---------------------------------------|---|---|---------------------------------|------------------------|
| IOTAV-L-OCU-I1-<br>IN                 | Cisco 865MHz<br>LoRaWAN Indoor<br>Occupancy Sensor      | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-ENV-<br>O1-IN                 | Cisco 865MHz<br>LoRaWAN Outdoor<br>Temp/Humidity Sensor | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-MTM-<br>O1-IN                 | Cisco 865MHz<br>LoRaWAN Machine<br>Temperature Sensor   | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-WLK-<br>O1-IN                 | Cisco 865MHz<br>LoRaWAN Water Leak<br>Sensor            | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-LUX-I1-<br>IN                 | Cisco 865MHz<br>LoRaWAN Light Level<br>Sensor           | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-GPS-L1-<br>IN                 | Cisco 865MHz<br>LoRaWAN Outdoor GPS<br>Sensor           | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-HAL-I1-<br>IN                 | Cisco 865MHz<br>LoRaWAN<br>Door/Window Sensor           | There is currently no replacement product available for this product. | -                               | -                      |
| IOTAV-L-ENV-I1-<br>IN                 | Cisco 865MHz<br>LoRaWAN Indoor<br>Temp/Humidity Sensor  | There is currently no replacement product available for this product. | -                               | -                      |
| AV251-MB=                             | AV251 Metal Base  | There is currently no replacement product available for this product. | -                               | -                      |
| AV251-MB                              | AV251 Metal Base  | There is currently no replacement product available for this product. | -                               | -                      |
| AV251-MGTB=                           | AV251 Magnetic Base                                     | There is currently no replacement product available for this product. | -                               | -                      |

| End-of-Sale<br>Product Part<br>Number | Product Description | Replacement Product<br>Part Number                                    | Replacement Product Description | Additional Information |
|---------------------------------------|---------------------|---|---------------------------------|------------------------|
| AV251-MGTB                            | AV251 Magnetic Base | There is currently no replacement product available for this product. | -                               | -                      |

#### Product migration options

Cisco Industrial Asset Vision customers will transition to Actility network server sold through Cisco price list (ACT-TPE-OCP, ACT-TPE-SAAS) or 3rd party network server leveraging Cisco Common Packet Forwarder (LORAWAN-CPF-LIC). Cisco will continue to provide LoRaWAN gateways and will work with the growing ecosystem of sensor manufacturers to address customer use cases.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at:

https://www.cisco.com/web/partners/incentives and promotions/tmp.html.

Customers may be able to continue to purchase the Cisco Industrial Asset Vision through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <a href="https://www.cisco.com/go/eos">https://www.cisco.com/go/eos</a>.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

https://www.cisco.com/web/about/ac227/ac228/ac231/about\_cisco\_takeback\_recycling.html.

#### For more information

For more information about the Cisco End-of-Life Policy, go to: <a href="https://www.cisco.com/c/en/us/products/eos-eol-policy.html">https://www.cisco.com/c/en/us/products/eos-eol-policy.html</a>.

For more information about the Cisco Product Warranties, go to: <a href="https://www.cisco.com/c/en/us/products/warranty-listing.html">https://www.cisco.com/c/en/us/products/warranty-listing.html</a>.

To subscribe to receive end-of-life/end-of-sale information, go to: <a href="https://cway.cisco.com/mynotifications">https://cway.cisco.com/mynotifications</a>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore **Europe Headquarters**Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at https://www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: https://www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA 03/24