



## END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO IP PHONE 7905 IN FAVOR OF THE CISCO IP PHONE 7905G

Cisco Systems announces the end of life of the Cisco IP Phone 7905 in favor of the Cisco IP Phone 7905G. The last day to order the Cisco IP Phone 7905 is August 8, 2003. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until August 8, 2005.

Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco 7905 IP Phone.

Customers are encouraged to migrate to the Cisco IP Phone 7905G, which has all the capabilities of the Cisco IP Phone 7905 as well as support for inline power and integration with CallManager version 3.3. You can find more information about this product at:

<http://www.cisco.com/en/US/products/hw/phones/ps379/ps1851/index.html>

**Table 1.** End-of-Life Milestones and Dates for the Cisco IP Phone 7905

Milestone	Definition	Date
End-of-Life Announcement Date	The document date of the end-of-sale and end-of-life announcement of a product to the general public.	July 8, 2003
End of Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale.	August 8, 2003
Last Shipment Date	The last possible date product shipment can be deferred to.	November 8, 2003
End of Software Maintenance Releases Date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	August 8, 2004
End of Routine Failure Analysis Date	The last possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	August 8, 2004
End of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	August 8, 2004
End of Service Contract Renewal Date	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	August 8, 2004
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	August 8, 2005

**Table 2.** Product Part Numbers Being Affected

End-of-Sales Product Part Number	Product Description
CP-7905	Cisco IP Phone 7905
CP-7905=	Cisco IP Phone 7905 spare
CP-7905-CORD-NA	7905 Series Power Cord, North America
CP-7905-CORD-CE	7905 Series Power Cord, Central Europe
CP-7905-CORD-UK	7905 Series Power Cord, United Kingdom

### PRODUCT MIGRATION OPTIONS

Table 3 provides relevant information for migrating from the Cisco IP Phone 7905 to the IP Phone 7905G, the recommended replacement product.

**Table 3.** Product Comparisons

	Cisco IP Phone 7905	Cisco IP Phone 7905G
Hardware List Price	\$195	\$165
H.323 v2 Support (via SW-SMH-UL-7905 Configuration Option)	Yes	Yes
Integrated Inline Power	No	Yes
CallManager 3.3 Integration Using SCCP Protocol (via SW-CCM-UL-7905 Configuration Option)	No	Yes
Local Power Supply Based on 5 volts. Included with the phone.	Yes	No
Local Power Supply Based on 48 volts. (same as other Cisco IP Phones). Must be ordered separately.	No	Yes

Table 4 provides information about different replacement options available to customers who had purchased the Cisco IP Phone 7905.

**Table 4.** Product Replacement Options

	End-of-Sales Product Part Number	Replacement Parts
Customer Intending to Use Inline Power	CP-7905	CP-7905G
	CP-7905=	CP-7905G
Customer Intending to Use Local Power	CP-7905	CP-7905G
	CP-7905-CORD-NA	CP-PWR-CUBE CP-PWR-CORD-NA
	CP-7905	CP-7905G
	CP-7905-CORD-CE	CP-PWR-CUBE CP-PWR-CORD-CE
	CP-7905	CP-7905G
	CP-7905-CORD-UK	CP-PWR-CUBE CP-PWR-CORD-UK
	CP-7905=	CP-7905G
	CP-7905-CORD-NA	CP-PWR-CUBE CP-PWR-CORD-NA
Customer Intending to Use Local Power	CP-7905=	CP-7905G
	CP-7905-CORD-UK	CP-PWR-CUBE CP-PWR-CORD-UK
Customer Intending to Use Local Power	CP-7905=	CP-7905G
	CP-7905-CORD-CE	CP-PWR-CUBE CP-PWR-CORD-CE

**ADDITIONAL INFORMATION**

For more information about Cisco products, please contact your Cisco account manager and/or Cisco Channel Partner.

For more information about the Cisco End-of-Life Policy, go to: [http://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](http://www.cisco.com/en/US/products/products_end-of-life_policy.html)

**Corporate Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

**European Headquarters**

Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

**Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

**Asia Pacific Headquarters**

Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel  
Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal  
Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan  
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright 2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, *Packer*, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) 205330.BO\_ETMG\_JQ\_8.05

