

## End-of-Sale and End-of-Life Announcement for the Cisco Digital Media System Version 4.0

EOL6242

Cisco® announces the end-of-sale and end-of life dates for the Cisco Digital Media System Version 4.0. The last day to order the affected product(s) is May 30, 2008. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

**Table 1.** End-of-Life Milestones and Dates for the Cisco Digital Media System Version 4.0

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	November 30, 2007
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 30, 2008
<b>Last Ship Date: App. SW, HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	August 28, 2008
<b>End of SW Maintenance Releases Date: App. SW</b>	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	May 30, 2009
<b>End of Routine Failure Analysis Date: HW</b>	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	May 30, 2009
<b>End of New Service Attachment Date: App. SW, HW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	May 30, 2009
<b>End of Service Contract Renewal Date: HW</b>	The last date to extend or renew a service contract for the product.	August 25, 2012
<b>End of Service Contract Renewal Date: App. SW</b>	The last date to extend or renew a service contract for the product.	August 26, 2010
<b>Last Date of Support: HW</b>	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	May 29, 2013
<b>Last Date of Support: App. SW</b>	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	May 30, 2011

HW = Hardware OS SW = Operating System Software App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
<b>DMM4.0-BASE-K9</b>	Digital Media Mgr Base V4.0 Perptl SW Li	DMM4.1-BASE-K9	Digital Media Mgr Base V4.1 Perptl SW Lic.
<b>DMM4.0-DSM1.0-K9</b>	DMM V4.0 Dig. Signage Module 1.0 Perptl. SW Lic.	DMM-DSM1.1-K9	DMM Digital Signage Module V1.1 Perptl. SW Lic.
<b>DMM4.0-DSM1.0-K9=</b>	DMM V4.0 Dig. Signage Module 1.0 Perptl. SW Lic., Spare	DMM-DSM1.1-K9=	DMM Digital Signage Module V1.1 Perptl. SW Lic., Spare
<b>DMM4.0-VPM4.0-K9</b>	DMM V4.0 Video Portal Module 4.0 Perptl. SW Lic.	DMM-VPM4.1-K9	DMM Video Portal Module V4.1 Perptl. SW Lic.
<b>DMM4.0-VPM4.0-K9=</b>	DMM V4.0 Video Portal Module 4.0 Perptl. SW Lic., Spare	DMM-VPM4.1-K9=	DMM Video Portal Module V4.1 Perptl. SW Lic., Spare
<b>MCS-7825-H2-DM21</b>	HW Only MCS-7825-H2 w/ 2GB RAM and Two 80GB HD	MCS-7825H3-K9-VP4	HW Only MCS-7825-H3 with 2GB RAM and Two 160GB SATA HD
<b>MCS-7825-H2-DM21=</b>	HW Only MCS-7825-H2 w/ 2GB RAM and 80GB HD	MCS-7825H3-DMS1=	HW Only MCS-7825-H3 w/ 2GB RAM, Two 160GB SATA HD, Spare
<b>MCS-7835H2-DMM-K9</b>	HW Only MCS-7835-H2 with 2GB RAM and Two 72GB SAS H	MCS-7835H2-K9-DMM4	HW Only MCS-7835-H2 with 2GB RAM and Two 72GB SAS HD
<b>MCS-7835H2-VP-K9</b>	HW Only MCS-7835-H2 with 2GB RAM and Two 72GB SAS H	MCS-7835H2-K9-VP4	HW Only MCS-7835-H2 with 2GB RAM and Two 72GB SAS HD
<b>VP4.0-1000-K9</b>	Cisco Video Portal V4.0 Perptl. SW Lic. For 1,000 Concurrent	VP4.1-1000-K9	Cisco Video Portal V4.1 Perptl. SW Lic. For 1,000 Concurrent
<b>VP4.0-7825-H2-K9</b>	Cisco Video Portal V4.0 Perptl. SW Lic. for MCS-7825-H2	VP4.1-500-K9	Cisco Video Portal V4.1 Perptl. SW Lic. For 500 Concurrent
<b>VPR4.0-K9</b>	Cisco Video Portal Reports V4.0 Perptl. SW Lic.	VPR4.1-K9	Cisco Video Portal Reports V4.1 Perptl. SW Lic.

## Product Migration Options

Customers are encouraged to migrate to Cisco Digital Media Manager 4.1. Information about this product can be found at: <http://www.cisco.com/en/US/products/ps6681/index.html>. There is no cost to perform the upgrade from version 4.0 to version 4.1.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through the Cisco Certified Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to: <http://cisco.com/go/remarketing>.

## For More Information

For more information about the Cisco Digital Media System Version 4.1, visit: <http://www.cisco.com/en/US/products/ps6681/index.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: [http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html).

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



**Americas Headquarters**  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
[www.cisco.com](http://www.cisco.com)  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 527-0883

**Asia Pacific Headquarters**  
Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
[www.cisco.com](http://www.cisco.com)  
Tel: +65 6317 7777  
Fax: +65 6317 7799

**Europe Headquarters**  
Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
[www-europe.cisco.com](http://www-europe.cisco.com)  
Tel: +31 0 800 020 0791  
Fax: +31 0 20 357 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

©2007 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networking Academy, Network Registrar, PIX, ProConnect, ScriptShare, SMARtNet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0708R)