



End-of-Sale and End-of-Life Announcement for the Cisco Catalyst Inline Power Patch Panel

Cisco Systems® announces the end-of-sale and end-of-life dates for the Cisco® Catalyst® Inline Power Patch Panel. The last day to order the affected product is May 25, 2006. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until May 25, 2011.

Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement.

Customers are encouraged to migrate to one of our Cisco Technology Developer Partner Program members, PowerDsine, and their PowerDsine 6548 or PowerDsine 6024G, both of which provide support for the new IEEE 802.3af and Cisco prestandard power schemes. Information about the replacement product can be found at: <http://www.powerdsine.com>. Tables 3 and 4 provide the relevant information for migrating to the replacement products.

Table 1. End-of-Life Milestones and Dates for the Cisco Inline Power Patch Panel

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	November 25, 2005
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 25, 2006
Last Shipment Date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	June 15, 2006
End of Software Maintenance Releases Date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	May 25, 2007
End of Routine Failure Analysis Date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	May 25, 2007
End of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	May 25, 2007
End of Service Contract Renewal Date	The last date to extend or renew a service contract for the product.	November 25, 2010
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	May 25, 2011

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Product Part Number of PowerDsine Company	Replacement Product Description
WS-PWR-PANEL	Catalyst Inline Power Patch Panel	PowerDsine 6548	High Density, Condensed 48-port Power over Ethernet Midspan
WS-PWR-PANEL	Catalyst Inline Power Patch Panel	or PowerDsine 6024G	Power over Gigabit Ethernet Midspan

PRODUCT MIGRATION OPTIONS

For customers who have Ethernet switches without in-line Power over Ethernet (PoE), several replacement options are recommended. The customers can use Power Cube 3 used (available from Cisco) or purchase a closet line power supply from PowerDsine.

The recommended replacements for the Cisco Catalyst Inline Power Patch Panel are produced by one our Cisco Technology Developer Partner Program members, PowerDsine, and its PowerDsine 6548 or PowerDsine 6024G (Tables 3 and 4). As another option, the Cisco IP Phone Power Cube 3 can also be used by plugging into a commercial power outlet located near the IP phone. However, the Cisco IP Phone Power Cube 3 can power only one IP phone. The PowerDsine 6548 provides 48 ports of IEEE 802.3af or Cisco prestandard power for powering up to 48 each 10/100BASE-T IP phones. The PowerDsine 6024 provides 24 ports of IEEE 802.3af power for powering up to 24 10/100/1000BASE-T IP phones.

Table 3. Product Comparisons 48 Ports of Cisco Prestandard PoE

Feature	Cisco Catalyst Inline Power Patch Panel	PowerDsine 6548
Support for 10/100BASE-T IP Phones	Yes	Yes
48 Ports of Cisco Prestandard PoE	Yes	Yes
Support for IEEE 802.3af PoE	No	Yes
Support for Powering Gigabit Ethernet (1000BASE-T) IP Phones	No	No

Table 4. Product Comparisons

Feature	Cisco Catalyst Inline Power Patch Panel	PowerDsine 6024
Support for 10/100/1000BASE-T IP Phones	No, 10/100BASE-T only	Yes
24 Ports of Cisco Prestandard PoE	Yes (48)	Yes (24)
Support for IEEE 802.3af PoE	No	Yes

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information, visit <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires a Cisco.com user ID to log on.

Customers may be able to continue to purchase the end-of-sale product through the Cisco Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, visit: http://www.cisco.com/en/US/ordering/or6/or17/order_refurbished_equipment_program_description.html

FOR MORE INFORMATION

For more information about the Cisco Catalyst Inline Power Patch Panel, visit

<http://www.cisco.com/en/US/products/hw/modules/ps2797/ps740/index.html> or contact your local account representative.

For more information about the Cisco End-of-Life Policy, visit: http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, visit: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel
Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal
Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) 205574.B_ETMG_IQ_12.05

