



END-OF-LIFE NOTICE, NO. 827

# END-OF-SALE FOR TOKEN RING ADAPTERS

## INTRODUCTION

Cisco Systems® is announcing the End-of-Sale of two Token Ring port adapters: PA-4R and PA-4R-FDX. These products are being replaced by the new Dedicated Token Ring Port Adapter (PA-4R-DTR), which provides more functionality and higher throughput capability.

## DISCONTINUED PRODUCTS

Table 1 lists the discontinued products and their replacements.

**Table 1.** Discontinued Products

Existing Product Number	Description	Replacement Product Number
PA-4R(=)	4-port Token Ring Port Adapter	PA-4R-DTR(=)
PA-4R-FDX(=)	4-port Full-Duplex Token Ring Port Adapter	PA-4R-DTR(=)

The End-of-Sale Date is July 30, 1999, and the Last Ship Date is August 30, 1999.

## REPLACEMENT PRODUCT INFORMATION


The port adapters being discontinued have been available for more than two years and utilize electronic components that soon will no longer be available. As a result, Cisco has developed a replacement for these port adapters that uses newer technology components. The new Dedicated Token Ring Port Adapter (PA-4R-DTR) can replace either of the discontinued port adapters in most installations. The PA-4R-DTR Port Adapter, which is currently shipping, is the preferred choice for several reasons:

- It has a lower purchase price than the End-of-Sale adapters.
- It has a higher packet throughput capability.
- It has more functionality (for example, IEEE 802.5r concentrator port capability).
- It uses new, improved technology.

The PA-4R-DTR Port Adapter is supported in Cisco IOS® Software Releases 11.1CA, 11.1CC, 11.3T, 12.0, and later (see [Table E:\Carolyn Work\LWI.COM\CISVS-8343 CDO EOL PB Refresh\ orig\827 PP.htm - 35283](E:\Carolyn Work\LWI.COM\CISVS-8343 CDO EOL PB Refresh\ orig\827 PP.htm - 35283) for specific maintenance releases where support begins). The PA-4R-DTR Port Adapter is not currently supported in Cisco IOS Release 11.2 or in Cisco IOS Release 11.1 Mainline and earlier releases.

**Table 2.** Cisco IOS Release Support

Product	IOS Release Where Supported
PA-4R-DTR(=)	Release 11.1(20)CA1, 11.1(22)CC, 11.3(6)T, and 12.0(1)
PA-4R(=)	Release 11.1, 11.1CA, 11.2, 11.2P, 11.3, 11.3T, and 12.0
PA-4R-FDX(=)	Release 11.1CA, 11.2P, 11.3, 11.3T, and 12.0



Whenever possible, customers should select the PA-4R-DTR Port Adapter for their Token Ring connectivity on Cisco 7200 and Cisco 7500 Series routers. However, Cisco understands that some customers may have requirements to continue using one of the older adapters. For example, customers may require an older adapter if they have begun a rollout plan and have standardized on a Cisco IOS release that does not support the PA-4R-DTR. Customers planning on a new rollout of Token Ring port adapters should choose the PA-4R-DTR with an appropriate software release. If this is not possible, the rollout should plan to conclude prior to July 30, 1999. Beyond this date, Cisco cannot guarantee availability of the discontinued products.

## **SUPPORT PROGRAMS**

End-of-Sale refers to the time when certain products are no longer available for new purchases. It does not apply to the service and support programs for those products. Cisco will continue to support the Token Ring port adapters after End-of-Sale through its SMARTnet<sup>®</sup> and Comprehensive Maintenance programs. Customers with either of these service contracts are entitled to free software updates, 24-hour phone support through the Technical Assistance Center (TAC), and advance replacement hardware for repairs. Comprehensive Maintenance customers also receive onsite service. To meet specific requirements, customers who do not have a maintenance contract can purchase software updates and hardware repair services rather than full-service coverage. Cisco is committed to providing software support for a minimum of two years and providing hardware support for five years after the End-of-Sale date.



#### **Corporate Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

#### **European Headquarters**

Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

#### **Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

#### **Asia Pacific Headquarters**

Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica  
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR  
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico  
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia  
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan  
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CDDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) VS/LW8343 04/05

