


# Consolidation on Copper and Dual-Fiber Small Form-Factor Pluggable Modules

PB681353

Transceiver Module Group is implementing a consolidation on select Gigabit Ethernet Small Form-Factor Pluggable (SFP) modules.

**Figure 1.** Gigabit Ethernet SFP Modules



The following table shows the Product IDs involved on this consolidation.

**Table 1.** Product ID Consolidation

Legacy Product ID		New Product ID	New Product ID Target First Customer Ship Date
GLC-SX-MM	SFP-GE-S	GLC-SX-MMD	August 2011
GLC-LH-SM	SFP-GE-L	GLC-LH-SMD	August 2011
GLC-ZX-SM	SFP-GE-Z	GLC-ZX-SMD	January 2013
GLC-T	SFP-GE-T	GLC-TE	TBD

## Legacy SFP Modules End of Sale

Legacy SFP modules and new SFP modules will coexist for a maximum period of 12-18 months; then legacy SFP modules will be end of sale.

**Table 2.** Target EoS Date for Legacy SFP Modules

Legacy Product ID	Target EoS date
<b>GLC-SX-MM</b>	March 2013
<b>SFP-GE-S</b>	March 2013
<b>GLC-LH-SM</b>	March 2013
<b>SFP-GE-L</b>	March 2013
<b>GLC-ZX-SM</b>	October 2013
<b>SFP-GE-Z</b>	October 2013
<b>GLC-T</b>	TBD
<b>SFP-GE-T</b>	TBD

---

### SFP features on new Product IDs:

- Backward compatible
- Digital Optical Monitoring
- UDI compliant
- PbFree
- Extended temperature range of operation (-5°C to 85 °C)

### For More Information

Legacy SFP modules end of sale

[http://www.cisco.com/en/US/products/hw/modules/ps5455/prod\\_eol\\_notices\\_list.html](http://www.cisco.com/en/US/products/hw/modules/ps5455/prod_eol_notices_list.html)

Product ID consolidation on SFP modules presentation

<http://www.in.cisco.com/dss/csstg/tmg/gbicsfp/index.shtml> (only Cisco internal)

[http://www.cisco.com/en/US/products/hw/modules/ps5455/prod\\_presentation\\_list.html](http://www.cisco.com/en/US/products/hw/modules/ps5455/prod_presentation_list.html)

New Product ID SFP modules datasheet

[http://www.cisco.com/en/US/prod/collateral/modules/ps5455/ps6577/product\\_data\\_sheet0900aecd8033f885.html](http://www.cisco.com/en/US/prod/collateral/modules/ps5455/ps6577/product_data_sheet0900aecd8033f885.html)

Compatibility information

[http://www.cisco.com/en/US/docs/interfaces\\_modules/transceiver\\_modules/compatibility/matrix/OL\\_6981.pdf](http://www.cisco.com/en/US/docs/interfaces_modules/transceiver_modules/compatibility/matrix/OL_6981.pdf)

[http://www.cisco.com/en/US/docs/interfaces\\_modules/transceiver\\_modules/compatibility/matrix/OL\\_8031.pdf](http://www.cisco.com/en/US/docs/interfaces_modules/transceiver_modules/compatibility/matrix/OL_8031.pdf)

Installation guides

[http://www.cisco.com/en/US/products/hw/modules/ps5455/prod\\_installation\\_guides\\_list.html](http://www.cisco.com/en/US/products/hw/modules/ps5455/prod_installation_guides_list.html)

For general information on Cisco transceiver modules

[http://www.cisco.com/en/US/products/hw/modules/ps5455/prod\\_module\\_series\\_home.html](http://www.cisco.com/en/US/products/hw/modules/ps5455/prod_module_series_home.html)



---

Americas Headquarters  
Cisco Systems, Inc.  
San Jose, CA

Asia Pacific Headquarters  
Cisco Systems (USA) Pte. Ltd.  
Singapore

Europe Headquarters  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)