

Cisco IOS X Software Release 12.2(37)EY for Cisco Catalyst 2960 Switches with LAN Lite Software

PB423860

Overview

Cisco® is announcing Cisco IOS® Software for the new Cisco Catalyst® 2960 Series Switches with LAN Lite Software. The Cisco Catalyst 2960 LAN Lite Switches are fixed-configuration standalone devices that provide Fast Ethernet connectivity for entry-level small branch office and campus wiring closet deployments. The Cisco Catalyst 2960 LAN Lite Switches reduce the network total cost of ownership by simplifying network configuration and maintenance with scalable management and troubleshooting.


The Cisco Catalyst 2960 LAN Lite Switches comprise the following:

Product Name	Part Number	Description
Cisco Catalyst 2960-24-S	(WS-C2960-24-S)	24 10/100 ports
Cisco Catalyst 2960-24TC-S	(WS-C2960-24TC-S)	24 10/100 ports + 2 10/100/1000 or SFP ports
Cisco Catalyst 2960-48TC-S	(WS-C2960-48TC-S)	48 10/100 ports + 2 10/100/1000 or SFP ports

This product bulletin describes the content and delivery information about Cisco IOS Software Release 12.2(37)EY, which is the first Cisco IOS Software release that provides support for the Cisco Catalyst 2960 LAN Lite Switches. Release 12.2(37)EY is an early deployment (ED) release based on Cisco IOS Software Release 12.2(37)SE. Cisco IOS Software Release 12.2(37)EY should not be used for any switch other than the Cisco Catalyst 2960 LAN Lite Switches.

The platform and features delivered with this ED release will be incorporated into Cisco IOS Software Release 12.2(44)SE and subsequent Cisco IOS Software 12.2SE releases. It is important to note that there are no planned maintenance releases for this ED release. In addition, please note the migration path to the latest 12.2SE release (Figure 1). Customers should prepare to upgrade using this migration path.

Figure 1. Cisco IOS Software Release 12.2(37)EY Train and Migration Guide



New Features in Cisco IOS Software Release 12.2(37)EY

This release contains all the features found in the LAN Lite Image feature set of Cisco IOS Software Release 12.2(37)SE.

Products supported with this release include the following:

- Cisco Catalyst 2960-24-S
- Cisco Catalyst 2960-24TC-S
- Cisco Catalyst 2960-48TC-S

Information about the Cisco Catalyst 2960 Series is available at <http://www.cisco.com/go/catalyst2960>.

For more detailed information about the platforms and features being delivered in Cisco IOS Software Release 12.2(37)EY, please reference the release notes at <http://www.cisco.com/univercd/cc/td/doc/product/lan/cat2960/index.htm>.

Support

Cisco IOS Software Release 12.2(37)EY follows the standard Cisco support policy as indicated at http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

Download Information

Customers can download Cisco IOS Software Release 12.2(37)EY from the Software Download Center at <http://www.cisco.com/public/sw-center/>.



Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Europe Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: +31 0 800 020 0791
Fax: +31 0 20 357 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

©2007 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSF, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networking Academy, Network Registrar, PIX, ProConnect, ScriptShare, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0708R)