



PRODUCT BULLETIN NO. [EOL4224](#)

END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE [SELECT CISCO 15454 HW](#)

Cisco Systems® announces the end-of-sale and end-of life dates for the [Select Cisco 15454 HW](#). The last day to order the affected product is [August 17, 2001](#). Customers with active service contracts will continue to receive support from the [Cisco Technical Assistance Center](#) until [August 16, 2006](#). Table 1 describes the end-of-life milestones, definitions, and dates for the [Select Cisco 15454 HW](#). Table 2 lists the product part numbers affected by this announcement.

Table 1. End-of-Life Milestones and Dates for the [Select Cisco 15454 HW](#).

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	February 18, 2001
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	August 17, 2001
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	February 17, 2006
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	August 16, 2006

HW = Hardware OS SW = Operating System Software App SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
15454-DS1N-14-W=	DS1, 1:N, DSX, 14 Ckt.
15454-OC48E31.90W=	OC48, ELR, 1531.90, 200GHz, 1 Ckt., SC
15454-OC48E33.47W=	OC48, ELR, 1533.47, 200GHz, 1 Ckt., SC
15454-OC48E35.04W=	OC48, ELR, 1535.04, 200GHz, 1 Ckt., SC
15454-OC48E36.61W=	OC48, ELR, 1536.61, 200GHz, 1 Ckt., SC
15454-OC48E38.19W=	OC48, ELR, 1538.19, 200GHz, 1 Ckt., SC
15454-OC48E39.77W=	OC48, ELR, 1539.77, 200GHz, 1 Ckt., SC
15454-OC48E42.94W=	OC48, ELR, 1542.94, 200GHz, 1 Ckt., SC
15454-OC48E52.52W=	OC48, ELR, 1552.52, 200GHz, 1 Ckt., SC
15454-TCC+U/G-PKG	TCC+ Upgrd Pkg., Incl. 2 Qty. TCC+ and 2.2.1 SW
15454-TCC+WCTM	VOL PK TCC+10 W/CTM (5 ntwrk element and 5 client licenses)
15454-TCC=	Timing Communications Control

PRODUCT MIGRATION OPTIONS

Contact [Cisco TAC](#) or [Account Manager](#) for details

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through Cisco's Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to:

http://www.cisco.com/en/US/ordering/or6/or17/order_refurbished_equipment_high_level_listing.html

FOR MORE INFORMATION

For more information about the [Select Cisco 15454 HW](#), visit <http://www.cisco.com/en/US/products/hw/optical/ps2006/ps5320/index.html> or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA
95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA
95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital
Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2006 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0601R)

Printed in the USA