

End-of-Sale and End-of-Life Announcement for Some Cisco ONS 15454, ONS 15454E, and ONS 15454W Bundles

EOL5482

Cisco® announces the end-of-sale dates for some Cisco ONS 15454, ONS 15454E, and ONS 15454W Bundles. The last day to order some Cisco ONS 15454, ONS 15454E, and ONS 15454W Bundles is May 1, 2007. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until otherwise specified by a component-specific end-of-life announcement or new Product ID. Table 1 describes the end-of-life milestones, definitions, and dates for some Cisco ONS 15454, ONS 15454E, and ONS 15454W Bundles. Table 2 lists the product part numbers affected by this announcement.

Table 1. End-of-Life Milestones and Dates for some Cisco ONS 15454, ONS 15454E, and ONS 15454W Bundles

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	January 30, 2007
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 1, 2007
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	July 30, 2007

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
15454-10E-58-SK	Contains 2ea 15454-10E-L1-58.1 and ONS-XC-10G-S1
15454-10ME-58-SK	Includes 2ea 15454-10ME-58.1
15454-32MD-SK	Contains 1ea 15454-32MUX-O AND 1ea 15454-32DUX-O
15454-4C58-SK	Contains 2ea 15454-AD-4C-58.1
15454-4MD-58-SK	Contains 2ea 15454-4MD-58.1
15454-AD-4B46-SK	Contains 2ea 15454-AD-4B-46.1
15454-DS1N-14-SK	Contains 2ea DS1N-14
15454-DS3-12E-SK	Contains 2ea DS3-12E
15454-DS3N-12E-SK	Contains 2ea DS3N-12E
15454-MR-58-SK	Contains 2ea 15454-MR-L1-58.1
15454-MRP-58-SK	Contains 2ea 15454-MRP-L1-58.1
15454-OC12-4-SK	Contains 2ea OC12I4-1310
15454-OC12I1310-SK	Contains 2ea OC12I1R1310
15454-OC12L1310-SK	Contains 2ea OC12L1R1310
15454-OC12L1550-SK	Contains 2ea OC12L1R1550
15454-OC3-8-SK	Contains 2ea OC3/STM1, IR, 1310, 8 Ckt., SC
15454-OC48IR-SK	Contains 2ea OC48IR1310A
15454-OC48LR-SK	Contains 2ea OC48LR1550A

End-of-Sale Product Part Number	Product Description
15454E-BLANK-SK	Contains 2ea ETSI Blank Module (Slot Filler)
15454E-BLANKFM-SK	Contains 2ea ETSI Blank Module for FMEC (Slot Filler)
15454E-DS3IN-12-SK	Contains 2 ea DS3IN-12
15454E-E3-12-SK	Contains 2ea E3-12
15454E-G1K-4-SK	Contains 2ea G1K-4
15454E-L4.1-1-SK	Contains 2ea L4.1-1
15454E-L4.2-1-SK	Contains 2ea L4.2-1
15454E-S1.1-4-SK	Contains 2ea S1.1-4
15454E-S1.1-8-SK	Contains 2ea S1.1-8
15454E-S4.1-1-SK	Contains 2ea S4.1-1

Product Migration Options

There is no replacement available for the some Cisco ONS 15454, ONS 15454E, and ONS 15454W Bundles at this time.

There is no replacement bundle for these end-of-life parts. The contents of the bundles remain orderable and can be ordered separately directly from the Global Cisco Price List.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through Cisco's Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to: http://www.cisco.com/web/ordering/ciscocapital/or6/or17/order_refurbished_equipment_high_level_listing.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Europe Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: +31 0 800 020 0791
Fax: +31 0 20 357 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

©2007 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, iPhone, IP/TV, IQ Expertise, the IQ logo, IQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networking Academy, Network Registrar, Packet, PIX, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0701R)