

## End-of-Sale and End-of-Life Announcement for the Miscellaneous Cisco ONS 15454 SONET Multiservice Provisioning Platform Software Packages, Licenses, and Documentation

EOL6228

Cisco® announces the end-of-sale and end-of-life dates for the Miscellaneous Cisco ONS 15454 SONET Multiservice Provisioning Platform Software Packages, Licenses, and Documentation. The last day to order the affected product(s) is November 1, 2008. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

**Table 1.** End-of-Life Milestones and Dates for the Miscellaneous Cisco ONS 15454 SONET Multiservice Provisioning Platform Software Packages, Licenses, and Documentation

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	November 2, 2007
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	November 1, 2008
<b>Last Ship Date: OS SW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	January 31, 2009
<b>End of SW Maintenance Releases Date: OS SW</b>	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	November 1, 2009
<b>End of New Service Attachment Date: OS SW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	November 1, 2009
<b>End of Service Contract Renewal Date: OS SW</b>	The last date to extend or renew a service contract for the product.	January 30, 2013
<b>Last Date of Support</b>	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	October 31, 2013

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
15454-DOC4.1.0B1=	BellSouth Sys Doc. Rel 4.1.0 English CD, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
15454-DOC4.1.0PB1=	BellSouth Sys Doc. Rel 4.1.0 English Paper, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
15454-DOC4.6.0B1=	BellSouth Sys Doc. Rel 4.6.0 English CD, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
15454-DOC4.6.0PB1=	BellSouth Sys Doc. Rel 4.6.0 English Paper, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
15454-DOC5.0.0B1=	BellSouth Sys Doc. Rel 5.0.0 English CD, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
15454-DOC5.0.0PB1=	BellSouth Sys Doc. Rel 5.0.0 English Paper, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
15454-DOC6.0.0B1=	BellSouth Sys Doc. Rel 6.0.0 English CD, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
15454-DOC6.0.0PB1=	BellSouth Sys Doc. Rel 6.0.0 English Paper, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
15454-DOC7.0.0B1=	BellSouth Sys Doc. Rel 7.0.0 English CD, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
15454-DOC7.0.0PB1=	BellSouth Sys Doc. Rel 7.0.0 English Paper, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
15454-DOC7.2.0PB1=	BellSouth Sys Doc. Rel 7.2.0 English Paper, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
15454-LIC-R4.1.7	15454 Upgrade License for R4.1.7, Right To Use License	See the Product Migration Options section below for detailed information on replacing this product.	
15454-R4.1.0SW-B1=	BellSouth Rel. 4.1.0 Feature Pkg., CD, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
15454-R4.1.7SWCD	Rel. 4.1.7 Feature Pkg., CD, Right To Use License	See the Product Migration Options section below for detailed information on replacing this product.	
15454-R4.1.7SWCD=	Rel. 4.1.7 Feature Pkg., CD, Right To Use License	See the Product Migration Options section below for detailed information on replacing this product.	
15454-R4.6.1SW-B1=	BellSouth Rel. 4.6.1 Feature Pkg., CD, Ver. 1 config (RTU)	See the Product Migration Options section below for detailed information on replacing this product.	
15454-R4.6.2K9-B1=	BellSouth Rel. 4.6.2 Feature Pkg., CD, Ver. 1 config (RTU)	See the Product Migration Options section below for detailed information on replacing this product.	
15454-R4.6.2SW-B1=	BellSouth Rel. 4.6.2 Feature Pkg., CD, Ver. 1 config (RTU)	See the Product Migration Options section below for detailed information on replacing this product.	
15454-R4.6.4K9-B1=	BellSouth Rel. 4.6.4 Feature Pkg., CD, Ver. 1 config (RTU)	See the Product Migration Options section below for detailed information on replacing this product.	
15454-R5.0.0K9-B1=	BellSouth Rel. 5.0.0 Feature Pkg., CD, Ver. 1 config (RTU)	See the Product Migration Options section below for detailed information on replacing this product.	

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
15454-R5.0.2K9-B1=	BellSouth Rel. 5.0.2 Feature Pkg., CD, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
15454-R5.0.4K9-B1=	Rel. 5.0.4 Feature Pkg., CD, Right to Use License	See the Product Migration Options section below for detailed information on replacing this product.	
15454-R5.0.6K9-B1=	BellSouth Rel. 5.0.6 Feature Pkg., CD, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
15454-R6.0.0K9-B1=	BellSouth Rel. 6.0.0 Feature Pkg., CD, Ver. 1 config (RTU)	See the Product Migration Options section below for detailed information on replacing this product.	
15454-R7.0.0K9-B1=	BellSouth Rel. 7.0.0 Feature Pkg., CD, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
15454-R7.2.0K9-B1=	BellSouth Rel. 7.2.0 Feature Pkg., CD, Ver.1 config(RTU)	See the Product Migration Options section below for detailed information on replacing this product.	
SF15454-5.0.6K9B1	BellSouth Rel. 5.0.6 SW, Preloaded on TCC, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
SF15454-R4.1.0-B1	BellSouth Rel. 4.1.0 SW, Preloaded on TCC, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
SF15454-R4.1.3-B1	BellSouth Rel. 4.1.3 SW, Preloaded on TCC, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
SF15454-R4.1.7	Rel. 4.1.7 SW, Pre-loaded on TCC	See the Product Migration Options section below for detailed information on replacing this product.	
SF15454-R4.6.1-B1	BellSouth Rel. 4.6.1 SW, Preloaded on TCC, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
SF15454-R4.6.2-B1	BellSouth Rel. 4.6.2 SW, Preloaded on TCC, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
SF15454-R4.6.2K9B1	BellSouth Rel. 4.6.2 SW, Preloaded on TCC, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
SF15454-R4.6.4K9B1	BellSouth Rel. 4.6.4 SW, Preloaded on TCC, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
SF15454-R5.0.0K9B1	BellSouth Rel. 5.0.0 SW, Preloaded on TCC, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
SF15454-R5.0.2K9B1	BellSouth Rel. 5.0.2 SW, Preloaded on TCC, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
SF15454-R5.0.4K9B1	Rel. 5.0.4 SW, Pre-loaded on TCC	See the Product Migration Options section below for detailed information on replacing this product.	
SF15454-R6.0.0K9B1	BellSouth Rel. 6.0.0 SW, Preloaded on TCC, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
SF15454-R7.0.0K9B1	BellSouth Rel. 7.0.0 SW, Preloaded on TCC, Ver. 1 config	See the Product Migration Options section below for detailed information on replacing this product.	
SF15454-R7.2.0K9B1	BellSouth Rel. 7.2.0 SW, Preloaded on TCC, Ver.1 config	See the Product Migration Options section below for detailed information on replacing this product.	

## Product Migration Options

There should be minimal customer impact, as these products were never released globally.

However, customers can migrate to the latest maintenance release on their product branch. Selected loads on each branch have been maintained to minimize customer impact. Packages that have been retained are:

- 4.1.4 ,4.1.82, 4.6.6
- 5.0.3, 5.0.6, 5.0.8
- 6.0.1, 6.0.3, 6.2.0, 6.2.2, 6.2.3
- 7.0.1, 7.0.3, 7.0.4, 7.0.5, 7.0.6, 7.2.3
- 8.0

Alternatively, customers are encouraged to migrate to the latest software package that is compatible with their present Cisco ONS 15454 Timing, Communications, and Control (TCC) card. For a TCC2P card, migration to the latest load is recommended. For the TCC+ card, customers can migrate to 4.1.82 or conduct an in-service processor upgrade to TCC2P, then migrate to the latest available release. Customers can receive credit on a trade in of a TCC+ card toward the purchase of a TCC2P. Information on software release details can be found at:

[http://cisco.com/en/US/products/hw/optical/ps2006/prod\\_release\\_notes\\_list.html](http://cisco.com/en/US/products/hw/optical/ps2006/prod_release_notes_list.html).

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through the Cisco Certified Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to: <http://cisco.com/go/remarketing>.

### **For More Information**

For more information about the Latest software package available, visit [http://www.cisco.com/en/US/products/hw/optical/ps2006/prod\\_release\\_notes\\_list.html](http://www.cisco.com/en/US/products/hw/optical/ps2006/prod_release_notes_list.html), or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: [http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html).

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



**Americas Headquarters**  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
[www.cisco.com](http://www.cisco.com)  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 527-0883

**Asia Pacific Headquarters**  
Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
[www.cisco.com](http://www.cisco.com)  
Tel: +65 6317 7777  
Fax: +65 6317 7799

**Europe Headquarters**  
Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
[www-europe.cisco.com](http://www-europe.cisco.com)  
Tel: +31 0 800 020 0791  
Fax: +31 0 20 357 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

©2007 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, IP/TV, IQ Expertise, the IQ logo, IQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networking Academy, Network Registrar, PIX, ProConnect, ScriptShare, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0708R)