



End-of-Sale and End-of-Life Announcement for the Cisco ONS 15454 MSPP E-Series Cards

Cisco Systems® announces the end-of-sale and end-of-life dates for the Cisco ONS 15454 MSPP E-Series Cards. The last day to order the affected product is July 10, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until July 8, 2012. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement.

Customers are encouraged to migrate to the CE-Series and ML-Series Cards. CE-Series Cards provide next-generation EOS capabilities such as GFP, VCAT, and LCAS/SWLCAS. ML-Series Cards provide new revenue-generating capabilities such as EVPL as well as E-LAN services. Product information regarding CE-Series and ML-Series Cards is available at:

http://cisco.com/en/US/products/hw/optical/ps2006/products_data_sheets_list.html.

Table 1. End-of-Life Milestones and Dates for the Cisco ONS 15454 MSPP E-Series Cards

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	July 10, 2006
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	July 10, 2007
Last Ship Date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	October 9, 2007
End of Routine Failure Analysis Date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	July 9, 2008
End of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	July 9, 2008
End of Service Contract Renewal Date	The last date to extend or renew a service contract for the product.	October 8, 2011
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	July 8, 2012

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
15454-E1000-2-G(=)	Gigabit Ethernet, 2 Ckt., L2, GBIC, XC/XC-VT/XC-10G	15454-CE-1000-4	4-port GE Carrier Edge card
15454-E1000-2-G(=)	Gigabit Ethernet, 2 Ckt., L2, GBIC, XC/XC-VT/XC-10G	15454-ML1000-2	Gigabit Ethernet, 2 Ckt., L2/L3, SFP
15454-E100T-G(=)	10/100BT, 12 Ckt., XC/XC-VT/XC-10G	15454E-CE-100T-8	8x10/100T Carrier Ethernet – ANSI/ETSI Support
15454-E100T-G(=)	10/100BT, 12 Ckt., XC/XC-VT/XC-10G	15454E-ML100T-12	Ethernet, 12 Ckt. – ANSI/ETSI Support
15454-E100T-G(=)	10/100BT, 12 Ckt., XC/XC-VT/XC-10G	15454E-ML100X-8	100-Mbps Fiber Ethernet, 8 SFP Ckt., L2/L3 – ANSI/ETSI Support
15454E-E1000-2(=)	2-port Gigabit Ethernet Module – need GBICs	15454-CE-1000-4	4-port GE Carrier Edge card
15454E-E1000-2(=)	2-port Gigabit Ethernet Module – need GBICs	15454E-ML1000-2	Gigabit Ethernet, 2 Ckt. – ANSI/ETSI Support

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
15454E-E100T-12(=)	12-port 10/100BT Ethernet Module	15454-CE-100T-8	8x10/100T Carrier Ethernet
15454E-E100T-12(=)	12-port 10/100BT Ethernet Module	15454-ML100T-12	10/100-Mbps Ethernet, 12 Ckt., L2/L3
15454E-E100T-12(=)	12-port 10/100BT Ethernet Module	15454-ML100X-8	100-Mbps Fiber Ethernet ML-Series, 8 SFP Ckt., L2/L3

PRODUCT MIGRATION OPTIONS

The recommended replacement for the Cisco ONS 15454 MSPP E-Series Cards is the Cisco ONS 15454 CE-Series and ML-Series.

Customers are encouraged to migrate to the Cisco ONS 15454 CE-Series and ML-Series cards. Information about this product can be found at: http://cisco.com/en/US/products/hw/optical/ps2006/products_data_sheets_list.html.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through the Cisco Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis.

For information about the refurbished equipment program, go to:

http://www.cisco.com/en/US/ordering/or6/or17/order_refurbished_equipment_program_description.html.

FOR MORE INFORMATION

For more information about the Cisco ONS 15454 MSPP E-Series Cards, visit

<http://www.cisco.com/en/US/products/hw/optical/ps2006/ps2010/index.html> and

<http://www.cisco.com/en/US/products/hw/optical/ps2006/ps2008/index.html> or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco.com Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus • Czech Republic
Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy
Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal
Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2006 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0601R)

Printed in USA

CS1-349670-01 05/06